

ASS. REC. BY:

REF: CS/CTI 20003650/KS d3

Special Instruction:

Surge: Kenneth

ASSIGNMENT (Office)

From (Person): Chee So Chow

of CTI

Date/Time: 5/3/2020 @ 5pm

Estimated Cost:

Bill to:

OD/TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

AW 9133L

Insured:

XE 3554M

at Workshop m/s

Yee Auto Service

Tel:

8866 8832

of

160 Sin Ming Drive #02-17

Policy No:

Claim No:

SNM20D201111/XE3554M/TKL

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/02/2020

6/3/2020

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time: 5:07pm 5/3/2020

Person Contacted:

Mr. Chen

Vehicle IN/OUT

Date/Time

Action/Instruction

Validated

AW 9133L - X

XE 3554M - CS/CTI 19002384/RIS d3e2

DoA: 29/01/2020

19/3

11pm 85200k email & confirm
(\$ 7,067.32 red 58%)

ASS. REC. BY:

REF: CTF

ASSIGNMENT

From: _____ Date: 6/3/2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GW 133L

at Workshop m/s Yee Auto

of 160 Sin Ming Drive #02-17

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 10'23

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GW 9133L Yr Regn: 12 03

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Dyna C.C. 2886

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 178055 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFUR 344 303001928

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185R14X8

R: 155R12X800

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

A Plus

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 29/2/20

Survey held at

Rear

R/Bal. 66 mm

L/Bal. 66 mm

D.O.I. 6/3/20

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 20 MAR 2020

Date/Time, File Pass to?

20/03/20

1) Typ: 4

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$ 5,200/- US)

Days Of Repair: 6

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others:

TOTAL

220

Nivitha (LKK Auto)

From: Chee So Chow <sochow.chee@sg.cntaiping.com>
Sent: Thursday, 5 March 2020 5:00 PM
To: 'assignments'
Cc: Claims Dept of CTI; Tan Kah Leong
Subject: FW: OUR REF: SNM20D201111/XE3554M/TKL - PRI: Your Vehicle: XE3554M; Our Ref: YeeAuto-GW9133L; Accident Involving GW 9133 L & XE 3554 M on 29 February 2020

Dear Nivita/Summer

As spoken to Ms Nivita, kindly conduct survey as soon as possible.
We shall upload in Merimen according.

Kah Leong
Please upload in Merimen and I-Gen.

Regards

Chee So Chow (Ms)

Claims Department

Email : claimsdept@sg.cntaiping.com
sochow.chee@sg.cntaiping.com

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6176 | F: (65) 6224 7175 / (65) 6224 7478

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Thursday, March 5, 2020 4:50 PM
To: Chee So Chow <sochow.chee@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; yeeauto pteltd <yeeautopteltd@gmail.com>
Subject: Fwd: OUR REF: SNM20D201111/XE3554M/TKL - PRI: Your Vehicle: XE3554M; Our Ref: YeeAuto-GW9133L; Accident Involving GW 9133 L & XE 3554 M on 29 February 2020

Hi So Chow,

We refer to our earlier tele-conversation.

As spoken, we forward herewith below our email dated 4 March 2020 and 5 March 2020 respectively as requested.

Kindly request for the Single Joint Expert, Mr. Kenneth Kong to contact the repairers, M/s Yee Auto Pte Ltd at 6457 5768 to make the necessary arrangements.

Regards,

Ms. Tan

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 8.45 a.m. to 5.45 p.m. and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

----- Forwarded message -----

From: **bonnie kwok** <litigation@bonniekwok.com>

Date: Thu, 5 Mar 2020 at 14:19

Subject: Re: OUR REF: SNM20D201111/XE3554M/TKL - PRI: Your Vehicle: XE3554M; Our Ref: YeeAuto-GW9133L; Accident Involving GW 9133 L & XE 3554 M on 29 February 2020

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>

Cc: yeeauto pteltd <yeeautopteltd@gmail.com>

Dear Sirs,

We have been instructed that the repairers have not received any calls from Mr. Kenneth Kong yet.

Kindly assist to expedite and ensure that the pre-repairs inspection is conducted within the stipulated time frame.

Regards,

ST

--

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 8.45 a.m. to 5.45 p.m. and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Wed, 4 Mar 2020 at 09:54, bonnie kwok <litigation@bonniekwok.com> wrote:

Dear Sirs,

Our client agrees to Kenneth Kong as the Single Joint Expert (SJE).

Please let us have his report in due course.

Kindly request for the SJE to contact the repairers, M/s Yee Auto Pte Ltd at 6457 5768 to make the necessary arrangements.

Regards,
ST

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 8.45 a.m. to 5.45 p.m. and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Tue, 3 Mar 2020 at 16:55, Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com> wrote:

Without Prejudice

Dear ST,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong

Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Sent: Tuesday, March 3, 2020 4:36 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; 'bonnie kwok' <litigation@bonniekwok.com>

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OUR REF: SNM20D201111/XE3554M/TKL - PRI: Your Vehicle: XE3554M; Our Ref: YeeAuto-GW9133L; Accident Involving GW 9133 L & XE 3554 M on 29 February 2020

Dear Kah Leong,

Please conduct PRS for GW9133L.

Note : officer in charge – Kah Leong 63896193.

*** Kindly quote our reference number when replying.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: bonnie kwok <litigation@bonniekwok.com>

Sent: Tuesday, March 3, 2020 11:02 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: Urgent: Pre-Repair Inspection: Your Vehicle: XE3554M; Our Ref: YeeAuto-GW9133L; Accident Involving GW 9133 L & XE 3554 M on 29 February 2020

Urgent

Dear Sirs,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. GW 9133 L at M/s Yee Auto Pte Ltd, Block 160 Sin Ming Drive #02-17 Sin Ming Autocity Singapore 575722.

Regards,
ST

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 8.45 a.m. to 5.45 p.m. and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5788 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Estimate No: ES2000024

Date: 03 Mar 2020

Policy No:

Veh Reg No: GW9133L

Make/Model: TOYOTA DYNA 150 D

Chassis No: JTFUF34Y303001926

Engine No: 5L5391350

Reg. Date: 10/12/2003

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 29/02/2020

TP Veh Reg No: XE3554M

*Not Authorized
11 Day 852000
Recovery After Paint
6 days*

Estimate Repair Cost to Vehicle No :GW9133L

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Spare Parts				
1 REAR TAILGATE	1,430.50	1 PC	<i>Ry</i> 1,430.50	✓
2 REAR TAILGATE STICKER 'TOYOTA'	250.00	1 PC	<i>na</i> 250.00	—
3 REAR TAILGATE '13 PAX' STICKER	20.00	1 PC	<i>na</i> 20.00	—
4 SPEED LIMIT STICKER '70KM/H'	20.00	1 PC	<i>na</i> 20.00	—
5 REAR END PANEL	465.50	1 PC	<i>h</i> 465.50	X
6 REAR END PANEL STOPPER - LH	57.60	1 PC	<i>na</i> 57.60	X
7 REAR END PANEL STOPPER - RH	57.60	1 PC	<i>na</i> 57.60	X
8 TAIL LAMP LH	375.66	1 PC	<i>h</i> 375.66	X
9 TAIL LAMP RH	375.66	1 PC	<i>h</i> 375.66	X
10 REAR TAILLAMP PANEL - LH	248.20	1 PC	<i>h</i> 248.20	X
11 REAR TAILLAMP PANEL - RH	248.20	1 PC	<i>h</i> 248.20	X
12 REAR NUMBER PLATE	60.00	1 PC	<i>h</i> 60.00	X
13 REAR NUMBER PLATE BRACKET	175.20	1 PC	<i>h</i> 175.20	X
14 REAR NUMBER PLATE LAMP	70.00	1 PC	<i>h</i> 70.00	X
15 REAR SIDEGATE PILLAR SAFETY HINGE - LH	185.90	1 PC	<i>h</i> 185.90	X
16 REAR SIDEGATE PILLAR SAFETY HINGE - RH	185.90	1 PC	<i>na</i> 185.90	—
17 REAR STOPPER BRACKET - LH	135.50	1 PC	<i>h</i> 135.50	X
18 REAR STOPPER BRACKET - RH	135.50	1 PC	<i>h</i> 135.50	X
19 REAR CARGO CANODY <i>Pc?</i>	1,950.00	1 PC	<i>Ry</i> 1,950.00	✓ 1500.00
20 REAR CARGO SIDEGATE - RH <i>Pc?</i>	1,650.00	1 PC	<i>Ry</i> 1,650.00	✓ 1100.00
21 REAR CARGO SIDEGATE RAILING - LH	485.20	1 PC	<i>h</i> 485.20	X
22 REAR CARGO SIDEGATE RAILING - RH	485.20	1 PC	<i>Ry</i> 485.20	✓
			9,067.32	9,067.32
Labour				
23 TO DISMANTLE & REPLACE DAMAGED PARTS. PANEL BEAT WHERE NECESSARY.	1,500.00	1 JOB	1,500.00	850
24 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,500.00	1 JOB	1,500.00	750
25 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	120.00	1 JOB	120.00	60
26 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	150
			3,200.00	3,200.00

10%



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department
Your Ref No: -
Claim Type: Third Party
Accident Date: 29/02/2020
TP Veh Reg No: XE3554M

Estimate No: ES2000024
Date: 03 Mar 2020
Policy No:
Veh Reg No: GW9133L
Make/Model: TOYOTA DYNA 150 D
Chassis No: JTFUF34Y303001926
Engine No: 5L5391350
Reg. Date: 10/12/2003

Estimate Repair Cost to Vehicle No :GW9133L

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			Total	SS 12,267.32
			Add GST @ 7%	858.71
			Total Amount Payable	SS 13,126.03

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND ONE HUNDRED TWENTY SIX AND CENTS THREE ONLY

For Yee Auto Pte Ltd



AUTHORISED SIGNATURE

YEE Auto Consultants hereby notify
the Receiver of the following:

- * To repair, replace or rectify
- * To replace, repair, or rectify
- * To replace, repair, or rectify
- * To replace, repair, or rectify
- * To replace, repair, or rectify
- * To replace, repair, or rectify
- * To replace, repair, or rectify
- * To replace, repair, or rectify

Administered by Receiver:
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20003650/KSD3N2
Date: 25/03/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN17632119022
Claimant Vehicle No :	GW9133L	Insured Vehicle No :	XE3554M
Date of Loss:	29/02/2020	Nature of Claim:	TP
		Claim No:	SNM20D201111C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GW9133L	Engine No:	5L5391350
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFUF34Y303001926
Reg. Date:	10/12/2003 (Man. Year: 2003)	Odometer:	178055 km
Colour:	Blue		
Engine Capacity:	2986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R14X8	Rear Tyre Size:	155 R12X8(D)
Front Left Side:	APLUS 8 mm	Rear Left Side:	APLUS 6/6 mm
Front Right Side:	APLUS 8 mm	Rear Right Side:	APLUS 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,067.32	4,752.44	4,314.88	47.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,775.00	1,425.00	44.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,267.32	6,527.44	5,739.88	46.79
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	12,267.32	5,200.00	7,067.32	57.61
+ GST 7.00/7.00% (S\$)	858.71	364.00	494.71	57.61
Nett Amount (S\$)	13,126.03	5,564.00	7,562.03	57.61

INSPECTION

Date of Assignment:	06/03/2020	
Date Inspected:	06/03/2020 Inspected At:	Yee Auto Pte Ltd (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Mar 2020)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GW9133L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,430.50 F	*1,430.50 FL
2	1		*REAR TAILGATE STICKER TOYOTA	Necessary	250.00 F	*250.00 FL
3	1		*REAR TAILGATE 13PAX STICKER	Necessary	20.00 F	*20.00 FL
4	1		*SPEED LIMIT STICKER 70KM/H	Necessary	20.00 F	*20.00 FL
5	1		*REAR END PANEL	Repair	465.50 F	*- FL
6	1		*REAR END PANEL STOPPER-LH	Not Necessary	57.60 F	*- FL
7	1		*REAR END PANEL STOPPER-RH	Not Necessary	57.60 F	*- FL
8	1		*TAIL LAMP LH	Serviceable	375.66 F	*- FL
9	1		*TAIL LAMP RH	Serviceable	375.66 F	*- FL
10	1		*REAR TAILLAMP PANEL-LH	Repair	248.20 F	*- FL
11	1		*REAR TAILLAMP PANEL-RH	Repair	248.20 F	*- FL
12	1		*REAR NUMBER PLATE	Serviceable	60.00 F	*- FL
13	1		*REAR NUMBER PLATE BRACKET	Repair	175.20 F	*- FL
14	1		*REAR NUMBER PLATE LAMP	Serviceable	70.00 F	*- FL
15	1		*REAR SIDEGATE PILLAR SAFETY HINGE-LH	Repair	185.90 F	*- FL
16	1		*REAR SIDEGATE PILLAR SAFETY HINGE-RH	Dented	185.90 F	*185.90 FL
17	1		*REAR STOPPER BRACKET-LH	Repair	135.50 F	*- FL
18	1		*REAR STOPPER BRACKET-RH	Repair	135.50 F	*- FL
19	1		*REAR CARGO SIDEGATE RAILING-LH	Repair	485.20 F	*- FL
20	1		*REAR CARGO SIDEGATE RAILING-RH	Bent	485.20 F	*485.20 FL
21	1		*REAR CARGO CANODY	Bent	1,950.00 FS	*1,500.00 FS
22	1		*REAR CARGO SIDEGATE-RH	Bent	1,650.00 FS	*1,100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,067.32	4,991.60
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	239.16
Total Parts (\$\$)	9,067.32	4,752.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY	New	1,500.00	950.00
2	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,500.00	750.00
3	TO APPLY RUST-PROOFING ON REPAIRED,REPLACED PANEL	New	120.00	60.00
4	TO CHECK WIRING FUNCTIONS	New	80.00	15.00
Gross Labour Cost (S\$)			3,200.00	1,775.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >