

FORTDELGRO ENGINEERING PTE LTD
PAIR ESTIMATE*

VEHICLE NO : SH 7023X
 MAKE : HYUNDAI
 MODEL : i40

DATE: 3. Mar. 2020

DOA: 2. Mar. 2020 **CHINA**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Rear Bumper <i>DEF</i>			\$553.00
10	Rear Bumper Clips <i>nec</i>		\$2.20	\$22.00
1	Rear Bumper Undercover <i>scr</i>			\$228.00
1	Rear Bumper Sponge <i>X? NH</i>			\$103.50
SUB TOTAL				\$906.50
LESS 20%				\$181.30
DISCOUNTED TOTAL				\$725.20
1	Rear Bumper Rubber Mat <i>hwa nec</i>			\$50.00
1	Reverse Sensor <i>xxxn</i>			\$135.70
1	Advertisement – Rear Bumper <i>nec</i>			\$50.00
2	Advertisement – Rear Fenders LH/RH <i>nec</i>		\$100.00	\$200.00
				\$435.70
Labour Charge				
1	Panel Beating			\$300.00
1	Spray Painting Charge			\$250.00
1	Remove/refix Reverse Sensor			\$80.00
1	Wiring Charge			\$50.00
1	Towing Fee			\$80.00
TOTAL LABOUR				\$760.00
ESTIMATE TOTAL				\$1,920.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Signature:
 Date:

Larry Ng

Ray (LKK)
4/3/2020 1205
Para Suran@kerauto.com
88622778
Qrefsyndy
add repair photo
L/S

45: 81209.92

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305385214

Date : 5. Mar. 2020

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

Vehicle Reg No. : SH 7023X

Date of Accident: 2. Mar. 2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA YN6675T

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

\$1,200.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : Larry Ng

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : Ram

Name : Ram

Date : 5/3/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

* Third party keen on private settlement with us *