

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: LONPAC INSURANCE BHD	Document No.	: SQT20001026	Page	1
	100 BEACH ROAD	Date	: 2. Mar 2020		
	#19-00 SHAW TOWERS	Customer No.	: WZL009		
	SINGAPORE 189702	Svc Advisor	: NG SIN HAI		
Registration No	: SLE590U	Engine No	: K24W72012005		
Chassis No	: JHMRC1890GC204289	Date Time	: 2. Mar 2020 4:17:34 PM		
Model	: ODYSSEY2.4 EXV-S 16YM NAVI-RES	Surveyor Name	:		
Owner's Name	: PHANG YEAN MOI	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 29/2/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	140.00	/	140.00	9.80	149.80
BOJSE	SEALANT FOR REAR END PANEL	1	100.00	/	100.00	7.00	107.00
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	100.00	X	100.00	7.00	107.00
BOJSE	SEALANT FOR TAILGATE	1	100.00	/	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00	/	100.00	7.00	107.00
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	380.00	/ (phk)	380.00	26.60	406.60
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	420.00	/	420.00	29.40	449.40
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	680.00	/	680.00	47.60	727.60
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00	/	100.00	7.00	107.00
BKRP02M	CUT OFF & RENEW RR PANEL. 650 x 5	1	6500.00	3250	6500.00	455.00	6955.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) 570 x 6	1	4160.00	3120	4160.00	291.20	4451.20
BKOT00R	REMOVE UPHOLSTERY SHATTERED GLASSES	1	650.00	325	650.00	45.50	695.50
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	650.00	580	650.00	45.50	695.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00	580	650.00	45.50	695.50
Sum Labor					14830.00	1,038.10	15,868.10

Printed on 2/3/2020 6:11:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
 100 BEACH ROAD
 #19-00 SHAW TOWERS
 SINGAPORE 189702

Registration No : SLE590U

Chassis No : JHMRC1890GC204289

Model : ODYSSEY2.4 EXV-S 16YM NAVI-RES

Owner's Name : PHANG YEAN MOI

Ins Policy No. :

Date of Accident : 29/2/2020

Document No. : SQT20001026

Date : 2. Mar 2020

Customer No. : WZL009

Svc Advisor : NG SIN HAI

Engine No : K24W72012005

Date | Time : 2. Mar 2020 4:17:34 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
RS-TMP3040L	VPC 4PCS REAR SENSORS / BR	1	320.00		320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X	1	45.00		45.00	3.15	48.15
33500-T6A-003	TAILLIGHT ASSYR. X	1	859.90	25	644.92	45.14	690.06
33550-T6A-003	TAILLIGHT ASSYL. X	1	859.90	25	644.92	45.14	690.06
34150-T6A-003	LIGHT ASSYR.LID / BR	1	396.20	25	297.15	20.80	317.95
34155-T6A-003	LIGHT ASSYL.LID / BR	1	396.20	25	297.15	20.80	317.95
74890-T6A-J01	GARNISH ASSYRR.LICENSE X	1	236.40	25	177.30	12.41	189.71
68100-T6A-Q10ZZ	TAILGATE COMP / DD	1	1098.60	25	823.95	57.68	881.63
74440-T6A-003	WEATHERSTRIPTAILGATE / CR4	1	120.50	25	90.37	6.33	96.70
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN / BR	1	180.10	25	135.07	9.45	144.52
74900-T6A-003ZB	GARNISH ASSYTAILGATE SPOILER X	1	630.30	25	472.72	33.09	505.81
91513-T6A-003	CLIPTAILGATE SPOILER X	6	2.50	25	11.25	0.79	12.04
75701-T6A-000	EMBLEMH / MC	1	27.00	25	20.25	1.42	21.67
04715-T6A-900ZZ	FACERR.BUMPER / DD	1	583.10	25	437.32	30.61	467.93
33505-SLJ-013	REFLECTOR ASSYR.RR. X	1	46.50	25	34.87	2.44	37.31
33555-SLJ-013	REFLECTOR ASSYL.RR. X	1	46.50	25	34.87	2.44	37.31
71502-T6A-003ZB	FACER.RR.BUMPER GARNISH / (CR4) CR4	1	78.80	25	59.10	4.14	63.24
71507-T6A-003ZB	FACEL.RR.BUMPER GARNISH X	1	78.80	25	59.10	4.14	63.24
71512-T6A-921ZB	SPOILER ASSYR.RR.SIDE X	1	117.10	25	87.82	6.15	93.97
71517-T6A-921ZB	SPOILER ASSYL.RR.SIDE X	1	117.10	25	87.82	6.15	93.97
71593-T6A-003	SPACERR.RR.BUMPER SIDE / BR	1	19.60	25	14.70	1.03	15.73
71598-T6A-003	SPACERL.RR.BUMPER SIDE / BR	1	19.60	25	14.70	1.03	15.73
91505-TM8-003	CLIP,BUMPER / MC	7	2.30	25	12.07	0.84	12.91
66100-T6A-300ZZ	PANEL COMP,RR. / DD	1	472.80	25	354.60	24.82	379.42
04656-T6A-300ZZ	PAN SET3RD SEAT X	1	346.70	25	260.02	18.20	278.22
72841-SH3-315	OILSHEET X	3	41.70	25	93.82	6.57	100.39
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER ?	1	211.60	25	158.70	11.11	169.81
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL X	1	11.00	25	8.25	0.58	8.83
84615-T6A-N71ZD	LINING COMPR.RR.SIDE 2X	1	806.90	25	605.17	42.36	647.53

Printed on 2/3/2020 6:11:28 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWERS
SINGAPORE 189702
Registration No : SLE590U
Chassis No : JHMRC1890GC204289
Model : ODYSSEY2.4 EXV-S 16YM NAVI-RES
Owner's Name : PHANG YEAN MOI
Ins Policy No. :
Date of Accident : 29/2/2020

Document No. : SQT20001026 **Page** 3
Date : 2. Mar 2020
Customer No. : WZL009
Svc Advisor : NG SIN HAI
Engine No : K24W72012005
Date | Time : 2. Mar 2020 4:17:34 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
84640-T6A-003ZA	LINING ASSYRR.PANEL / CR4	1	106.30	25	79.72	5.58	85.30
84643-T6A-Q01ZA	COMP LIDTOOL X	1	63.00	25	47.25	3.31	50.56
84665-T6A-N71ZD	LINING COMPL.RR.SIDE X	1	783.40	25	587.55	41.13	628.68
73211-T6A-Q02	GLASS SET,RR.WINDSHIELD / BR	1	1037.30	25	777.97	54.46	832.43
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE / MC	2	18.50	25	27.75	1.94	29.69
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER / MC	1	17.30	25	12.97	0.91	13.88
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER / MC	1	17.30	25	12.97	0.91	13.88
73221-SR4-000	SPACERRR.W/SHIELD / MC	4	4.00	25	12.00	0.84	12.84
73225-TM8-000	RUBBER A WINDSHIELD DAM / MC	1	3.80	25	2.85	0.20	3.05
73226-SZW-000	DAMPERSTD 5X5 / MC	2	8.70	25	13.05	0.91	13.96
76711-T6A-003	CAPPIVOT / MC	1	5.00	25	3.75	0.26	4.01
BO-WS-SEALANT	WINDSCREEN SEALANT (N) / MC	2	60.00		120.00	8.40	128.40
Sum Item					8000.81	560.06	8,560.87
BO-V-KOOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	1	300.00		300.00	21.00	321.00
Sum Ext. Service					300.00	21.00	321.00

Survey By: Sten (LKK) 8/3/2020
Date & Time: _____
Excess: _____
Status: _____
Signature: _____

W/L MC
8 days
6/3/20, 2.30pm
P/P
By PK sy

Total Amount 23,130.81 1,619.16 24,749.97
Total (Inclusive of GST) 24,749.97

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

Printed on 2/3/2020 6:11:28 PM

No illegal modification(s) is allowed

This is a computer generated invoice. No signature is required.

Part prices are subject to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$58.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

How ever repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

Signature: _____
Date: _____