

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 31585

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0232/2020/NS
Date : 4-Mar-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mdm Tan Toh Heah
Address : 322 Laurel Ave
Singapore 275944
Telephone : HP +65 98301103
Type of Claim : Own Damage Claims
Policy No. : 2100342574-06
Vehicle No : **SKK 1215 C**
Model Code : Audi A4 TFSI QU 8K206
Model / Year : Jun-13
Engine No : CDN 331188
Chassis No : WAUZZZ8K6DA212647
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Feb-20
Place of Accident : Blk 204/209 Bedok Public Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKK 1215 C

S/N Nature of Jobs	Estimated Charges	Surveyor's Recommendations
To remove, check and reinstall front wire harness for		
1 headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
To dismantle and renew front bumper, rhs front fender and		
2 rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00 1250	
3 To respray front bumper and rhs front fender.	\$ 2,000.00 1100	
4 To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES	: <u>\$ 5,002.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax:

Material List for Accident Vehicle Regn No. SKK 1215 C

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
1	FRONT BUMPER <i>Defect</i>	\$	2,581.00	✓ 2064.80
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$	244.00	+
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	215.00	+
4	FRONT BUMPER GRILLE - LOWER CENTRE	\$	310.00	+
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>new</i>	\$	183.00	+
6	FRONT BUMPER SUPPORT ELEMENT - UPPER	\$	56.00	+
7	FRONT BUMPER VENT GRILLE - RH <i>missing</i>	\$	545.00	✓ 436.00
8	FRONT WHEEL SPOILER - RH <i>new</i>	\$	48.00	+
9	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>new</i>	\$	828.00	+
10	FRONT BUMPER FOAM FILLER PIECE	\$	117.00	+
11	FRONT BUMPER SUPPORT ?	2 \$	24.00	? X
12	FRONT BUMPER GUIDE SECTION - RH ?	\$	34.00	? X
13	SIGNAL HORN - RH LOW TONE <i>new</i>	\$	189.00	+
14	SPRING SHACKLE - RH <i>new</i>	\$	23.00	+
15	FRONT FENDER - RH <i>Defect</i>	\$	932.00	✓ 745.20
16	FRONT FENDER ATTACHMENT PARTS ?	\$	54.00	? X
17	FRONT FENDER BRACKET - RH ?	\$	50.00	? X
18	DEFORMATION ELEMENT BRACKET - RH REAR <i>new</i>	\$	46.00	+
19	FRONT FENDER BRACE - RH LOWER ?	\$	112.00	? ✓ 89.20
20	WHEEL HOUSING LINER - RH <i>new</i>	\$	226.00	✓ 180.40
SUB TOTAL SPARE PARTS CHARGES		:	\$ 6,817.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 1215 C

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 42.00	+
22	STONE CHIP GUARD <i>new</i>	\$ 69.00	✓ 54.64
23	ADHESIVE TAPE	\$ 52.00	? X
24	HEADLIGHT MOUNTING - RH ?	\$ 112.00	+ ✓ 89.20
25	HEADLAMP BRACKET - RH <i>new</i>	\$ 100.00	+
26	HEADLIGHT - RH <i>old</i>	\$ 2,208.00	✓ 1766.40
27	HALOGEN FOG LAMP - RH <i>new</i>	\$ 247.00	+
28	LIFT CYLINDER - RH <i>old new</i>	\$ 198.00	+
29	AIR CHARGE COOLER PRESSURE HOSE - RH <i>new</i>	\$ 274.00	+
30	RADIATOR AIR GUIDE - RH ?	\$ 25.00	+
31	RADIATOR SEALING STRIP <i>new</i>	\$ 15.00	+
32	SUNDRIES	\$ 300.00	✓ 15.36
TOTAL SPARE PARTS CHARGES		: \$ 10,459.00	
TOTAL LABOUR CHARGES		: \$ 5,002.00	
GRAND TOTAL		: \$ 15,461.00	

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 05/03/2010
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days.

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant