

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 31604

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0235/2020/NS
Date : 4-Mar-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian,
8 days + 1 Sunday - ok
02/07/2020 - Carrine

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Ch'ng Olivier Kuan Yew
Address : 19 Seletar Road
#04-39
Singapore 807020
Telephone : HP +65 97733377
Type of Claim : Own Damage Claims
Policy No. : 2100501737-02
Vehicle No : **SLG 3233 X**
Model Code : Audi A4 1.8 TFSI MU 8K203
Model / Year : May-13
Engine No : CJE 046540
Chassis No : WAUZZZ8K9DA197545
Mileage : 11140
Date In : 3-Mar-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Mar-20
Place of Accident : 21 Changi North Rise

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLG 3233 X

S/N	Nature of Jobs		Estimated Charges	Surveyor's ommendations
1	To tow vehicle from scene of accident.	S/N \$	280.00	
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
3	To remove and reinstall aircon condenser, charge air cooler and radiator. Check electical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00	\$ 1,200.00
4	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$	5,250.00	\$ 3,000.00
5	To respray front bumper, lhs front fender, bonnet and hinges.	\$	3,000.00	\$ 1,650.00
6	To renew lhs front rim. To carry out pre-repair wheel alignment. Check and post-repair wheel alignment check.	S/N \$	520.00	
7	To carry out pre-repair diagnostic check and post repair diagnostic check.	S/N \$	384.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 10,994.00	\$ 6,402.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 3233 X

S/N	Parts Description		<u>Damage Parts & Prices</u>	
			S/Nett	Remarks
1	FRONT BUMPER		\$ 2,169.00	\$ 1,735.20
2	FRONT BUMPER FIXING PARTS		\$ 244.00	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 215.00	
4	FRONT BUMPER GRILLE - LOWER CENTRE		\$ 127.00	
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE		\$ 183.00	
6	FRONT BUMPER SUPPORT ELEMENT - UPPER		\$ 56.00	
7	RADIATOR GRILLE		\$ 1,026.00	\$ 820.80
8	FRONT BUMPER AIR GUIDE GRILLE - LH		\$ 127.00	\$ 101.60
9	FRONT WHEEL SPOILER - LH		\$ 48.00	
10	FRONT BUMPER SIDE REINFORCEMENT BEAM		\$ 828.00	\$ 662.40
11	FRONT BUMPER FOAM FILLER PIECE		\$ 117.00	
12	FRONT BUMPER SUPPORT	2	\$ 24.00	\$ 9.36
13	FRONT BUMPER COVER		\$ 120.00	
14	FRONT BUMPER GUIDE SECTION - LH		\$ 34.00	\$ 27.12
15	CAUTION SIGN STICKER	NEC	\$ 13.00	
16	AIRCON STICKER	NEC	\$ 22.00	
17	SIGNAL HORN - LH HIGH TONE		\$ 189.00	
18	SPRING SHACKLE - LH HIGH TONE		\$ 23.00	
19	FRONT FENDER - LH		\$ 932.00	\$ 745.20
20	FRONT FENDER ATTACHMENT PARTS		\$ 54.00	
SUB TOTAL SPARE PARTS CHARGES		:	\$ 6,551.00	\$ 4,101.68

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 3233 X

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
		<i>c/f</i>		\$ 4,101.68
21	FRONT FENDER BRACKET - LH FRONT		\$ 50.00	\$ 39.44
22	DEFORMATION ELEMENT BRACKET - LH REAR		\$ 46.00	
23	FRONT FENDER BRACE - LH LOWER		\$ 112.00	\$ 89.20
24	STONE CHIP GUARD		\$ 69.00	\$ 54.64
25	ADHESIVE TAPE		\$ 52.00	\$ 40.96
26	WHEEL HOUSING LINER - LH		\$ 226.00	\$ 180.40
27	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 42.00	
28	BONNET		\$ 2,629.00	\$ 2,103.20
29	BONNET PROTECTIVE FILM - FRONT		\$ 43.00	\$ 34.08
30	BONNET ATTACHMENT PARTS		\$ 159.00	
31	BONNET LID HINGE - LH / RH	2	\$ 140.00	
32	BONNET CATC HOOK		\$ 132.00	
33	BONNET GAS FILLED STRUT - LH		\$ 112.00	
34	BONNET EDGE PROTECTION - FRONT		\$ 26.00	\$ 20.80
35	BONNET LID LOCK		\$ 202.00	
36	BONNET LID LOCK CABLE		\$ 46.00	
37	BONNET LOCK COVER		\$ 21.00	
38	HEADLIGHT MOUNTING - LH		\$ 112.00	\$ 89.20
39	HEADLAMP BRACKET - LH		\$ 100.00	\$ 79.28
40	HEADLIGHT - LH		\$ 2,208.00	\$ 1,766.40
SUB TOTAL SPARE PARTS CHARGES		:	\$ 6,527.00	\$ 8,599.28

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 3233 X

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/Nett	Remarks
			<i>c/f</i> \$ 8,599.28
41	GAS DISCHARGE LAMP CONTROL UNIT	\$ 1,074.00	
42	DAY DRIVING LIGHTS POWER MODULE	\$ 532.00	\$ 425.60
43	GAS DISCHARGE LAMP	\$ 404.00	
44	HEADLIGHT RETAINING PLATE - LH	\$ 23.00	
45	HEADLIGHT HOSE - LH	\$ 34.00	
46	HALOGEN FOG LAMP - LH	\$ 247.00	
47	LIFT CYLINDER - LH	\$ 198.00	\$ 158.00
48	LIFT CYLINDER HOSE	\$ 172.00	
49	LOCK CARRIER	\$ 956.00	\$ 764.40
50	LOCK CARRIER BRACE - LH	\$ 43.00	
51	RADIATOR AIR GUIDE - LH	\$ 25.00	
52	RADIATOR SEALING STRIP	\$ 15.00	
53	FRONT NO PLATE	S/N \$ 60.00	\$ 60.00
54	FRONT RIM - LH	TBC	
55	SUPPLEMENTARY	\$ 450.00	\$ 359.60
56	SUNDRIES	\$ 400.00	\$ 53.04
TOTAL SPARE PARTS CHARGES		: \$ 17,711.00	\$ 10,419.92
TOTAL LABOUR CHARGES		: \$ 10,994.00	\$ 6,402.00
GRAND TOTAL		: \$ 28,705.00	\$ 16,821.92

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0235/2020/NS 10-Mar-20 Glory Tan 1 of 1 SLG 3233 X Audi A4 1.8 TFSI MU 8K203	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	Refrigerant pipe	\$ 299.00	\$	238.80
2	Repair kit for quick release coupling	\$ 65.00	\$	52.00
3	Coolant	\$ 86.00	\$	68.80
TOTAL		\$ 450.00	\$	359.60

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant