

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 31588

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0233/2020/NS
Date : 4-Mar-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Premium Automobiles Pte Ltd
Address : 55 Ubi Road 1
Singapore 408699
Telephone : (Off) +65 63882323
Type of Claim : Own Damage Claims
Policy No. :
Vehicle No : **SMN 9173 Y**
Model Code : Audi A7 5B 3.0 TFSI QU 4K
Model / Year : 31/8/2019
Engine No : DLZ 028225
Chassis No : WAUZZZF20KN081255
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 1-Mar-20
Place of Accident : Audi Centre Level 7 At 281 Alexandra Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408659
Tel: 6366 2323 Fax: 6841 1163

Telefax

Estimated Labour Charges for Accident Vehicle SMN 9173 Y

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00 ✓	
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	509	\$ 1,350.00 509	
3	To respray rear bumper. 559		\$ 1,200.00 559	
4	To carry out diagnostic check.	S/N	\$ 192.00 ✓	
TOTAL LABOUR CHARGES		:	<u>\$ 3,102.00</u>	

Premium Automobiles

65-Ubi Road I, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax:

Material List for Accident Vehicle Regn No. SMN 9173 Y

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	REAR BUMPER ✓ <i>DR</i>	\$	3,517.00	2,813.60
2	REAR BUMPER FIXING PARTS ?	\$	223.00	×
3	REAR BUMPER SPOILER ✓ <i>CR</i>	\$	833.00	666.40
4	TRIM MOLDING - CENTRE ✓ <i>BR</i>	\$	463.00	370.40
5	TRIM MOLDING - RH ✓ <i>BR</i>	\$	86.00	68.80
6	FRONT BUMPER SECURING STRIP ✓ <i>APC</i>	\$	162.00	129.60
7	TELEPHONE AERIAL - RH REAR ?	\$	167.00	×
8	REAR BUMPER CARRIER ?	\$	915.00	×
9	REAR BUMPER GUIDE SECTION - RH UPPER ?	\$	43.00	×
10	REAR BUMPER HOLDING STRAP - CENTRE ?	\$	111.00	×
11	REAR PARKING AID SENSOR ?		TBC	×
12	REAR PARKING AID SEAL RING ✓ <i>MC</i>	4 \$	14.00	
13	LED TAIL LIGHT - RH OUTER ✓ <i>BR</i>	\$	1,301.00	1,040.80
14	TAIL LIGHT TRIM - RH ✓ <i>MC</i>	\$	41.00	32.80
15	SUNDRIES ?	\$	300.00	×
TOTAL SPARE PARTS CHARGES		\$	8,176.00	
TOTAL LABOUR CHARGES		:	\$	3,102.00
GRAND TOTAL		\$	11,278.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Steve (LKK)

5/3/99, 11.00 am
OD - Not Acc'd (R.O.I)

EXC - ?

P/P

My BL by

3 days

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant