



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/LCR19001962/Gtd3s2-1

78 SHENTON WAY #08-16  
CHARTIS BUILDINGS SINGAPORE 079120

Date : 27-04-2020



ATTN: NG JEFFREY

Code : LCR

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLM 4539B	<b>Veh. Inspected</b>	SFH 9090S
<b>Policy No.</b>	0999994774	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	4940415371SG	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	NG JEFFREY	<b>Assign Date</b>	05/03/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MERCEDES-BENZ C180	<b>c.c</b>	1595
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2013
<b>Chassis No.</b>	WDD2043312G132358	<b>Colour</b>	GREY
<b>Odometer</b>	-	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	225/45 R17	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	225/45 R17	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	225/45 R17	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	225/45 R17	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

<b>Accident Date</b>	26/01/2019	<b>Inspection Date</b>	30/01/2019
<b>Survey held at</b>	AUTO ASSIST-2 KAKI BUKIT AVE 2# 01-33		
<b>Repairer</b>	-		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>18 Working Days</b>
-------------------------------------	------------------------