

um Automobiles

Singapore 408699
Fax: 6841 1183

Material List for Accident Vehicle Regn No. SMN 7057 M

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
61	AIR INTAKE DUCT <i>Not nec</i>	\$	63.00	X
62	INTER COOLER GASKET <i>new</i>	\$	13.00	+
63	AIR FILTER <i>new</i>	\$	256.00	+
64	WATER DRAINAGE HOSE <i>new</i>	\$	32.00	+
65	AIR INTAKE MANIFOLD <i>Not nec</i>	\$	131.00	X
66	RADIATOR AIR GUIDE - LH / RH <i>RH Disltd</i>	2 \$	46.00 23	nn
67	RADIATOR AIR GUIDE - UPPER CENTRE <i>Disltd</i>	\$	12.00	✓ nn
68	FRONT WINDOW SLOT SEAL - LH / RH <i>new</i>	2 \$	508.00	+
69	ROOF MOULDING - LH / RH <i>new</i>	2 \$	1,112.00	+
70	FRONT NO PLATE <i>Disltd</i>	S/N \$	60.00	✓ \$60-00
71	SUNDRIES <i>Nec</i>	\$	500.00	? \$84-56
TOTAL SPARE PARTS CHARGES		:	\$ 33,799.00	
TOTAL LABOUR CHARGES		:	\$ 9,260.00	16,744.00
GRAND TOTAL		:	\$ 43,059.00	

50,543.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: