

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 31752

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0245/2020/NS
Date : 05-Mar-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

9 days exclude 1 Sunday - ok

jb 8 Apr 20

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Dong Siling, Anna
Address : BI 318A Anchorvale Link
#11-243
Singapore 541318
Telephone : +65 97121760
Type of Claim : Own Damage Claims
Policy No. : 1900148091
Vehicle No : **SMN 7057 M**
Model Code : Audi A3 Sportsback 1.0 TF
Model / Year : Aug-19
Engine No : CHZ C31354
Chassis No : WAUZZZ8V8KA099825
Mileage : 10512
Date In : 05-Mar-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 05-Mar-20
Place of Accident : Changi Navak Base

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMN 7057 M

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To remove and renew aircond condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	\$ S/N	1,200.00	\$ 1,200.00
3	To dismantle both front door panel trim. To remove and reinstall both wing mirror assy.	S/N \$	700.00	\$ 300.00
4	To dismantle and renew front bumper, both front fenders, bonnet and both headlights. To repair both front doors. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed. <i>(Included 2 Headlamps, charge cooler, misc. \$1000.00 at 2 days)</i>	\$	7,000.00	\$ 3,250.00
5	To respray front bumper, both front fenders, bonnet, hinges, both upper A-pillars and both front doors.	\$	7,100.00	\$ 2,750.00
6	To carry out pre-repair doagnostic check and post repair diagnostic check.	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 9,260.00	\$ 8,244.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 7057 M

S/N	Parts Description	Damage Parts & Prices		
			S/Nett	Remarks
1	FRONT BUMPER	\$	1,756.00	\$ 1,404.80
2	FRONT BUMPER FIXING PARTS	\$	176.00	
3	FRONT BUMPER GUIDE SECTION - LH / RH	2 \$	72.00	
4	FRONT BUMPER GRILLE - CENTRE	\$	151.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$	280.00	
6	FRONT BUMPER CLOSING ELEMENT - LH / RH	2 \$	560.00	\$ 223.60
7	RADIATOR GRILLE	\$	1,338.00	\$ 1,070.40
8	RADIATOR GRILLE - CLOSING ELEMENT	\$	180.00	\$ 143.60
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2 \$	354.00	
10	AIRCON STICKER	NEC \$	7.00	\$ 5.36
11	CAUTION SIGN STICKER	NEC \$	13.00	\$ 10.24
12	FRONT BUMPER SIDE REINFORCEMENT BEAM	\$	681.00	\$ 544.80
13	FRONT BUMPER FOAM FILLER PIECE	\$	178.00	\$ 142.40
14	FOAM FILLER PIECE COVER	\$	115.00	\$ 91.60
15	SIGNAL HORN - LH HIGH TONE	\$	188.00	
16	SIGNAL HORN - RH LOW TONE	\$	188.00	
17	FRONT FENDER - LH / RH	2 \$	1,604.00	\$ 641.20
18	FRONT FENDER ATTACHMENT PARTS	\$	68.00	\$ 40.96
19	FRONT FENDER BRACKET - LH / RH	2 \$	52.00	
20	FRONT FENDER BRACKET - LH / RH	2 \$	90.00	\$ 71.92
SUB TOTAL SPARE PARTS CHARGES		:	\$ 8,051.00	\$ 4,390.88

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 7057 M

S/N	Parts Description	c/f	Damage Parts & Prices		
			S/Nett	Remarks	
			\$		4,390.88
21	FRONT FENDER BRACE - LH / RH	2	\$ 180.00	\$	71.92
22	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 116.00	\$	45.92
23	FRONT WHEEL HOUSING LINER - LH / RH	2	\$ 318.00	\$	127.20
24	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 54.00		
25	BONNET		\$ 2,581.00	\$	2,064.80
26	BONNET ATTACHMENT PARTS		\$ 155.00	\$	91.84
27	BONNET LID HINGE - LH / RH	2	\$ 116.00		
28	SIDE SEAL - RH		\$ 39.00		
29	BONNET GAS FILLED STRUT		\$ 112.00		
30	BONNET EDGE PROTECTION - FRONT		\$ 26.00	\$	20.80
31	BONNET CATCH HOOK		\$ 84.00	\$	67.12
32	BONNET STRIKER - LH / RH	2	\$ 208.00	\$	165.60
33	BONNET LID LOCK	2	\$ 403.00	\$	322.40
34	BONNET BOWDEN CABLE - CENTRE		\$ 54.00	\$	43.20
35	BONNET LID LOCK CABLE		\$ 69.00	\$	55.20
36	LED HEADLIGHT - LH / RH	2	\$ 10,386.00	\$	8,308.80
37	MAIN LIGHT ELECTRONICS POWER MODULE - RH		\$ 714.00		
38	LED WITH HEAT SINK - RH		\$ 689.00		
39	LIGHT CONTROL SYSTEM CONTROL UNIT		\$ 524.00		
40	VENT HOSE - RH		\$ 38.00	\$	29.84
SUB TOTAL SPARE PARTS CHARGES		:	\$ 16,866.00	\$	15,805.52

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 7057 M

S/N	Parts Description	C/F	Damage Parts & Prices		Remarks
			S/Nett		
			\$		15,805.52
41	LIFT CYLINDER - LH / RH	2	\$ 268.00		
42	LIFT CYLINDER HOSE		\$ 64.00		
43	LOCK CARRIER		\$ 685.00	\$	547.60
44	AIRCON CONDENSER		\$ 519.00	\$	415.20
45	REFRIGERANT LINE		\$ 613.00	\$	490.00
46	REFRIGERANT LINE		\$ 471.00	\$	376.40
47	REFRIGERANT LINE BRACKET		\$ 25.00	\$	20.00
48	REFRIGERANT LINE DUAL CLIP		\$ 29.00	\$	22.48
49	RADIATOR		\$ 932.00	\$	745.20
50	ADDITIONAL RADIATOR		\$ 851.00	\$	680.40
51	RADIATOR BRACKET - UPPER	2	\$ 78.00	\$	62.24
52	RADIATOR BUSH - LOWER	2	\$ 19.00	\$	14.56
53	READY MIX COOLANT		\$ 169.00	\$	134.72
54	RADIATOR FAN RING		\$ 182.00		
55	RADIATOR FAN RING		\$ 1,070.00	\$	856.00
56	EXTERNAL TEMPERATURE SENSOR		\$ 55.00		
57	TEMPERATURE SENSOR BRACKET		\$ 18.00		
58	INTAKE AIR DUCT COVER		\$ 28.00	\$	21.84
59	AIR INLET		\$ 54.00	\$	42.80
60	AIR DUCT		\$ 19.00		
SUB TOTAL SPARE PARTS CHARGES			\$ 6,149.00	\$	20,234.96

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 7057 M

S/N	Parts Description		Damage Parts & Prices		Remarks
			S/Nett		
		c/f		\$	20,234.96
61	AIR INTAKE DUCT		\$	63.00	
62	INTER COOLER GASKET		\$	13.00	
63	AIR FILTER		\$	256.00	
64	WATER DRAINAGE HOSE		\$	32.00	
65	AIR INTAKE MANIFOLD		\$	131.00	
66	RADIATOR AIR GUIDE - LH / RH	2	\$	46.00	
67	RADIATOR AIR GUIDE - UPPER CENTRE		\$	12.00	
68	FRONT WINDOW SLOT SEAL - LH / RH	2	\$	508.00	
69	ROOF MOULDING - LH / RH	2	\$	1,112.00	
70	FRONT NO PLATE	S/N	\$	60.00	\$ 60.00
70a	ADDED PARTS - SEE ATTACHED		\$	1,141.00	\$ 898.40
71	SUNDRIES		\$	500.00	\$ 84.56
TOTAL SPARE PARTS CHARGES			:	\$ 34,940.00	\$ 21,277.92
TOTAL LABOUR CHARGES			:	\$ 9,260.00	\$ 8,244.00
GRAND TOTAL			:	\$ 44,200.00	\$ 29,521.92

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.