

FIRST AUTOWORKS

Repair Estimate

Date : 06/03/2020

Reference: SLK 4473S

To Whom It May Concern

Make: Opel
Astra

Dear Sir,

RE: VEHICLE : SLK 4473S
CHASSIS NO. W0LBE8EA2H8037542
ENGINE NO.: B1163237GT2X0617

TP Budget Direct
Shirley

Name of insured : ~~Amos Low Kim Fatt~~
Date of accident.: 04/03/2020

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BUMPER <i>Rebond</i>	1,500.00 ✓
2	1	FRT BUMPER SIDE RETAINER LH, Guide <i>new</i>	60.00 ✗
3	1	FRT BUMPER SIDE BRACKET LH <i>new</i>	58.00 ✗
4	1	FRT BUMPER TOW COVER <i>new</i>	40.00 +
5	1	FRT BUMPER CLIP SET - Rivet <i>new</i>	40.00 -
6	1	LH HEADLAMP <i>at</i>	820.00 -
7	1	FRT FENDER LH	740.00 +
8	1	FRT UPPER GRILLE	420.00 +
9	1	FRT LOWER GRILLE	210.00 +
10	1	FRT EMBLEM	120.00 +
11	1	FRT LH FOG LAMP	320.00 +
12	1	FRT LH FOG LAMP COVER	110.00 +
13	4	FRT BUMPER PARKING SENSOR	420.00 +
14	4	FRT BUMPER PARKING SENSOR SEAL	40.00 +
15	1	FRT BUMPER PARKING SENSOR WIRE HARNESS	618.00 +
16	1	FRT FENDER INNERSHIELD LH	180.00 +
17	1	FRT ENGINE UNDER DUST COVER LH	80.00 +
18	1	FRT BUMPER UNDER DUST COVER	190.00 +

Parts Total: 5,966.00
Less 10%: 596.60
Total: 5,369.40

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	2800.00 650
2	Carry out spray painting on accident affected area. (Frt bumper, LHF Fender)	1850.00 550
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	40.00 ✓
4	To conduct 4 wheel alignment	50.00 ✗

Labour Total : 4,740.00

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185


Other

<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	Frt Number Plate <i>Ne m</i>	40.00 ✓
Other Total :		40.00

Total : \$10,149.40
Gst (7%) : \$710.46
GRAND TOTAL: \$10,859.86

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN T COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Advisor
Ronnie Tan
DID: 6844 1985 Fax:6844 5185

Adrian Lj

P/P 10/03/20

03 Pays.

total: 3364 (P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933 Tel 68441985 Fax 68445185

TAX INVOICE

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD
Singapore Shopping Centre
190 Clemenceau Avenue #03-01
Singapore 239924

GST Ref. No: M2-0111811-5

Vehicle No: SLK 4473S
Chasis No :W0LBE8EA2H8037542
Engine No: B1163237GT2X0617

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

No	Qty	Description	Price (SGD)
1	1	FRT BUMPER	1,500.00
2	1	FRT BUMPER CLIP SET - Rivet	40.00
3	1	RH HEADLAMP	820.00

Total: 2360.00
Less 10%: 236.00
Parts Total : 2124.00


Labour

No	Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate & align repair /	650.00
2	Carry out spray painting on affect area frt portion (frt bumper)	550.00
3	To disconnect front wire harness of electrical component to facilitate repair, reconnect & check electrical function after repair	40.00

Labour Total : 1240.00

Sub Total : \$3,364.00
GST (7%) \$235.48
Grand Total: **\$3,599.48**

Yours Faithfully,



Ronnie Tan
Service Advisor
Tel: 68441985 Fax:68445185

E & O E

ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1ST AUTOWORKS PTE LTD"
PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE