

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

05-06-20

Date of Accident : 04-03-2020

OUR REF : SLW 2622D/T/20

KUIK TIEN HENG, DANIEL

Blk 210 Choa Chu Kang Central

#11-162

Singapore 680210

FWD: Ceilie
LKK - Mercedes

Date In/out: 05/13/20 to 05/03/20

Not Authorized
LKK
L/S \$13,500
9 days

VEHICLE NO : SLW 2622D

VEHICLE MODEL : MERCEDES BENZ B180

CHASSIS NO : WDD2462422J249860

LIST ITEM

Front Bumper		De/Don	1,440.88	✓
Front Bumper Side Retainer	2pcs @ 45.60	11	91.20	X
Front Bumper Clips	(set) 16pcs @ 8.00	80	128.00	✓
Front Bumper Parking Sensor - RH	2pcs @ 159.34	shoped	318.68	10c
Front Bumper Top Inner Pad Garnish		Torn	291.65	✓
Front Bumper Badge		rel	122.74	✓
Front Bumper Sponge		Torn	108.48	✓
Front Bumper Reinforcement		Barf	385.15	✓
Front Bumper Lower Chorme Moulding	2pcs @ 141.80	11	283.60	X
Bonnet		11	2,670.00	X
Bonnet Lock		8u	114.02	X
Bonnet Lock Catch		11	168.11	X
Bonnet Stand Clips		11	6.14	X
Front Grille		Che	640.18	✓
Front Grille Badge		Che	142.14	✓
Front Grille Badge Base		Che	298.63	✓
Radar Unit		shoped	431.68	✓
Head Lamp Assy	2pcs @ 1240.60	Che	2,481.20	✓
Head Lamp Lower Bracket		11	338.80	X

Front Support Panel		Bent/Cne	898.14	
Air Cond Condensor		Bent/Pur	1,018.64	
Air Cond Condensor Side Bracket	2pcs @ 34.10	11	68.20	X
Air Cond Condensor Side Air Grille Garnish RH & LH	2pcs @ 114.74	Torn	229.48	IPC
Air Cleaner Inlet Duct		Dis	139.16	
Rear Bumper Fascia		Torn	1,375.04	
Rear Bumper Side Retainer - LH		Bent	35.11	
Rear Bumper Side Attachement		Cng	29.16	
Rear Bumper Chorme Moulding	2pcs @ 161.82	Missio	323.64	IPC
Rear Bumper Clips	10pcs @ 8.00 1set 60	rec	80.00	
Rear Bumper Parking Sensor - LH		11	159.34	X
Rear Bumper Parking Sensor Holder - LH		11	18.11	X
Tail Lamp - LH		11	537.99	X
Tail Lamp Sealant		11	50.00	X
Tail Lamp Clips	2pcs @ 8.00	11	16.00	X
Rear Fender - LH		Bad good/wrong	2,468.14	
Rear Fender Splash Shield		Torn	141.63	
Rear Fender Splash Shield Clips	8pcs @ 8.00 1set 50	rec	64.00	
Rear Fender Air Vent		Two	58.10	
Rear Fender Glass Moulding		11	116.82	X
Rear Fender Glass Inner Seal		rec	52.14	
Rear Fender Glass Sealant		rec	60.00	30 S.W
Rear Fender Glass Clips	6pcs @ 8.00	11	48.00	X
Rear Knuckle Arm - LH	1150	Bent	1,490.00	
Rear Lower Arm		On	395.14	X
Rear Trailing Arm		Cne	440.62	
Rear Upper Arm		11	381.64	X
Rear Absorber		Two	498.60	
Rear Absorber Mounting		11	80.60	X

15733-12

Rear Wheel Bearing Hup

Page 480.61

	22,215.33
Less Discount 10%:	2,221.53
	19,993.80

SPECIAL NETT ITEM

Sport Rim Assy

1,680.00 X

LABOUR CHARGE

Towing.

120.00 50

To Check Wiring System.

120.00 30

To Tuff Coat Affected Areas.

280.00 50

To Remove & Refix Interior Upholstery.

250.00 100

To Remove & Refix Rear LH Fender Glass.

180.00 100

To Remove & Refix Rear LH Undercarriage.

480.00 150

To Check and Adjust Computer 4 Wheel Alignment (Before & After).

240.00 100

To Reset & Reprogramming Electrical Module System.

450.00 50

To Remove & Refix Air Cond Condensor, Vacuum & Top Up Gas.

280.00 100

To Remove & Refix Radiator & Top Up Coolant.

11 280.00 X

To Remove & Refix Rear LH Sport Rim & Contact Wheel Balancing.

11 120.00 X

To Respray Affected Areas.

2,200.00 1200

To Renew Damaged Parts, Straighten & Repair & Aligned All Parts.

2,100.00 1400

28,773.80

GST 7%: 2,014.17

TOTAL AMOUNT: 30,787.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: