

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 31831

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0246/2020/NS
Date	:	6-Mar-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Gunaravi Rajendran
Address	:	28 Jalan Peradun Singapore 808673
Telephone	:	HP +65 98396119
Type of Claim	:	Own Damage Claims
Policy No.	:	2100398005-05
Vehicle No	:	SDA 8777 L
Model Code	:	Audi A4 1.8 TFSI MU 8K203
Model / Year	:	Dec-14
Engine No	:	CJE 091344
Chassis No	:	WAUZZZ8K7FA056816
Mileage	:	107394
Date In	:	5-Mar-20
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	5-Mar-20
Place of Accident	:	Lorong 4 Jalan Yahya Awal Johor Bahru

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDA 8777 L

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 /	
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00	1250
3	To respray front bumper and rhs front fender.	\$ 2,000.00	5/6 1190
4	To carry out diagnostic check.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: \$ 5,002.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDA 8777 L

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER / <i>DD</i>	\$ 2,169.00	
2	FRONT BUMPER FIXING PARTS ?	\$ 244.00	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ?	\$ 215.00	
4	FRONT BUMPER GRILLE - LOWER CENTRE ?	\$ 127.00	
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE ?	\$ 183.00	
6	FRONT BUMPER SUPPORT ELEMENT - UPPER ?	\$ 56.00	
7	FRONT BUMPER VENT GRILLE - RH ?	\$ 127.00	
8	FRONT WHEEL SPOILER - RH ?	\$ 48.00	
9	FRONT BUMPER GUIDE SECTION - RH / <i>BR</i>	\$ 34.00	
10	FRONT BUMPER FOAM FILLER PIECE ?	\$ 117.00	
11	FRONT BUMPER SIDE REINFORCEMENT BEAM ?	\$ 828.00	
12	FRONT BUMPER SUPPORT (RH) / <i>BR</i>	<i>12</i> \$ 24.00 <i>12</i>	
13	FRONT FENDER - RH / <i>DD</i>	\$ 932.00	
14	FRONT FENDER ATTACHMENT PARTS ?	\$ 54.00	
15	FRONT FENDER BRACKET - RH FRONT ?	\$ 50.00	
16	DEFORMATION ELEMENT - RH REAR ?	\$ 46.00	
17	FRONT FENDER BRACE - RH LOWER ?	\$ 112.00	
18	STONE CHIP GUARD X	\$ 69.00	
19	ADHESIVE TAPE X	\$ 52.00	
20	WHEEL HOUSING LINER - RH ?	\$ 226.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 5,713.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDA 8777 L

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	WHEEL HOUSING LINER ATTACHMENT PARTS - RH / <i>MC</i>	\$ 42.00	
22	HEADLIGHT MOUNTING - RH ?	\$ 112.00	
23	HEADLAMP BRACKET - RH ?	\$ 100.00	
24	HEADLIGHT - RH ?	\$ 2,208.00	
25	HALOGEN FOG LAMP - RH ?	\$ 247.00	
26	LIFT CYLINDER - RH / <i>MR</i>	\$ 198.00	
27	SUNDRIES ?	\$ 300.00	
TOTAL SPARE PARTS CHARGES		: \$ 8,920.00	
TOTAL LABOUR CHARGES		: \$ 5,002.00	
GRAND TOTAL		: <u>\$ 13,922.00</u>	

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

:

Steve (LKK)

Surveyed Date

:

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

6/3/20, 1.00pm
OD- Not Author (Revel)
P/P
By Re By
5 days
Excess - ?

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant