

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20003696/AKS3Q2

Date: 29/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900263626

Claimant

Vehicle No : JRA195

Insured Vehicle No : SMR5281Z

Date of Loss: 21/02/2020

Nature of Claim: TP

Claim No: 1493654122SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JRA195

Make & Model: PERODUA MYVI, 1.3 (A)

Engine No: T19B31G

Reg. Date: 11/08/2015 (Man. Year: 2015)

Chassis No: PM2M602S002238455

Colour: Purple

Odometer: 44244 km

Engine Capacity: 1298 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65R14

Rear Tyre Size:

175/65R14

Front Left Side: Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,499.00	1,532.00	1,967.00	56.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	580.00	1,070.00	64.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,149.00	2,112.00	3,037.00	58.98
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	5,149.00	1,600.00	3,549.00	68.93
+ GST 7.00/7.00% (S\$)	360.43	112.00	248.43	68.93
Nett Amount (S\$)	5,509.43	1,712.00	3,797.43	68.93
+ Loss of Use (3.0 x S\$20.00/day) (S\$)		60.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,774.00		
Global Sum Settlement (S\$)		1,770.00		

INSPECTION

Date of Assignment: 06/03/2020

Date Inspected: 06/03/2020 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)

1 Kaki Bukit Ave 6, Blk C #01-43

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Not Necessary	390.00 F	*- FL
2	8		*FRONT GRILLE CLIP	Not Necessary	52.00 F	*- FL
3	1		*FRONT GRILLE CHROME	Cracked	180.00 F	*180.00 FL
4	1		*FRONT GRILLE EMBLEM LOGO	Not Necessary	45.00 F	*- FL
5	1		*FRONT BUMPER	Cracked	480.00 F	*480.00 FL
6	10		*FRONT BUMPER CLIP	Necessary	65.00 F	*30.00 FL
7	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	50.00 F	*- FL
8	1		*FRONT BUMPER CENTER LOWER GARNISH	Not Necessary	160.00 F	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	290.00 F	*- FL
10	1		*FRONT R/H BUMPER SIDE RETAINER	Necessary	80.00 F	*35.00 FL
11	1		*FRONT R/H BUMPER FOG LAMP	Cracked	270.00 F	*270.00 FL
12	1		*FRONT R/H HEADLAMP	Cut	485.00 F	*485.00 FL
13	1		*FRONT R/H FENDER	Not Necessary	340.00 F	*- FL
14	1		*FRONT R/H FENDER COWLING	Not Necessary	180.00 F	*- FL
15	8		*FRONT R/H FENDER COWLING CLIP	Not Necessary	52.00 F	*- FL
16	1		*FRONT BUMPER PROXIMITY SENSOR	Damaged	380.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,499.00	1,680.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	148.00
Total Parts (S\$)	3,499.00	1,532.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT FRONT SENSOR	New	100.00	50.00
2	TO CHECK WIRING	New	100.00	30.00
3	TUFF KOTE	New	150.00	0.00
4	PANEL BEATING	New	600.00	300.00
5	SPRAY PAINTING	New	700.00	200.00
Gross Labour Cost (\$\$)			1,650.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >