



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

06/03/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPA16

Ichancha

Accident date: 21-02-2020

Estimated repair cost for vehicle no: JRA195 PERODUA MYVI

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front Grille <i>3x4</i>		\$390.00 <i>x</i>
2	8	Front Grille Clip <i>3x4</i>	\$6.50	\$52.00 <i>x</i>
3	1	Front Grille Chrome <i>needed</i>		\$180.00 <i>✓</i>
4	1	Front Grille Emblem Logo <i>3x4</i>		\$45.00 <i>x</i>
5	1	Front Bumper <i>needed</i>		\$480.00 <i>✓</i>
6	10	Front Bumper Clip <i>3x4</i>	\$6.50	\$65.00 <i>30</i>
7	1	Front Bumper Number Plate <i>3x4</i>		\$50.00 <i>x</i>
8	1	Front Bumper Center Lower Garnish <i>3x4</i>		\$160.00 <i>x</i>
9	1	Front Bumper Reinforcement <i>3x4</i>		\$290.00 <i>x</i>
10	1	Front Bumper Proximity Sensor <i>Dayd</i>		\$380.00 <i>200/s</i>
11	1	Front R/H Bumper Side Retainer <i>3x4</i>		\$80.00 <i>35</i>
12	1	Front R/H Bumper Fog Lamp <i>needed</i>		\$270.00 <i>✓</i>
13	1	Front R/H Headlamp <i>6x</i>		\$485.00 <i>✓</i>
14	1	Front R/H Fender <i>3x4</i>		\$340.00 <i>x</i>
15	1	Front R/H Fender Cowling <i>3x4</i>		\$180.00 <i>x</i>
16	8	Front R/H Fender Cowling Clip <i>3x4</i>	\$6.50	\$52.00 <i>x</i>

1480

1332

Subtotal:- \$3,499.00

S.N: 200

Labour charges

To remove & refit front sensor

~~\$100.00~~ 50

To check wiring

~~\$100.00~~ 30

Tuff kote

580

~~\$150.00~~ X

Panel beating

~~\$600.00~~ 300

Spray painting

~~\$700.00~~ 200

Subtotal:- \$1,650.00

Total:- \$5,149.00

total: 2112

h/s: 1.6K ✓

03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: