

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBC9585E200302

Estimate

Customer		Date: 05-03-20	
Name: AIG Asia Pacific Insurance Pte Ltd		Vehicle No: GBC9585E	
Address: Motor Claims Department		Model/Make: Fiat Doblo 1.6D	
78 Shenton Way #07-16		Cargo MJ (M)	
AIG Building		Singapore 079120	

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper	\$ 627.00	
2	Bumper Clips 1 set	\$ 50.00	
3	Bumper Reinforcement	\$ 475.30	
4	Bumper Reverse Sensor 1 set	\$ 220.00	
5	End Panel	\$ 620.00	
	To check all wiring & electrical component for proper function	\$ 50.00	
	Remove and refix rear bumper reverse sensor	\$ 120.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 400.00	
	To putty & spray painting & including touch up paint on accident affected area	\$ 500.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 3,062.30

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

Not Allocated
Liu
1/5 @ 1600
3 days.

P-1152.30
107
P-1037.07
S.N-200.00
L-770.00
2007.07
207
1605

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: