


ESTIMATE

Date : 06/03/2020
To : INDIA INTERNATIONAL INSURANCE PTE LTD
Attn. : *Not Authorised*
Office / Mobile :
Email Address : *Recovery B4 paint*
From : MOTORVIVA PTE LTD
Attn. : KONYINSIEW
Office / Mobile : +65 6861 0007
Email / Fax No. : KonYinSiew@goldbell.com.sg
Reg No : GBJ4520M
Model : 263.22Q.1 (632 BLACK METALLIC)
Chassis No : ZFA26300006H36730
Engine No : 263A8C008156910
Quotation No. : 107087
Ref. No. :
D.O.A. : 04/03/2020
Policy No. : MS005049
Claim Type : TP CLAIM - INDIA
Workshop : 8 TUAS AVE 1E
6 days 88459.00

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		REAR BACK DOOR LH	1	1,796.48	0	1,796.48	1,796.48
2		REAR BACK DOOR RH	1	1,790.71	0	1,790.71	1,790.71
3		REAR BACK DOOR PANEL LH	1	243.39	0	243.39	243.39
4		REAR BACK DOOR PANEL RH	1	173.32	0	173.32	173.32
5		REAR BACK DOOR PANEL CLIPS	40	3.00	0	3.00	120.00
6		REAR BACK DOOR LH HINGE BOTTOM	1	146.72	0	146.72	146.72
7		REAR BACK DOOR LH HINGE TOP	1	146.72	0	146.72	146.72
8		REAR BACK DOOR RH HINGE BOTTOM	1	146.72	0	146.72	146.72
9		REAR BACK DOOR RH HINGE TOP	1	146.72	0	146.72	146.72
10		REAR BACK DOOR LOCK LH	1	178.55	0	178.55	178.55
11		REAR BACK DOOR CATCH RH	1	72.72	0	72.72	72.72
12		REAR BACK DOOR LOCK RH	1	230.23	0	230.23	230.23
13		REAR BACK DOOR CATCH LH	1	115.67	0	115.67	115.67
14		REAR BACK DOOR MOULDING	1	344.85	0	344.85	344.85
15		REAR BACK DOOR MOULDING UPPER	1	85.16	0	85.16	85.16
16		REAR BACK DOOR MOULDING CENTER	1	206.26	0	206.26	206.26
17		REAR BACK DOOR STEP	1	84.60	0	84.60	84.60
18		REAR BACK DOOR HANDLE LH	1	300.96	0	300.96	300.96
19		REAR BACK DOOR HANDLE RH	1	82.93	0	82.93	82.93
20		REAR EMBELM - FIAT	1	75.68	0	75.68	75.68
21		REAR WOLDING - PROFESSIONAL	1	103.94	0	103.94	103.94
22		REAR WOLDING - DOBLO	1	65.34	0	65.34	65.34
23		REAR WOLDING - MAXI	1	40.36	0	40.36	40.36
24		REAR WOLDING - 10S	1	47.47	0	47.47	47.47
25		REAR WOLDING - MULTIJET2	1	69.60	0	69.60	69.60
26		TAILAMP LH	1	417.55	0	417.55	417.55
27		TAILAMP RH	1	417.55	0	417.55	417.55
28		REAR BUMPER	1	596.75	0	596.75	596.75
29		REAR BUMPER RETAINER LH	1	26.75	0	26.75	26.75
30		REAR BUMPER RETAINER RH	1	26.75	0	26.75	26.75



IVECO





Motorviva Pte Ltd
A member of Goldbell Engineering

MOTORVIVA PTE LTD

Main Office: 8 Tuas Ave 18 Singapore 638892 Tel: 6865 2518
Finance: 8 Tuas Ave 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Showroom: 21 Toh Guan Road East #01-15 Toh Guan Centre Singapore 608603 Tel: 6865 2518 Fax: 6861 7956
Iveco: 8 Tuas Ave 18 Singapore 638892 Tel: 6863 6864 Fax: 6861 3676
Website: www.motorviva.com.sg
Co. Reg. No: 199507614Z

Page 2 / 4

ESTIMATE

Date :	06/03/2020	Reg No :	GBJ4520M
To :	INDIA INTERNATIONAL INSURANCE PTE LTD	Model :	263.22Q.1 (632 BLACK METALLIC)
Attn. :		Chassis No :	ZFA26300006H36730
Office / Mobile :		Engine No :	263A80008156910
Email Address :		Quotation No. :	107087
		Ref. No. :	
From :	MOTORVIVA PTE LTD	D.O.A. :	04/03/2020
Attn. :	KONYINSIEW	Policy No. :	MS005049
Office / Mobile :	+65 6861 0007	Claim Type :	TP CLAIM - INDIA
Email / Fax No. :	KonYinSiew@goldbell.com.sg	Workshop :	8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
31		REAR BUMPER REINFORCEANCE	1	258.04	0	258.04	258.04
32		REAR BUMPER SEAL GASKET	1	60.01	0	60.01	60.01
33		REAR BUMPER END PANEL	1	312.95	0	312.95	312.95
34		REAR BUMPER REFELCTOR LH	1	21.07	0	21.07	21.07
35		REAR BUMPER REFELCTOR RH	1	21.07	0	21.07	21.07
36		REAR BUMPER TOWING COVER	1	14.83	0	14.83	14.83
37		REAR BUMPER SCREWS	10	5.00	0	50.00	50.00

PARTS TOTAL : 108 9,038.42

SPECIAL NETT ITEMS

1	WINDSCREEN SEALANT	1		120.00
2	REAR VEHICLE NUMBER PLATE WITH CHASING	1		35.00
3	REVERSE SENSOR	1		350.00
4	STICKER - COMPANY LOGO	1		400.00
5	STICKER - SPEED LIMIT (70KM/H)	1		25.00
6	STICKER - 6 PAX	1		25.00

PARTS TOTAL: 955.00

P : \$4439


S/N : \$410

L : \$3620

\$8459



IVECO





Motorviva Pte Ltd
A member of Goldbell Engineering

MOTORVIVA PTE LTD
Main Office: 8 Tuas Ave 18 Singapore 638892 Tel: 6865 2518
Finance: 8 Tuas Ave 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Showroom: 21 Toh Guan Road East #01-15 Toh Guan Centre Singapore 608609 Tel: 6865 2518 Fax: 6561 7956
Iveco: 8 Tuas Ave 18 Singapore 638892 Tel: 6863 6864 Fax: 6861 3676
Website: www.motorviva.com.sg
Co. Reg No.: 199507614Z

Page 3 / 4

ESTIMATE

Date	: 06/03/2020	Reg No	: GBJ4520M
To	: INDIA INTERNATIONAL INSURANCE PTE LTD	Model	: 263.22Q.1 (632 BLACK METALLIC)
Attn.	:	Chassis No	: ZFA26300006H36730
Office / Mobile	:	Engine No	: 263A80008156910
Email Address	:	Quotation No.	: 107087
From	: MOTORVIVA PTE LTD	Ref. No.	:
Attn.	: KONYINSIEW	D.O.A.	: 04/03/2020
Office / Mobile	: +65 6861 0007	Policy No.	: MS005049
Email / Fax No.	: KonYinSiew@goldbell.com.sg	Claim Type	: TP CLAIM - INDIA
		Workshop	: 8 TUAS AVE 18

LABOUR CHARGES

1	TO REMOVE, REFIX & REPAIR AFFECTED DAMAGED PARTS. INCLUDING KNOCK OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS	2800.00	1800
2	TO REMOVE AND REFIX BOTH REAR DOOR WINDSCREEN	200.00	160
3	TO TRANSFER DOOR COMPARTMENT, LOCK AND MECHANISM, ETC	500.00	240
4	TO TRANSFER, CHECK, RECONNECT ALL NECESSARY WIRING SYSTEM AND CHECK FUNCTIONALLY	200.00	20
5	TO SAND DOWN, PUTTY, CLEAN, WASH, POLISH AND SPRAY PAINT INTERIOR AND EXTERIOR BOTH REAR BACK DOOR, REAR BUMPER AND END PANEL TO ORIGINAL COLOURS	2500.00	1400

LABOUR TOTAL :	6,200.00
SUB-TOTAL :	16,193.42
GST @ 7% for \$ 16,193.42	1,133.54
GRAND TOTAL (\$\$) :	17,326.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



IVECO

