

ASS. REC. BY:

REF: CS/EGI 20003721 AV f3

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Jacelyn Foo of Ergo Date/Time: 9.3.2020 10.15am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SBA 1818M Insured: XE 403K

at Workshop m/s New Hock Tech motor Tel: 67479241

of 1 Carri Bukit Ara 6 Bldg # 01-43 Autobay

Policy No: \_\_\_\_\_ Claim No: CDMCA 20000409 / SBA 1818M

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 6.3.2020  
(Client's Record)

CA / REV / REP. / REV 24 HRS <sup>up</sup> H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 9.3.2020 10.30am Person Contacted: Duky Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SBA 1818M-X</u>
	<u>XE 403K - CC4 / AXA 17019501 / Ueq 392 Ref. 09/10/2017</u>
<u>10/3/20</u>	<u>Informed Jacelyn pending workshop est by merimen</u>
<u>9/4/20</u>	<u>Adrian confirmed LS \$19,500 (Red SF, Totals, 59%)</u>
<u>9/4/20</u>	<u>Send preli revised via merimen</u>

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SBQ1818M Yr Regn: 2016 May  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Honda Vezel c.c. 1496  
 Colour: Red A/C: Insured / Std / NI / NA  
 Sp. Reading: 55512 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: RU11110345  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 215/60 R16  
 R: 215/60 R16

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Continental  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 09/03/20  
 Survey held at NHT  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>TP Ergo.</u>
	<u>MV : 56K</u>
	<u>PV : 36.9K</u>
	<u>Nett : 19.1K</u>

Date/Time, File Pass to?  : Prefi. Report  
 : Final Report

Days Of Repair: 14  
 Resurvey No. of Trip: 2

1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) 9/4 - typist

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Report Format: mainmen  
 Lump Sum / L.B.L: 19,500p

Survey Fee:	_____
Transportation:	_____
3 + PS. SI	_____
Photos	_____
Others	_____
TOTAL	_____



# 新福德車廠私人有限公司

## NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

09/03/2019

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TP Ergo.

Voron.

Accident date:

Estimated repair cost for vehicle no: SBQ1818M HONDA VEZEL 1.5 A

CHASSIS: RU31269326

S/N	QTY	ITEMS	U/PRICE	AMOUNT
1	1	Front Windscreen <i>cracked</i>		<del>\$2,200.00</del> 1488
3	1	Front Windscreen Moulding <i>new</i>		\$171.80 ✓
4	1	Front Wiper Garnish <i>Not New</i>		\$240.00 X
5	1	Front Bonnet <i>Dented</i>		\$892.30 ✓
6	2	Front Bonnet Hinge ?	\$48.50	\$97.00 X
7	1	Front Bonnet Lock <i>new</i>		\$97.80 X
8	1	Front Bonnet Insulator		\$122.30 X
9	8	Front Bonnet Insulator Clip <i>Not New</i>	\$6.50	\$52.00 X
10	2	Front Head Lamp <i>lot</i>	\$1,820.90	\$3,641.80 ✓
11	2	Front Head Lamp Lower Bracket <i>cracked</i>	\$45.00	\$90.00 ✓
12	1	Front Bumper <i>Deformed</i>		\$495.80 ✓
13	1	Front Bumper Lower Lid <i>lot</i>		\$351.00 ✓
14	10	Front Bumper Clip <i>new</i>	\$6.50	<del>\$65.00</del> 30
15	2	Front Bumper Side Retainer <i>new</i>	\$27.10	\$54.20 ✓
16	1	Front Bumper Number Plate <i>new</i>		\$50.00 X
17	1	Front Bumper Centre Lower Grille <i>Deformed</i>		\$96.80 ✓
18	1	Front Bumper Reinforcement <i>Bent</i>		\$321.80 ✓
19	2	Front Bumper Reinforcement Top Cover <i>new</i>	\$24.20	\$48.40 X
20	4	Front Bumper Reinforcement Top Cover Clip <i>new</i>	\$6.50	\$26.00 X
21	1	Front Bumper Towing Cover <i>new</i>		\$15.70 X
22	2	Front Bumper Fog Lamp <i>cracked</i>	\$327.70	\$655.40 ✓
23	2	Front Bumper Fog Lamp Cover <i>cracked</i>	\$45.00	\$90.00 ✓
24	1	Front Grille Outer Cover		\$385.00 ✓
25	1	Front Grille Inner <i>cracked</i>		\$268.90 ✓
26	1	Front Grille Emblem Logo <i>new</i>		\$27.40 ✓
27	1	Front Grille Top Bracket <i>new</i>		\$45.80 ✓
28	1	Front Grille Chrome <i>new</i>		\$68.00 X
29	8	Front Grille Clip <i>new</i>	\$6.50	<del>\$52.00</del> 20

30	1	Front Support Panel			\$576.20*
31	1	Front Support Panel Top Cover			\$85.30*
32	10	Front Support Panel Top Cover Clip	X1P	\$6.50	\$65.00✓
33	1	Front Air-Con Condenser	ML		\$750.80*
34	1	Front Air-Con Condenser Fan Motor Assy			\$491.80*
35	1	Front Radiator			\$1,250.60*
36	1	Front Radiator Fan Motor Assy			\$509.10✓
37	1	Front L/H Side Mirror Assy			\$782.80*
38	1	Front L/H Fender			\$582.00*
39	1	Front L/H Fender Cowling	ML		\$130.00*
40	6	Front L/H Fender Cowling Clip		\$6.50	\$39.00*
41	1	Front R/H Fender <i>Dis/orted</i>			\$582.00✓
42	1	Front R/H Fender Cowling <i>low</i>			\$130.00✓
43	6	Front R/H Fender Cowling Clip <i>ML</i>		\$6.50	\$39.00✓
44	1	Front R/H Arch Protector <i>cut</i>			\$166.00✓
45	8	Front R/H Arch Protector Clip <i>ML</i>		\$6.50	<del>\$52.00</del> 30
46	1	Front Rim <i>cut</i>			\$758.60 400(SW)
47	1	Front Tyre <i>Not ML</i>			\$380.00*
48	2	Front Lower Arm <i>RH Best</i>		\$351.00	\$702.00 351
49	2	Front Knuckle Arm <i>RH Dmgd</i>		\$238.70	\$477.40 238.70
50	2	Front Knuckle Arm Bearing <i>RH Dmgd</i>		\$135.50	\$271.00 135.50
51	2	Front Shock Absorber <i>RH Best</i>		\$430.10	\$860.20 430.10
52	2	Front Drive Shaft <i>ML ML</i>		\$1,103.40	\$2,206.80*
53	1	Front Steering Rack <i>Best</i>			\$2,270.60✓
54	1	Front R/H Side Mirror Assy <i>Damaged</i>			\$782.80✓
55	1	Front R/H Door <i>Dis/orted</i>			\$1,000.60✓
56	2	Front R/H Door Hinge <i>Best</i>		\$43.00	\$86.00✓
57	1	Front R/H Door Outer Handle Assy <i>cut</i>			<del>\$416.90</del> 211
59	1	Front R/H Door Lock <i>Damaged</i>			\$296.60✓
60	1	Front R/H Door Weatherstrip <i>cut</i>			\$195.80✓
61	2	Front R/H Door Side Rubber <i>ML</i>		\$45.10	\$90.20*
62	2	Front R/H Door Frame Sticker <i>new</i>		\$30.10	\$60.20✓
63	1	Front R/H Door Inner Trim Board <i>cut/ok</i>			\$510.70✓
64	10	Front R/H Door Inner Trim Board Clip <i>ML</i>		\$6.50	<del>\$65.00</del> 30
65	1	Front R/H Door Inner Gear Motor Assy <i>Damaged</i>			\$400.70✓
66	1	Front R/H Door Glass <i>id</i>			\$605.70✓
67	2	Front R/H Door Glass Moulding <i>cut</i>		\$50.60	\$101.20
68	1	Rear R/H Door <i>Distorted</i>			\$1,000.60✓
69	2	Rear R/H Door Hinge <i>best</i>		\$42.00	\$84.00✓
70	1	Rear R/H Door Lock <i>Damaged</i>			\$270.20✓
71	1	Rear R/H Door Weatherstrip <i>cut</i>			\$106.60*
72	2	Rear R/H Door Side Rubber <i>ML</i>		\$30.60	\$61.20*
73	2	Rear R/H Door Frame Sticker <i>new</i>		\$38.90	\$77.80✓

74	1	Rear R/H Door Inner Trim Board	cracked		\$510.70	✓
75	10	Rear R/H Door Inner Trim Board Clip	new	\$6.50	<del>\$65.00</del>	30
76	1	Rear R/H Door Inner Gear Motor Assy	damaged		\$378.20	✓
77	1	Rear R/H Door Glass	new		\$380.00	X
78	2	Rear R/H Door Glass Moulding	replaced	\$49.00	<del>\$98.00</del>	48
79	1	Rear R/H Arch Protector	at		\$180.10	✓
80	8	Rear R/H Arch Protector Clip	new	\$6.50	<del>\$52.00</del>	30
81	1	Rear R/H Fender	cracked		\$1,018.20	✓
82	1	Rear R/H Fender Cowling	rust		\$94.60	✓
83	8	Rear R/H Fender Cowling Clip	new	\$6.50	\$52.00	+
84	1	Rear Axle	bent		\$1,583.60	✓
85	2	Rear Axle Bearing	RH and	\$328.60	<del>\$657.20</del>	378.60
86	2	Rear Shock Absorber	new	\$248.60	\$497.20	+
87	1	R/H Door Pillar Frame Assy	repair		\$1,293.50	X
88	1	R/H Rocker Panel Skirt	cracked		\$397.50	✓
89	10	R/H Rocker Panel Skirt Clip	new	\$6.50	<del>\$65.00</del>	30

90 1 Rear Rim - kit

~~758.60~~ 400 (500)

235 170

Subtotal:- \$38,416.00

10017.50 (201800)

**Labour charges**

To remove & refit cushion & trim board	<del>\$280.00</del> 80
To remove & refit air-con condenser, radiator, fan motor & top up gas	\$280.00 X
To remove & refit <sup>RT</sup> front <del>L/H</del> door, glass, lock, weatherstrip, frame sticker, trim board, window motor & regulator	<del>\$240.00</del> 80
To remove & refit <sup>RT</sup> rear <del>L/H</del> door, glass, lock, weatherstrip, frame sticker, trim board, window motor & regulator	<del>\$240.00</del> 80
To remove & refit front windscreen	\$120.00 ✓
Gum	\$60.00 X
To remove & refit front undercarriage, drive shaft & steering rack	<del>\$380.00</del> 300
To remove & refit rear axle, bearing & shock absorber	<del>\$380.00</del> 300
To check wheel alignment	<del>\$150.00</del> 80
To check wiring	<del>\$100.00</del> 80
Tuff kote	4840 <del>\$150.00</del> 80
Towing fee	<del>\$150.00</del> 60
Panel beating	<del>\$2,500.00</del> 1700
Spray painting	<del>\$3,000.00</del> 1900

Subtotal:- \$8,030.00  
 Total:- \$46,446.00 47,204.60

total 24457.52  
 h/s. 19500.

14 Days.

19516  
 14271

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: