

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:		Date:	09 Apr 2020
<u>Preliminary Advice</u>			

Insured Vehicle No	: XE403K	Accident Date	: 06/03/2020
TP Vehicle No	: SBQ1818M	Assignment Date	: 09/03/2020
Make	: HONDA ACCORD	Est. Duration of Repair	: 14 DAYS
Date of Inspection	: 9/3/2020		
Inspection At	: NEW HOCK TECK MOTOR PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s body and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	47,204.60
Revised Amount	:S\$	24,481.52
Check Items (Estimated)	:S\$	0.00
Total	:S\$	24,481.52
Lump Sum Repair (estimated)	:S\$	19,500.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
(X)	Other comments : The vehicle survey on "WITHOUT PREJUDICE" basis.