

ASS. REC. BY: Sun AnREF: NTUC NSI/NC 0003726 / 09f352

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

At Workshop m/s _____

of _____

Insured: SKF 87284Policy No. 51044518 0-01 (15/01/2020 - 14/01/2021)Claims No. M7/1089603-001

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHB5472 H Yr Regn: 19/12/2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Prius c.c. 1798Colour: Maroon A/C: Insured / Std / NI / NASp. Reading: 190420 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTOKB3FU403574124Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: NII / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 05/03/2020 D.O.I. 6/3/2020Survey held at SMARTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>SHB 5472 H - NA / MSG 17001146 / 24 DCA 06/01/2017 T.P.</u>
	<u>SKF 87284 - X TAX/03/20/2012</u>
	<u>SKF 87284</u>
	<u>RECEIVED 20 MAR 2020</u>
	<u>Confirm with Poh Jun</u>
	<u>Finalize \$1119.63 @ 3 day (P/P) Used @ 6397.07, 85%</u>

Date/Time, File Pass to?

☐ : Prel. Report1) 26/3 1119.63☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Westland (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Phone

Others

TOTAL

Rep. Formel: TPLump Sum / I.E.I.: 1119.63

Shiau Chan (LKKAUTO)

From: MTCL@income.com.sg
Sent: Wednesday, 25 March 2020 5:51 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: REQUEST CLAIM NUMBER

Hi,

Please refer to below for the claim number, thanks.

Regards,

Ignatius Koh
Operations, Motor & Personal
Lines
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in wit
yo

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Wednesday, 25 March 2020 2:02 PM
To: MTCL@income.com.sg
Subject: REQUEST CLAIM NUMBER

Dear Sir/Madam,

Please refer to the below:

TP Claims against NTUC Income: Follow-Through Survey

Date : 25/03/2020

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	D:
1	MT/1089603-001	SMRT TAXIS PTE LTD	SHB 5472H	SKF 8728U	

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	05/03/2020 11:02
Vehicle No.(For Motor)	SKF8728U	Certificate Number	

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5107255180-01		TAY SUAN CHOON	S7717461C	GPC	drivo CLASSIC	SKF8728U	SKF8728U	15/02/2020	14/02/2021

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/03/2020 15:50
Date Of Accident	05/03/2020 03:50
Exact Location Of Accident	KPE (BEFORE BUANGKOK DR EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5472H
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	1XXXXX369K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-80000000
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	
Driver	
Name of Driver	LIM KIM WAH
NRIC No	SXXXX865G
Date Of Birth	25/09/1955
Occupation	OUTDOOR
Date Of Driving Pass	05/01/1976
Driving Experience	44 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 11
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG KPE TOWARDS BUANGKOK DRIVE (BEFORE BUANGKOK DRIVE EXIT), SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SKF8728U HAD COLLIDED ONTO THE REAR OF MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TOO BIG
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKF8728U
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver TAY SUAN CHOON
 NRIC/Passport Number SXXXX461C
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

A diagram showing three upward-pointing arrows and two boxes labeled A and B. Box A is on the middle line, and box B is on the bottom line.

B-SKF87284

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No :

Sketch Plan Pg. 2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB5472H
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Mar 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8282118
Chassis No.:	JTDKB3FU903579129
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$24,655.00
Total Rebate Amount:	\$28,405.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 09 Mar 2020

OK



Case Details

Case Reference Number :

TAX/03/20/2012

Type of Repair : Accident Repair

Vehicle Registration Number :

SHB5472H

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-10750-ID

Assigned By : Taxi Claims Manager
TeamInsurance Company Name : NTUC Income Insurance Co-operative
Ltd

Accident Date and Time : 04/03/2020 07:50 PM

Vehicle Age(In Months) : 27

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	Repair	X R
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	X Svc
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	1	11.00	11.00	25.00	8.25	Replace	0	0	Check	X Svc
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	1	3.80	3.80	25.00	2.85	Replace	1	2.85	Replace	/ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	1	3.80	3.80	25.00	2.85	Replace	1	2.85	Replace	/ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	1	3.80	3.80	25.00	2.85	Replace	1	2.85	Replace	/ Nec
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Check	X Svc
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give	X Svc

Total Spare Part Cost 4,030.06

Surveyor Total 569.62

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 3,408.91

Final Sur Total 569.62

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SEAL, RR BUMPER , RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	X SVC
One Time Key In	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	X SVC
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	✓ Nec
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	✓ SCH
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	1	0	Repair	X SVC
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Give	X SVC
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	1	11.10	Replace	✓ SCH
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ Nec
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	X SVC
One Time Key In	Main			COVER, REAR FLOOR UNDER , RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Check	X SVC
One Time Key In	Main			COVER, REAR FLOOR UNDER , LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Check	X SVC
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Check	X SVC
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0	Check	X SVC
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	438.10	10.00	394.29	Replace	1	0	Old Dam	X SVC

Total Spare Part Cost 4,030.06

Surveyor Total 569.62

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 3,408.91

Final Sur Total 569.62

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FENDER SUB-ASSY, FR, RH	1	933.10	933.10	25.00	699.83	Replace	0	0	Not Give	X Svc
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	0	0	Not Give	X Svc
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Check	X Svc
Total Spare Part Cost									4,030.06	Surveyor Total 569.62				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									3,408.91	Final Sur Total 569.62				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LEFT REAR PORTION	507.00	200	
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	0	
4	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	80	
5	Main	TO RESPRAY REAR FENDER RH	378.00	0	
6	Main	TO RESPRAY REAR PANEL	180.00	0	
Total:			1,476.00	280.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			360.00	70.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	20.00	30	✓
2	Main	TO REPLACE SUNDRY PARTS	100.00	20	✓
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	✓
4	Main	TO WASH AND VACUUM	60.00	0	
Total:			360.00	70.00	

4516.70

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	3,408.91	569.62
Total Labour Cost	507.00	200.00
Total Spray Painting	1,476.00	280.00
Other	360.00	70.00
Overall Total	5,751.91	1,119.62
Lump Sum Repair Option		
Lump Sum Total	0.00	1,119.62
Surveyor Approved Amount		1,119.62
No of Repair Days*	5	3
Remarks	*	F/P Repair, Before paint photo.

Surveyor Name

Sun Pin (LKK)

Signature

Survey Date

06/03/2020

Save Clear


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- Is subject to final approval from Insurance

Acknowledged by Repairer

Signature:

Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park E4, Singapore
P&A Number: 03685592
Estimator Telephone Number: 68667423
Accident Reporting Number: 68667677

Date Generated: 19/03/2020

User ID: Pong Guan

Section A - Accident Details

Registration Number	SHB5472H
Case Reference Number	TAX/03/20/2012
Registration Date	19/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LEE KIM WAH
Type of Accident	Head to Rear
Accident Date and Time	5/3/2020 3:50 AM
Accident Reported Date and Time	5/3/2020 3:56 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24106040
Special Instruction to ARC, if any	TP / REAR PORTION/ NTUC - LKK
Prepared Date and Time	6/3/2020 12:54 PM
Chassis Number	
License	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$1,476.00	\$280.00
Total Spare Part Cost	\$4,030.06	\$569.62
Total Other Cost	\$360.00	\$70.00
TOTAL COST	\$6,373.06	\$1,119.62 (P/P)
Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Requested / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	06/03/2020 1:12 PM	06/03/2020 3:42 PM
Signature		
Remarks		P/P Repair, Before paint photo

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2003-0236	Invoice Number	
Quotation Date	14.03.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates
Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LEFT REAR PORTION	\$507.00	\$200.00
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$80.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,476.00	\$280.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
PLACE SUNDRY PARTS	\$100.00	\$20.00
CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$360.00	\$70.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	100.00	\$0.00	Replace	Repair
		5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check
		5219147030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Check
		5246247030	PAD, RR BUMPER, RH & LH, 1	1.00	\$3.80	25.00	\$2.85	Replace	Replace
		5246247020	PAD, RR BUMPER, RH & LH, 2	1.00	\$3.80	25.00	\$2.85	Replace	Replace
		5246247010	PAD, RR BUMPER, RH & LH, 3	1.00	\$3.80	25.00	\$2.85	Replace	Replace
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Check
		5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given
		5259147050	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given
		5259247040	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
Fax Number: 63652562
Estimator Telephone Number: 63662623
Accident Reporting Number: 63652672

Date Generated: 19/03/2020

User ID: PehSuan

	52453470	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace	
TOTAL	52565479	FILLER, RR BUMPER, RH	1.00	\$119.90	100.00	\$0.00	Replace	Repair	
	52566479	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X
	52169470	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace	
		PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	
		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
	58398470	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Check	
	58399470	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Check	X
	66259470	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Check	X
	89997301	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Check	X
	81551472	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$438.10	100.00	\$0.00	Replace	Old Damage	X
	53801470	FENDER SUB-ASSY, FR, RH	0.00	\$933.10	0.00	\$0.00	Replace	Not Given	X
	53875470	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given	X
	58307470	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Check	X
Total				\$5,100.20		\$569.63			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

569.63 /
+ 200.00 /
+ 350.00 /
1119.63 /

3 days

P/P



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20003726/Qqf3s2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 01-04-2020	
Code: INC4			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKF 8728U	Veh. Inspected	SHB 5472H
Policy No.	5107255180-01	Coverage (\$)	0.00
Claim No.	MT/1089603-001	Excess (\$)	0.00
Assign From		Assign Date	06/03/2020
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU903579129	Colour	MAROON
Odometer	190420	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/03/2020	Inspection Date	06/03/2020
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5472H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	PAD, RR BUMPER, RH & LH, 1 (DISC 25%)	NECESSARY	3.80	2.85
1	PAD, RR BUMPER, RH & LH, 2 (DISC 25%)	NECESSARY	3.80	2.85
1	PAD, RR BUMPER, RH & LH, 3 (DISC 25%)	NECESSARY	3.80	2.85
10	CLIPS PIECE, FRT & RR BUMPER @ \$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	GUARD, RR BUMPER, LOWER (DISC 25%)	SCRATCHED	558.30	418.73
1	COVER, GUARD RR BUMPER LOWER (DISC 25%)	SCRATCHED	14.80	11.10
2	PIXEL STICKER @ \$60.00 (SN)	NECESSARY	120.00	120.00
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	318.80	-
1	SEAL, RR BUMPER ARM, RH & LH	SERVICEABLE	11.00	-
1	RETAINER, RR BUMPER, RH	SERVICEABLE	112.70	-
1	RETAINER, RR BUMPER, LH	SERVICEABLE	111.50	-
1	SEAL, RR BUMPER, RH	SERVICEABLE	85.20	-
1	SEAL, RR BUMPER, LH	SERVICEABLE	85.20	-
1	FILLER, RR BUMPER, RH	SERVICEABLE	119.90	-
1	FILLER, RR BUMPER, LH	SERVICEABLE	119.90	-
1	SENSOR REVERSE	SERVICEABLE	180.00	-
1	COVER, REAR FLOOR UNDER, RH	SERVICEABLE	169.50	-
1	COVER, REAR FLOOR UNDER, LH	SERVICEABLE	234.30	-
1	COVER, REAR FLOOR UNDER CENTER	SERVICEABLE	222.60	-
1	ANTENNA, ELECTRICAL KEY	SERVICEABLE	60.30	-
1	LENS & BODY, REAR COMBINATION LAMP, RH	SERVICEABLE	438.10	-
1	FENDER SUB-ASSY, FR, RH	SERVICEABLE	933.10	-
1	LINER, FR FENDER, RH	SERVICEABLE	198.40	-
1	END PANEL SUB-ASSY, BODY LOWER BACK	SERVICEABLE	629.80	-
1	COVER, RR BUMPER ASSY	TO REPAIR SEE LABOUR	423.90	-
			5,173.70	569.63
LABOUR				
PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF COVER, RR BUMPER ASSY.			507.00	200.00

Report Ref No. NS/INC20003726/Qqf3s2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINT.		1,476.00	280.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	30.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,343.00	550.00
	GRAND TOTAL		7,516.70	1,119.63
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,119.63

Report Ref No. NS/INC20003726/Qqf3s2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.