

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 11 Mar 2020

Preliminary Advice

Vehicle No	: YN9495B	Accident Date	: 24/02/2020
Make	: MITSUBISHI CANTER	Policy No.	: DMCVSN3074451900
Assignment Date	: 09/03/2020	Excess	: S\$450.00
Date of Inspection	: 09/03/2020	Est. Duration of Repair	: 28 days
Inspection At	: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18 Singapore 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	45,124.83
Revised Amount	:S\$	24,938.83
Check Items (Estimated)	:S\$	19,142.00
Total	:S\$	44,080.83

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	40,000.00
COE / PARF Rebate	:S\$	2,882.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,118.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer agreed to undertake the repair cost not exceeding \$ 32,000.00 on lump sum basis.