

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

$$\begin{array}{r}
 P = 2,337.6 \\
 N = 30 \\
 L = 750 \\
 \hline
 3,117.6 \\
 - 20\% \\
 \hline
 2,494.08
 \end{array}$$

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 09/03/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLK8782Z

CHASSIS NO : RU11206596

MAKE / MODEL : Honda Vezel 1.5X CVT

DATE OF ACCIDENT : 06/03/2020

YOUR INSURED VEHICLE NUMBER : SKS9710U

MILEAGE : 122760 km

415
\$2,500
3 days

<u>PARTS DeSCRIPTION</u>		<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1	Front bumper / CR4	1PC	\$ 955.00	\$ 955.00	850
2	F/L fender wheel arch moulding / SCH	1PC	\$ 300.00	\$ 300.00	192
3	F/L headlampassy (LED) / CRA	1PC	\$ 2,100.00	\$ 2,100.00	1,850
Refurisher LH / CRA \$30 /					
LIST TOTAL S\$:				\$ 1,255.00	2,922
20.00% DISCOUNT S\$:				\$ 251.00	-20%
				\$ 1,004.00	2,337.6
<u>SPECIAL NETT</u>					
1	Front bumper clips / mee	1 SET	\$ 80.00	\$ 80.00	30
Special Nett Total S\$:				\$ 80.00	30
<u>LABOUR CHARGES</u>					
1	To labour charge for removing front bumper out to facilitate repairs and replacement of damaged part / fender		\$ 500.00	\$ 500.00	2,500
2	To respray front bumper and F/L fender wheel arc moulding		\$ 500.00	\$ 500.00	400
LABOUR TOTAL S\$:				\$ 1,000.00	
TOTAL S\$:				\$ 2,084.00	750
7% GST				\$ 145.88	
GRAND TOTAL S\$:				\$ 2,229.88	

Repair day - 3 days

Lump Sum Repair

After paint photo.

04/03/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: