

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5145S**AAD2003-035***Not Authorized
Recovery B4 point*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

06 MAR 2020

SHD 5145S

JTDKB3FU403077418

TOYOTA

PRIUS

4.3.2020

AIG

12-12-18

PART		LIST	
1	FRONT BUMPER	\$ Bu 1cm	516.00 ✓
1	FRONT BUMPER SIDE RETAINER LH	\$ Dir	82.30 ✓
1	REINFORCEMENT, FRONT BUMPER	\$ R	716.60 X
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$ R	246.10 X
1	ABSORBER, FRONT BUMPER, LOWER	\$ R	132.70 X
1	ABSORBER, FRONT BUMPER ENERGY	\$ R	79.60 X
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$ R	241.90 X
1	COVER, ENGINE UNDER, NO.1	\$ R	472.40 X
1	COVER, FRONT BUMPER HOLE, LH	\$ R	29.30 X
1	EXTENSION, FRONT BUMPER, LH	\$ R	120.10 X
1	FRONT LED LAMP (LOWER) LH	\$ m/cmt	951.40 ✓
1	FRONT HEADLAMP LH	\$ Cmt	2,637.60 ✓
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$ SVC	960.50 7X
1	MOTOR, HEADLAMP LEVELING, LH	\$ R	487.50 X
1	FRONT FENDER LH	\$ Bu	977.80 ✓
1	LINER, FRONT FENDER, LH	\$ Cmt	202.50 ✓
1	COVER SUB ASSY, FRONT PILLAR, UPPER LH	\$ R	100.40 X
1	FRONT FENDER EMBLEM LH	\$ R	54.60 ✓
1	PROTECTOR, FRONT FENDER SIDE PANEL, LH	\$ R	93.90
1	SEAL, FENDER APRON MUDGUARD, LH	\$ R	51.90
1	FRONT BONNET	\$ R	983.10
1	HINGE ASSY, HOOD, LH	\$ R	58.90
1	LEFT SIDE VIEW MIRROR	\$ R	1,339.30
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$ R	594.80
1	GRILLE SUB-ASSY, RADIATOR	\$ R	346.00
1	EMBLEM ASSY, RADIATOR GRILLE	\$ R	90.80
1	GRILLE, RADIATOR, LOWER NO.1	\$ R	170.10
1	PANEL SUB-ASSY, FRONT DOOR, LH	\$ R	1,300.70
1	TAPE, BLACK OUT, NO.1 FRT LH	\$ R	13.30

Trans-cab Auto Services Pte Ltd**AAD2003-035**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5145S

- 1 TAPE, BLACK OUT, NO.2 FRT LH
- 1 TAPE, BLACK OUT, NO.3 FRT LH
- 1 SUPPORT, RADIATOR, UPPER LH
- 1 SUPPORT SUB-ASSY, RADIATOR, LH
- 1 FRONT LH DRIVE SHAFT ASSY
- 1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 LH
- 1 JOINT ASSY, LOWER BALL, FRONT LH
- 1 KNUCKLE, STEERING, LH
- 1 ABSORBER ASSY, SHOCK, FRONT LH
- 1 GEAR ASSY, STEERING
- 1 COVER, RADIATOR SUPPORT OPENING

\$	<i>Sm</i>	43.50	}	<i>X</i>
\$	<i>Sm</i>	26.30		
\$	<i>Sm</i>	78.90		
\$	<i>Sm</i>	245.10		
\$	<i>Sm</i>	1,251.70		
\$	<i>Sm</i>	760.10		
\$	<i>Sm</i>	238.40		
\$	<i>Sm</i>	663.40		
\$	<i>Sm</i>	438.30		
\$	<i>Sm</i>	1,955.40		
\$	<i>Sm</i>	235.30		

TOTAL	\$	19,988.50
25%	\$	4,997.13
	\$	14,991.38

Special Nett

- 1 FRONT WHEEL RIM
- 1 FRONT WHEEL RIM COVER
- 1 FRONT TYRE 195/65/15
- 1SET CLIP, FRONT FENDER LINER
- 1 FRONT NUMBER PLATE WITH MOULDING
- 1SET BUMPER CLIP FRT
- 1SET FRONT BUMPER RETAINER CLIP
- 1 FRONT DOOR STICKER "Trans-Cab"
- 1 FRONT WINDSCREEN MOULDING
- 2 WINDSCREEN SEALANT
- 1 FRONT WINDSCREEN INNER SPONGE SEAL

\$	<i>Sm</i>	1,879.40	<i>X</i>
\$	<i>Sm</i>	211.50	<i>X</i>
\$	<i>Sm</i>	350.00	<i>X</i>
\$	<i>Sm</i>	35.00	✓
\$	<i>Sm</i>	200.00	<i>X</i>
\$	<i>Sm</i>	66.00	✓
\$	<i>Sm</i>	35.00	<i>X</i>
\$	<i>Sm</i>	100.00	<i>X</i>
\$	<i>Sm</i>	160.00	<i>X</i>
\$	<i>Sm</i>	253.80	<i>X</i>
\$	<i>Sm</i>	120.00	<i>X</i>

TOTAL	\$	3,410.70
--------------	-----------	-----------------

TOTAL PARTS	\$	18,402.08
--------------------	-----------	------------------

LABOUR

Panel Beating, Knocking And Straightening The Necessary
Portion, Remove And Renewal Of Parts, Adjust And Realign The
Same

\$ 6,000.00 *4000*

Putty And Spray Painting Of The Affected Portion.

\$ 6,000.00 *4400*

Trans-cab Auto Services Pte Ltd**AAD2003-035**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5145S

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Bonnet fittings, attachments and perform water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To transfer of Door fittings, attachments and perform water seepage test.	\$	170.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	380.00	X
TOTAL	\$	15,100.00	

Trans-cab Auto Services Pte Ltd

AAD2003-035

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5145S

Over All Total \$ 33,502.08

(PART-BY-PART) Repair Days

20 days

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: