

SLN 1698L

TP Budget Direct Veron.

Toyota Harrier 1986 CC

ZSU600094478

Rear Bumper Deformed	1343 ✓
Rear Bumper Clips. New	30 ✓
Rear Bumper Side Holder LH. New NEC	68 ✓
Rear Bumper Lower Garnish Deformed	407 ✓
Rear LH Wheel Rim. Cut	2157 500 (SN)
Rear LH Tyre. New	300 (SN) X
Rear LH Wheel Hub c/w Bearing. New	375. X

Panel Beating	400 200
Spray Painting.	800 600
Wiring.	50 X
To underbody.	100 30
To remove reverse sensor	100 50

6130.00

List: 1848

Len 25%: 1386

S.N: 500

Labour 880

total 2766

1/5 22K

03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ABC