



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CENTRAL NARCOTICS BUREAU

Ref : CC2/CNB20003777/Qeq2

CORPORATE SERVICES DIVISION

BLK B POLICE CANTONMENT COMPLEX 393 NEW Date : 17-03-2020

BRIDGE ROAD SINGAPORE 088763



Code : CNB

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	QX 1286H (SLL 9124L)
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	10/03/2020

2. Vehicle Particulars & Condition

Make & Model	MAZDA3	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	JM6B42A8G0346265	Colour	GREY
Odometer	36055	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	FALKEN	6 mm
L/H Front Tyre	205/60 R16	FALKEN	6 mm
R/H Rear Tyre	205/60 R16	FALKEN	6 mm
L/H Rear Tyre	205/60 R16	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	Inspection Date	10/03/2020
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	

5a. Remarks

--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Registration No. QX 1286H (SLL 9124L)

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Front LH Absorber	1	Bent	\$234.00	\$234.00	
1.2	Front LH Absorber Mounting	1	Bent	\$102.00	\$102.00	
1.3	Front RH Absorber	1	Serviceable	\$234.00	-	
1.4	Front RH Absorber Mounting	1	Serviceable	\$102.00	-	
1.5	Front LH Stabilizer Link	1	Bent	\$90.00	\$90.00	
1.6	Front LH Lower Arm	1	Bent	\$354.00	\$354.00	
1.7	Front Bumper	1	Crumpled	\$1,020.00	\$1,020.00	
1.8	LHS HeadLamp	1	Scratched	\$1,980.00	\$1,980.00	
1.9	Front LH Engine Under Cover	1	Crumpled	\$228.00	\$228.00	
1.1	Front LH Engine Under Cover Clips	10	Necessary	\$7.80	\$78.00	
1.11	Front LH Tyre Rim, 16"	1	Broken	\$936.00	\$936.00	
1.12	Front LH & RH Tyre (205/60/R16)	2	N/S Scratched	\$224.40	\$224.40	
	COSTING	TOTAL PARTS COST			\$5,246.40	
2	SCOPE OF REPAIRS					
2.1	Remove & Replace Front LH Absorber & Absorber Mounting					2
2.2	Remove & Replace Front RH Absorber & Absorber Mounting					0
2.3	Remove & Replace Front LH Stabilizer Link					1
2.4	Remove & Replace Front LH Lower Arm					1
2.5	Remove, Replace & Spray Paint for Front Complete Bumper					5
2.6	Remove, Replace & Wiring for LHS HeadLamp					0.5
2.7	Remove & Replace Front LH Engine Under Cover					0.5
2.8	Remove & Replace Front LH Tyre Rim					0.5
2.9	Panel Beat & Spray Paint for Front LH Fender					4

2.10	Putty & Spray Paint for Front LH Door					5
2.11	Putty & Spray Paint for Rear LH Door					5
2.12	Putty & Spray Paint for Rear LH Wheel Arc Panel					2.5
2.13	Putty & Spray Paint for Rear Bumper					4
2.14	Wheel Alignment Test					1
COSTING		TOTAL MAN-HOUR				32.00


Registration No. QX 1286H (SLL 9124L)

Vehicle Inspected By



OYSUN PIN

Asst. Automotive Assessor



ADRIAN LING WAI PING

B. Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. QX 1286H (SLL 9124L)

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

