

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 31561

## Telefax

Estimate : Accident Repairs  
Workshop : Ubi Road 1  
Contact No : 6366 2323  
Fax No : 6841 1183  
Reference : PA/OD/0238/2020/NS  
Date : 5-Mar-20

**Vehicle NOT IN workshop. Please arrange for survey**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

Owner's Name : Mr Mirchandani Ajay Narayan  
Address : 15 Tong Watt Road  
#22-08  
Singapore 238026  
Telephone : HP +65 81110501  
Type of Claim : Own Damage Claims  
Policy No. :  
Vehicle No : **SKW 9402 M**  
Model Code : Audi A3 Cabriolet 1.4 TFS  
Model / Year : Nov-15  
Engine No : CZC 293150  
Chassis No : WAUZZZ8V2G1039255  
Mileage : -  
Date In : -  
Estimated By : Johnny Boo / Allan Wu  
Accident Date : 16-Feb-20  
Place of Accident : Basement Car Park At Wharf Residence

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SKW 9402 M

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00 500	
3	To respray rear bumper. 550	\$ 900.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
<b>TOTAL LABOUR CHARGES</b>		<b>: <u>\$ 2,422.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SKW 9402 M

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER ✓ BR	\$	1,761.00
2	REAR BUMPER FIXING PARTS ?	\$	182.00
3	REAR BUMPER GUIDE SECTION - LH / RH ?	2 \$	30.00
4	REAR BUMPER LOCKING MECHANISM ?	2 \$	55.00
5	REAR BUMPER SPOILER - LH ?	\$	223.00
6	REAR LIGHT REFLECTOR - <del>LH</del> / RH ?	1/2 \$	78.00
7	REAR PARKING AID SENSOR ?	2	TBC
8	REAR BUMPER WIRING SET ?	\$	484.00
9	REAR BUMPER SIDE REINFORCEMENT BEAM ✓ BT	\$	538.00
10	REAR BUMPER BRACKET - LH / RH X	2 \$	24.00
11	REAR BUMPER GUIDE SECTION - LH / RH X	2 \$	126.00
12	SUNDRIES ?	\$	200.00
<b>TOTAL SPARE PARTS CHARGES</b>		:	<b>\$ 3,701.00</b>
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 2,422.00</b>
<b>GRAND TOTAL</b>		:	<b>\$ 6,123.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

9/3/20, 1.30pm  
: Steve (LKK) OD - ~~Not~~ Authn (Rev 1)  
: 3 days  
: P/P  
: Ry Del sm  
: Excess - ?

## Please Note

- : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant