

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 31561

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0238/2020/NS
Date : 5-Mar-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Mirchandani Ajay Narayan
Address : 15 Tong Watt Road
#22-08
Singapore 238026
Telephone : HP +65 81110501
Type of Claim : Own Damage Claims
Policy No. :
Vehicle No : **SKW 9402 M**
Model Code : Audi A3 Cabriolet 1.4 TFS
Model / Year : Nov-15
Engine No : CZC 293150
Chassis No : WAUZZZ8V2G1039255
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Feb-20
Place of Accident : Basement Car Park At Wharf Residence

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKW 9402 M

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓	✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,050.00 500 ✓	✓
3	To respray rear bumper. 550	\$ 900.00 550 ✓	✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$ 2,422.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKW 9402 M

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER ✓ BR	\$ 1,761.00	1408.80
2	REAR BUMPER FIXING PARTS ?	\$ 182.00	× NN
3	REAR BUMPER GUIDE SECTION - LH / RH ?	2 \$ 30.00	× NN
4	REAR BUMPER LOCKING MECHANISM ?	2 \$ 55.00	× NN
5	REAR BUMPER SPOILER - LH ?	\$ 223.00	× NN
6	REAR LIGHT REFLECTOR - LH / RH ?	1/2 \$ 78.00	× NN
7	REAR PARKING AID SENSOR ?	2 TBC	× NN
8	REAR BUMPER WIRING SET ?	\$ 484.00	× NN
9	REAR BUMPER SIDE REINFORCEMENT BEAM ✓ BT	\$ 538.00	430.40
10	REAR BUMPER BRACKET - LH / RH X	2 \$ 24.00	× NN
11	REAR BUMPER GUIDE SECTION - LH / RH X	2 \$ 126.00	× NN
12	SUNDRIES ?	\$ 200.00	× NN
TOTAL SPARE PARTS CHARGES		: \$ 3,701.00	
TOTAL LABOUR CHARGES		: \$ 2,422.00	
GRAND TOTAL		: \$ 6,123.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

9/3/20, 1.30pm
: Steve (LKK) OD - ~~Not~~ Authn (Rev 1)
: 3 days
: P/P
: Ry Del sm
: Excess - ?

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant