

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 31391

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0229/2020/NS
Date : 4-Mar-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Yap Yonh Thi
Address : 189 Tai Keng Garden
Singapore 534365
Telephone : +(65) 90020412
Type of Claim : Own Damage Claims
Policy No. : 1900119434
Vehicle No : **SLA 8988 A**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : Jul-19
Engine No : CVK 085637
Chassis No : WAUZZZF59KA065119
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Feb-20
Place of Accident : Multi Story Carpark At 282 Toh Guan Rd S(600282)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLA 8988 A

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 /	
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00	1250
3	To respray front bumper and rhs front fender. <i>1 door fender</i>	\$ 2,500.00	1650 1650
4	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 /	
5	To carry out diagnostic check.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: <u>\$ 6,252.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLA 8988 A

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER / 00	\$ 2,142.00	1713.60 ✓
2	FRONT BUMPER FIXING PARTS ? X NN	\$ 383.00	
3	FRONT BUMPER SECURING STRIP / MC	\$ 34.00	27 ✓
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE X NN	\$ 215.00	
5	FRONT BUMPER AIR GUIDE - RH X NN	\$ 59.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH X NN	\$ 446.00	
7	FRONT BUMPER GUIDE SECTION - RH ? X NN	\$ 34.00	
8	FRONT PARKING AID SENSOR - OUTER ? X NN	TBC	
9	FRONT PARKING AID SEAL RING MC X NN 4	\$ 14.00	
10	FRONT FENDER - RH / 00	\$ 997.00	797.60 ✓
11	FRONT FENDER ATTACHMENT PARTS MC X NN	\$ 50.00	
12	FRONT FENDER CLOSING ELEMENT - RH ? X NN	\$ 70.00	
13	FRONT FENDER BRACKET - RH ? X NN	\$ 33.00	
14	FRONT FENDER BRACE - RH ? X NN	\$ 112.00	
15	DEFORMATION ELEMENT BRACKET - RH ? X NN	\$ 46.00	
16	WHEEL HOUSING LINER - RH ? X NN	\$ 259.00	
17	WHEEL HOUSING LINER ATTACHMENT PARTS ? X NN	\$ 86.00	
18	WHEEL SPOILER - RH X ✓ CRA	\$ 69.00	55.20 ✓
19	WHEEL SPOILER TRIM - RH X ? X NN	\$ 34.00	
20	STONE CHIP GUARD - RH X / MC	\$ 48.00	38.40 ✓
SUB TOTAL SPARE PARTS CHARGES		: \$ 5,131.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLA 8988 A

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	FENDER LEDGE COVER - OUTER [?] ✓ NEC	\$ 34.00	27.20 ✓
22	FENDER LEDGE COVER - RH FRONT [?] ✓ NEC	\$ 15.00	12.00 ✓
23	LED HEADLIGHT - RH ✓ ^{cut}	\$ 7,438.00	5950.40 ✓
24	LIFT CYLINDER - RH X NN	\$ 187.00	
25	FRONT ALUMINIUM RIM - RH ✓ ^{cut}	\$ 964.00	771.20 ✓
26	ALUMINIUM RIM RUBBER VALVE 145 X NN ⁴¹	\$ 13.00	
27	SUNDRIES [?] X NN	\$ 300.00	
TOTAL SPARE PARTS CHARGES		: \$ 14,082.00	
TOTAL LABOUR CHARGES		: \$ 6,252.00	
GRAND TOTAL		: \$ 20,334.00	

All charges are not inclusive of GST.

Legend Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

:
:
:
:
:
:

Steve (LKK)

9/3/24, 3.00pm
00 - Not Author (Rmt)

P/P

Ry Bel sy

Excess - ?

6 days

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0229/2020/NS 18-Jun-20 Glory Tan 1 of 1 SLA 8988 A Audi A5 SB 2.0 TFS
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Front fender chrome trim RHS ✓ NEC	\$ 150.00	
TOTAL		\$ 150.00	

For Premium Automobiles Pte Ltd

Guo Qiang

LKK

Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0229/2020/NS 2-Jul-20 Glory Tan 1 of 1 SLA 8988 A Audi A5 SB 2.0 TFS
Quantity	Description	Unit Price	Amount
<u>Labours</u> 1	To dismantle and reinstall rhs front door panel trim. To remove and reinstall rhs wing mirror cover.	s/n \$ 400.00	280
TOTAL		\$ 400.00	

For Premium Automobiles Pte Ltd

Steve
16/9/20

 Authorised Signature