

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA15019938/KPA3Q2-1

Date: 21/10/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

GA004263

Claimant

Vehicle No : SHF724T

Insured Vehicle No :

SKD1048E

Date of Loss: 30/10/2015

Nature of Claim:

TP

Claim No: C0361230

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHF724T

Make & Model:

RENAULT LATITUDE, 2.0 D dCi (A)

Engine No:

M9R8839C002400

Reg. Date:

31/12/2014 (Man. Year: 2014)

Chassis No:

VF1ABL15AUC281169

Colour:

Metallic White/Red

Odometer:

73090 km

Engine Capacity:

1995 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side:

Rovelo 9 mm

Rear Left Side:

Rovelo 9 mm

Front Right Side:

Rovelo 9 mm

Rear Right Side:

Rovelo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,841.11	2,139.38	12,701.73	85.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,700.00	1,550.00	5,150.00	76.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,541.11	3,689.38	17,851.73	82.87
+ GST 7.00/7.00% (S\$)	1,507.88	258.26	1,249.62	82.87
Nett Amount (S\$)	23,048.99	3,947.64	19,101.35	82.87
+ Car Rental (4.0 x S\$133.75/day) (S\$)		535.00		
		(S\$)		
		4,482.64		
Liabile Amount (50.00%) (S\$)		2,241.32		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		2,246.67		
Global Sum Settlement (S\$)		2,200.00		

INSPECTION

Date of Assignment:

23/11/2015

Date Inspected:

23/11/2015 Inspected At:

Trans-cab Auto Services Pte Ltd (HQ)

No. 42 Sungei Kadut St 1

Singapore 729346

Estimated Period of Repair:

4.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jun 2017)
Parts:	143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHF724T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER FRT (CONSISTENT)	Serviceable	968.78 FL	*- FL
2	1	*BUMPER RETAINER FRT RH (CONSISTENT)	Serviceable	116.47 FL	*- FL
3	1	*BUMPER SUPPORT FRT RH (CONSISTENT)	Serviceable	18.37 FL	*- FL
4	1	*FENDER PANEL FRT RH (CONSISTENT)	Repair	602.95 FL	*- FL
5	1	*FENDER WHEELARCH FRT RH (CONSISTENT)	Serviceable	107.33 FL	*- FL
6	1	*DOOR MIRROR RH (CONSISTENT)	Serviceable	1,141.08 FL	*- FL
7	1	*DOOR PANEL FRT RH (CONSISTENT)	Repair	2,188.20 FL	*- FL
8	1	*DOOR HINGE UPPER RH (CONSISTENT)	Repair	211.15 FL	*- FL
9	1	*DOOR HINGE LOWER (CONSISTENT)	Repair	231.19 FL	*- FL
10	1	*DOOR CHECK FRT RH (CONSISTENT)	Serviceable	149.83 FL	*- FL
11	1	*DOOR LOCK FRT RH (CONSISTENT)	Repair	699.04 FL	*- FL
12	1	*DOOR CATCH FRT RH (CONSISTENT)	Repair	100.94 FL	*- FL
13	1	*DOOR HANDLE OUTER FRT RH (CONSISTENT)	Serviceable	198.55 FL	*- FL
14	1	*DOOR HANDLE CAP FRT RH (CONSISTENT)	Serviceable	20.34 FL	*- FL
15	1	*ROCKER PANEL OUTER RH (CONSISTENT)	Repair	759.61 FL	*- FL
16	1	*DOOR PANEL REAR RH (CONSISTENT)	Bent / Warped	2,188.20 FL	*2,188.20 FL
17	1	*DOOR HINGE UPPER RH (CONSISTENT)	Repair	242.88 FL	*- FL
18	1	*DOOR HINGE LOWER RH (CONSISTENT)	Repair	231.19 FL	*- FL
19	1	*DOOR LOCK REAR RH (CONSISTENT)	Repair	699.04 FL	*- FL
20	1	*DOOR HANDLE OUTER REAR RH (CONSISTENT)	Serviceable	97.31 FL	*- FL
21	1	*DOOR HANDLE MODULE REAR RH (CONSISTENT)	Serviceable	102.77 FL	*- FL
22	1	*FENDER PANEL REAR RH (CONSISTENT)	Repair	2,537.80 FL	*- FL
23	1	*BUMPER COVER REAR (CONSISTENT)	Repair	852.66 FL	*- FL
24	1	*SET FRONT BUMPER CLIP (CONSISTENT)	Not Necessary	66.00 FS	*- FS
25	1	*SET WHEELARCH CLIP RH (CONSISTENT)	Not Necessary	66.00 FS	*- FS
26	1	*CAP HUB RH FRT (CONSISTENT)	Serviceable	35.00 FS	*- FS
27	1	*RIM RH FRT (CONSISTENT)	Serviceable	385.00 FS	*- FS
28	1	*TYRE RH FRT (CONSISTENT)	Serviceable	330.00 FS	*- FS
29	1	*CAP HUB RH RR (CONSISTENT)	Dented	35.00 FS	*35.00 FS
30	1	*RIM RH RR (CONSISTENT)	Serviceable	385.00 FS	*- FS
31	1	*TYRE RH RR (CONSISTENT)	Serviceable	330.00 FS	*- FS
32	1	*DOOR STICKER TRANS-CAB (CONSISTENT)	Necessary	80.00 FS	*60.00 FS
33	1	*DOOR STICKER CLASSIC (CONSISTENT)	Necessary	30.00 FS	*15.00 FS
34	1	*DOOR STICKER 6555-3333 (CONSISTENT)	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,287.68	2,358.20
- List Item Discount on L Items 10.00/10.00% (S\$)	1,446.57	218.82
Total Parts (S\$)	14,841.11	2,139.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,800.00	500.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	880.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
5	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALACING	New	170.00	0.00
6	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
7	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
Gross Labour Cost (\$\$)			6,700.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >