



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2004909  
INV Date 14/07/2020  
Reference CC4/LPC20003789/T1da3n2  
Code LPC2



### PROFESSIONAL SERVICE FEE

Vehicle No. SHC 799T  
Insured Veh. GBB 8726C  
Claim No. 19/20/20/VC05/023171  
Policy No. Z19VC05003174  
Accident Date 07/03/2020  
Inspection Date 09/03/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC20003789/T1da3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 14-07-2020



Code : LPC2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 8726C	Veh. Inspected	SHC 799T
Policy No.	Z19VC05003174	Coverage (\$)	0.00
Claim No.	19/20/20/VC05/023171	Excess (\$)	0.00
Assign From	GERALD	Assign Date	09/03/2020

#### 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU080819	Colour	YELLOW
Odometer	717912	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	TRIANGLE	6 mm
L/H Front Tyre	205/60 R16	TRIANGLE	6 mm
R/H Rear Tyre	205/60 R16	TRIANGLE	6 mm
L/H Rear Tyre	205/60 R16	TRIANGLE	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS
---

#### 5. General Information

Accident Date	07/03/2020	Inspection Date	09/03/2020
Survey held at	DING AUTOMOTIVE PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 799T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR LHS FENDER (NPA)	TO REPAIR SEE LABOUR	-	-
1	REAR LHS DOOR (NPA)	TO REPAIR SEE LABOUR	-	-
			-	-
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR LHS DOOR STICKER BOOK NOW COMFORT DELGRO GOOGLE PLAY APPS STORE (SN)	CUT	150.00	100.00
			150.00	100.00
	<b><u>LABOUR</u></b>			
	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF REAR LHS FENDER AND REAR LHS DOOR .		600.00	300.00
	RESPRAY REAR LHS FENDER .		250.00	200.00
	RESPRAY REAR LHS DOOR .		250.00	200.00
	RUST PROOFING .		100.00	30.00
			1,200.00	730.00
<b>GRAND TOTAL</b>			<b>1,350.00</b>	<b>830.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>830.00</b>

Report Ref No. CC4/LPC20003789/T1da3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 799T

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 799T

RE-INSPECTION

