

SK Automobile Pte Ltd  
 (Co Reg. No. 201500047H)  
 23 Kaki Bukit Ave 4, #03-01  
 Vicom Inspection Centre (S415933)  
 Tel: 6789 5155 Fax : 6783 5155

TO	: AIG	DATE	: 9-Mar-20
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	: Asher.	VEHICLE NO	: SMC694C
ADDRESS	:	MODEL	: HONDA FIT
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:		: GK31320040
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT	: XIONG 8121 0478		

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Distorted</i>	1	\$ 998.00	\$ <u>998.00</u> <i>814</i>
2	TAIL GATE STOPPER <i>new</i>	1	\$ 28.50	\$ 28.50 <i>+</i>
3	TAIL GATE INNER LOCK <i>Distorted</i>	1	\$ 289.00	\$ <u>289.00</u> <i>198</i>
4	TAIL GATE WIPER MOTOR <i>new</i>	1	\$ 589.00	\$ 589.00 <i>+</i>
5	TAIL GATE ABSORBER <i>new</i>	2	\$ 136.20	\$ 272.40 <i>+</i>
6	TAIL GATE HINGE <i>new</i>	2	\$ 31.00	\$ 62.00 <i>+</i>
7	TAIL GATE DETECTOR <i>Not new cracked</i>	1	\$ 154.00	\$ <u>154.00</u> <i>85</i>
8	TAIL GATE WEATHER STRIP <i>lit</i>	1	\$ 154.00	\$ 154.00 <i>✓</i>
9	TAIL GATE INNER TRIM <i>cracked</i>	1	\$ 258.00	\$ 258.00 <i>✓</i>
10	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 110.00	\$ 110.00 <i>✓</i>
11	TAIL GATE OUTER GARNISH <i>new</i>	1	\$ 184.00	\$ 184.00 <i>+</i>
12	TAIL GATE OUTER GARNISH LOGO <i>new</i>	1	\$ 58.00	\$ 58.00 <i>+</i>
13	TAIL GATE REFELCTOR <i>new</i>	2	\$ 311.00	\$ 622.00 <i>+</i>

14	TAIL GATE EMBLEM "FIT" <i>Neu</i>	1	\$ 35.00	\$ 35.00	✓
15	REAR BUMPER <i>Distorted</i>	1	\$ 659.00	\$ 659.00	✓ 545
16	REAR BUMPER SIDE GARNISH <i>could</i>	2	\$ 121.00	\$ 242.00	✓
17	REAR BUMPER CENTER GARNISH <i>could</i>	1	\$ 124.00	\$ 124.00	✓
18	REAR BUMPER SIDE RETAINER <i>Neu</i>	2	\$ 45.00	\$ 90.00	✓
19	TAIL LAMP <i>could</i>	2	\$ 489.00	\$ 978.00	610. ✓
20	REVERSE SIREN <i>could</i>	1	\$ 121.00	\$ 121.00	65 ✓
21	REAR FENDER INNER TRIM (LOWER) <i>could</i>	2	\$ 389.00	\$ 778.00	385 ✓
22	REAR FENDER INNER SHIELD <i>Neu</i>	2	\$ 89.60	\$ 179.20	x
23	REAR END PANEL <i>Distorted</i>	1	\$ 542.00	\$ 542.00	✓
24	REAR FLOOR PANEL <i>Repair</i>	1	\$ 985.00	\$ 985.00	x
25	REAR FLOOR TOP BOARD <i>Deleted</i>	1	\$ 415.00	\$ 415.00	298 ✓
26	REAR END PANEL TOP GARNISH <i>could</i>	1	\$ 101.00	\$ 101.00	✓
27	REAR TOOLS TOOLS BOX COVER <i>Neu</i>	1	\$ 220.00	\$ 220.00	x
28	REAR TOOLS TOOLS BOX COMPARTMENT <i>could</i>	1	\$ 421.00	\$ 421.00	285 ✓
29	REAR EXHAUST TAIL PIPE <i>Neu</i>	1	\$ 898.00	\$ 898.00	x
30	REAR EXHAUST MOUNTING <i>Neu</i>	2	\$ 38.00	\$ 76.00	x

5334  
4267.20

TOTAL PRICE \$ 10,643.10  
LESS 20% \$ 2,128.62  
SUB TOTAL PRICE \$ 8,514.48

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Neu</i>	1	\$ 50.00	\$ 50.00	x
3	REAR BUMPER CLIP <i>Neu</i>	10	\$ 6.50	\$ 65.00	30
4	TAIL LAMP CLIP <i>Neu</i>	4	\$ 8.50	\$ 34.00	20
5	TAIL LAMP PANEL SEALANT <i>Neu</i>	2	\$ 80.00	\$ 160.00	x
6	TAIL LAMP INNER PANEL SEALANT <i>Neu</i>	2	\$ 80.00	\$ 160.00	x
7	TAIL GATE SEALANT <i>Neu</i>	1	\$ 80.00	\$ 80.00	x
8	TAIL GATE INNER TRIM CLIP <i>Neu</i>	12	\$ 6.50	\$ 78.00	30
9	TAIL GATE WINDSCREEN SEALANT <i>Neu</i>	1	\$ 80.00	\$ 80.00	40
10	TAIL GATE WINDSCREEN INNER SEAL <i>Neu</i>	1	\$ 80.00	\$ 80.00	40
11	REAR FENDER SEALANT <i>Neu</i>	2	\$ 80.00	\$ 160.00	x
12	REAR FENDER INNER SHIELD CLIP <i>Neu</i>	12	\$ 6.50	\$ 78.00	x
13	REAR FENDER INNER SHIELD CLIPS <i>Neu</i>	12	\$ 6.50	\$ 78.00	x
14	REAR FENDER INNER TRIM CLIPS <i>Neu</i>	19	\$ 6.50	\$ 123.50	50
15	REAR END PANEL INSULATION SEAL <i>Neu</i>	1	\$ 150.00	\$ 150.00	60
16	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200 ✓

17	REVERSE CAMERA <i>Not Nel</i>	1	\$ 450.00	\$ 450.00
			TOTAL	\$ 2,046.50

x 470

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	<del>\$1,500.00</del>	1000	
2	TO SPRAY PAINT AFFECTED AREA	<del>\$1,300.00</del>	800	
3	TUFF COAT	<del>\$180.00</del>	60	
4	WIRING CHECK	<del>\$60.00</del>	30	
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	<del>\$300.00</del>	80	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	<del>\$250.00</del>	50	
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	<del>\$200.00</del>	50	
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$120.00	✓	
9	TRANFER TAILGATE MECHANISM	\$80.00	✓	
10	CONDUCT WATER LEAKAGE TEST	\$100.00	x	
TOTAL		\$4,090.00	2270	

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 10,560.98  
 TOTAL LABOUR COST : \$ 4,090.00  
 TOTAL REPAIR COST : \$ 14,650.98

*Adrian King,  
 P/P 09/03/20  
 07 Days.*

**APPROVED DETAILS**

EXCESS  
 NO. OF WORKING DAYS  
 RE-SURVEY  
 PART BY PART OR LUMP SUM  
 DATE & TIME OF SURVEY  
 SURVEYED BY  
 CONTACT NUMBER  
 FAX NUMBER

JJK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- If display damaged, part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Total: 7007.20 ✓  
 (P/P)*