



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

09/03/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP A16

Yic

Accident date: 08/03/2020

Estimated repair cost for vehicle no: SLF2990E HONDA VEZEL 1.5 A '16

CHASSIS: RU11117696

S/N	QTY	ITEMS	U/PRICE	AMOUNT	
1	1	Front R/H Head Lamp <i>lt</i>		\$1,820.90	✓
2	1	Front Head Lamp Lower Bracket <i>crld</i>		\$45.00	✓
3	1	Front Bumper <i>Delonced.</i>		\$495.80	✓
4	1	Front Bumper Lower Lid <i>lt</i>		\$351.00	✓
5	10	Front Bumper Clip <i>NEC</i>	\$6.50	\$65.00	30
6	1	Front R/H Bumper Side Retainer <i>NEC</i>		\$27.10	✓
7	1	Front R/H Bumper Fog Lamp <i>3 NIP</i>		\$327.70	X
8	1	Front R/H Bumper Fog Lamp Cover <i>3 NIP</i>		\$45.00	X
9	1	Front R/H Fender <i>Dented</i>		\$582.00	✓
10	1	Front R/H Fender Cowling <i>torn</i>		\$130.00	✓
11	6	Front R/H Fender Cowling Clip <i>NEC</i>	\$6.50	\$39.00	30
12	1	Front R/H Protector <i>Delonced</i>		\$166.00	✓
13	8	Front R/H Protector Clip <i>m</i>	\$6.50	\$52.00	20
14	1	Front R/H Rim <i>lt</i>		\$758.60	480(SN)
15	1	Front R/H Tyre <i>NIP NEC</i>		\$380.00	X
16	1	Front R/H Lower Arm <i>Best</i>		\$351.00	✓
17	1	Front R/H Knuckle Arm <i>2nd</i>		\$238.00	✓
18	1	Front R/H Knuckle Arm Bearing <i>NEC</i>		\$135.50	✓
19	1	Front R/H Shock Absorber <i>Best</i>		\$430.10	X
20	1	Front R/H Drive Shaft <i>3 NIP</i>		\$1,103.40	X
21	1	Front Steering Rack <i>3 NIP</i>		\$2,270.60	X

485240

Subtotal:- \$9,813.70

388192

S.N: 480

Labour charges

To remove & refit front undercarriage, drive shaft & steering rack	220	\$380.00
To check wheel alignment		\$150.00 80
To check wiring	1130	\$100.00 30
Tuff kote		\$150.00 X
Panel beating		\$800.00 400
Spray painting		\$600.00 400

Subtotal:- \$2,180.00

Total:- \$11,993.70

total 5491.92

L/S. A.4K.

05 Days.

A.4K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:.