



Your Ref : CMTD2001037/GPL

Date: 28th April 2020

Our Ref : CS/SMO20003807/Hsf3s2

M/s Sampo Insurance Singapore Pte Ltd

50 Raffles Place

#05-01/06 Singapore Land Tower

Singapore 048623

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBE 7093K
ACCIDENT ON 07/03/2020 INSURED VEHICLE NO. SLN 8238M**

Instruction was received to inspect the vehicle Reg. No. FBE 7093K. The inspection was conducted on 10/03/2020 at the premises of M/s MS Car Auto Pte Ltd, 8 Kaki Bukit Avenue 4 #01-07 Premier @ Kaki Bukit Singapore 415875.

The following vehicle information was recorded:

Registration Number	: FBE 7093K
Make/Model	: YAMAHA T135
Year of Registration	: 2010
Body Colour	: Red
Chassis Number	: 5YP302210
Engine Capacity	: 135 cc
Speedometer Reading	: 31919 km

The vehicle sustained damages at the front portion and o/s body. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	1,500.00
Less: LTA Reimbursement Value (RV)	(S\$	317.00)
Nett Liability	S\$	1,183.00

Vehicle Inspected By:



LEE HOCK ANN
Asst. Automotive Assessor



K.K.LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.