

ASS. REC. BY:

REF:

C8/E61200003809/Ka83n2

Special Instruction:

Surveyor: Kenneth

## ASSIGNMENT (Office)

From (Person): Jacelyn Foo

of E61

Date/Time: 10/3/2020

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC5836L

Insured: GBE1132X

at Workshop in/s Trans-Cab

Tel:

of No. 2 Ang Mo Kio St. 63

Policy No:

Claim No: CDMCG20000427

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 7/3/2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction

Schedule (✓)

SHC5836L-X

GBE1132X-X

11/3/20 2:37pm revised to Jacelyn Foo via Meimien.

ASS. REC. BY:

REF: ERZ/

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time \_\_\_\_\_ Action / Instruction \_\_\_\_\_

1 /

C/Sump @ 7550 (Red @ 3321.75, 81%)

Veh No: S1TC 58362 Yr Regn: 12, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault LORIANE c.c. 1995

Colour: m. white / Red A/C: Insured / Std / NI / NA

Sp. Reading: 688870 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VF1A9L15AUC. 280921

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: MT / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

G17.

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 7/3/20

Survey held at

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 10/3/2020

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Rear body

The UIC / Chassis frame / Body Structure affected due to collision.

RECEIVED 13 MAR 2020

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

F - RS - SI

I - Others

TOTAL

Report Format :

MER-TP

Lump Sum / I.B.F. (\$

7550

350

11

361

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 11 Mar 2020

**Preliminary Advice**

Insured Vehicle No	: GBE1132X		
TP Vehicle No	: SHC5836L	Accident Date	: 07/03/2020
Make	: RENAULT LATITUDE	Assignment Date	: 10/03/2020
Date of Inspection	: 10/03/2020	Est. Duration of Repair	: 6.00
Inspection At	: TRANS-CAB SERVICES PTE LTD (HQ) 2 ANG MO KIO STREET 63 SINGAPORE 569111		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s rear body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	40,771.25
Revised Amount	:S\$	9,455.79
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,455.79

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## Nivitha (LKK Auto)

**From:** Jacelyn Foo <jacelyn.foo@ergo.com.sg>  
**Sent:** Tuesday, 10 March 2020 11:15 AM  
**To:** Meikwan@lkkauto.com; admin-d@lkkauto.com; admin-a@lkkauto.com  
**Cc:** Zheng Hanyang; Candy Kong; 'Zhe Wei'  
**Subject:** RE: ERGO Claims Ref: CDMCG20000427 | ARRANGE FOR SURVEY SHC5836L  
**Attachments:** img-310093834.pdf

Data Classification: Confidential, C3

**\*\* NOTE: Please create case, input our Claim ref no. and upload ALL survey related documents into Merimen. Payment invoices shall be ignored for cases that are not submitted via Merimen.**

Hi LKK,

Please conduct this survey request.

**(Note: Survey vehicle only, LOD will be handled by Ergo)**

Kindly inform us if you are not able to attend it.

Thank you!

Warmest Regards,  
Jacelyn Foo  
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five  
Singapore 038985  
DID: +65 6829 9199  
[jacelyn.foo@ergo.com.sg](mailto:jacelyn.foo@ergo.com.sg)

# ERGO

[www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

### EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message. Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference. ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

**From:** Candy Kong <candy.kong@transcab.com.sg>  
**Sent:** Tuesday, March 10, 2020 11:09 AM  
**To:** Jacelyn Foo <jacelyn.foo@ergo.com.sg>; 'Zhe Wei' <zhewei.kek@transcab.com.sg>

Cc: Zheng Hanyang <hanyang.zheng@ergo.com.sg>

Subject: ERGO Claims Ref: CDMCG20000427 | ARRANGE FOR SURVEY SHC5836L

Hi Jacelyn

Kindly arrange as below :

6	LKK	LKK Auto Consultants Pte Ltd
---	-----	------------------------------

Thks & Rdgs

Candy Kong

Claims Service Assistant



**TRANS-CAB SERVICES PTE LTD**

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

**From:** Jacelyn Foo [mailto:jacelyn.foo@ergo.com.sg]

**Sent:** Tuesday, 10 March, 2020 10:56 AM

**To:** Zhe Wei <zhewei.kek@transcab.com.sg>

**Cc:** 'Candy Kong' <candy.kong@transcab.com.sg>; Zheng Hanyang <hanyang.zheng@ergo.com.sg>

**Subject:** FW: ERGO Claims Ref: CDMCG20000427 | ARRANGE FOR SURVEY SHC5836L

Data Classification: Confidential, C3

Dear Zhe Wei,

Please refer to our list of surveyors :

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPk	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd
9	AJAX	AJAX Inspection Services Pte Ltd
10	AA	Appraisal Associate

Thanks!

Warmest Regards,  
Jacelyn Foo  
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five  
Singapore 038985  
DID.: +65 6829 9199  
[jacelyn.foo@ergo.com.sg](mailto:jacelyn.foo@ergo.com.sg)

[www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

#### EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

-----Original Message-----

From: Zhe Wei <[zhewei.kek@transcab.com.sg](mailto:zhewei.kek@transcab.com.sg)>  
Sent: Tuesday, March 10, 2020 9:49 AM  
To: ERGO Insurance Pte. Ltd. (Claims Department) <[claims@ergo.com.sg](mailto:claims@ergo.com.sg)>  
Cc: 'Candy Kong' <[candy.kong@transcab.com.sg](mailto:candy.kong@transcab.com.sg)>  
Subject: RE: ARRANGE FOR SURVEY SHC5836L

DEAR ALL,

Please arrange for survey as below :

GBE1132X - 07.03.2020 at 1440Hrs - SHC5836L

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate

Best Regards,  
Kek Zhewei  
Claims Officer

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

This email has been checked for viruses by AVG.  
<https://www.avg.com>



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Shiau Chan (LKKAuto)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Friday, 13 March 2020 11:34 AM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** FW: TP VEHICLE SHC 5836L (DOA: 07/03/2020) -- AAD2003-047  
**Attachments:** SHC5836 EST.pdf

### Without Prejudice

Dear Shiau Chan

Amount confirmed \$ 7,550 (before GST).

Thank You  
Best Regards,  
**Ng Wai Yin**  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**

TRANS-CAB SERVICES PTE LTD  
No. 2 Ang Mo Kio Street 63  
Singapore 569111  
Tel: 6287 6666 Fax: 6287 7764

---

**From:** Shiau Chan (LKKAuto) [mailto:[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)]  
**Sent:** Thursday, 12 March, 2020 10:14 AM  
**To:** 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>  
**Subject:** TP VEHICLE SHC 5836L (DOA: 07/03/2020)

Dear Wai Yin,

WITHOUT PREJUDICE

Based on our surveyor's estimate marking, the calculation of repair cost will be at Lump Sum \$7,550.00 before GST and 6 repair days.

Kindly check.

Best Regards,  
**Shiau Chan (Ms)** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)



[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	878K
<b>Vehicle Details</b>	
Vehicle No.:	SHC5836L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	09 Mar 2020
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002291
Chassis No.:	VF1ABL15AUC280921
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	11 Dec 2014
First Registration Date:	11 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Dec 2022
PARF Rebate Amount:	\$8,748.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	10 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$17,778.00
<b>Total Rebate Amount:</b>	<b>\$26,526.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 09 Mar 2020

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/03/2020 09:15
Date Of Accident	07/03/2020 14:40
Exact Location Of Accident	BIRCH ROAD TOWARDS RACE COURSE ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5836L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	2XXXXX878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

### Driver

Name of Driver	DULAKBAR BIN JOHARI
NRIC No	SXXXX203D
Date Of Birth	01/03/1957
Occupation	OUTDOOR
Date Of Driving Pass	28/03/1985
Driving Experience	34 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85144023
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 611 HOUGANG AVENUE 8 #06-504
Postcode	530611
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON 07/03/2020 AT ABOUT 1440HRS, I WAS TRAVELLING STRAIGHT ALONG THE SECOND LANE OF BIRCH ROAD TOWARDS RACE COURSE ROAD. SUDDENLY I FELT AN IMPACT ON THE LEFT SIDE OF MY TAXI, VEHICLE B(GBE1132X) CAME OUT FROM MINOR ROAD AND COLLIDED ONTO THE LEFT SIDE PORTION OF MY TAXI.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE1132X
Vehicle Make/Model/Colour	LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**DETAILS OF INJURED PERSON 1**

Name DULAKBAR BIN JOHARI

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHC5836L

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

## Sketch Plan #2 Pg. 1

### SKETCH PLAN

Bird Road towards Race Course End

A: SHC-5836L

B: G85 1132 X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to G3A Report.

## DECLARATION

I/We declare the foregoing particulars are true in every respect:

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5836L****AAD2003-047***Not Authorised  
L1 Snp & 75501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

10 MAR 2020

**SHC 5836L**

VF1ABL15AUC280921

RENAULT

LATITUDE

7.3.2020

**ERGO**

11/12/2014

**PART****LIST**

1	DOOR PANEL FRT LH	\$	2,844.66	✓
1	DOOR REGULATOR FRT LH	\$	758.10	
1	DOOR REGULATOR MOTOR FRT LH	\$	501.40	
1	DOOR REGULATOR GUIDE FRT LH	\$	69.00	
1	DOOR WHEATHESTRIIP FRONT LH	\$	316.00	
1	DOOR SEAL FRONT LH	\$	69.60	
1	DOOR SEAL LOWER FRONT LH	\$	93.90	
1	DOOR GLASS RUNNER SEAL FRONT LH	\$	332.00	
1	DOOR MOULDING FRONT LH	\$	100.50	
1	DOOR FINISHER FRONT LH	\$	258.90	
1	DOOR HANDLE OUTER FRONT LH	\$	169.50	
1	DOOR HANDLE CAP FRONT LH	\$	17.30	
1	DOOR HANDLE MODULE FRT LH L70Y	\$	133.40	
1	DOOR LOCK FRT LH	\$	453.80	
1	DOOR MIRROR ASSY LH	\$	727.90	
1	ROCKER PANEL INNER GARNISH LH	\$	466.51	
1	ROCKER PANEL INNER LH	\$	1,024.79	
1	ROCKER PANEL OUTER LH	\$	1,184.99	
1	DOOR HARNESS WIRE LH	\$	2,670.00	
1	DOOR FINISHER CLIP KIT LH	\$	94.00	
1	DOOR PANEL REAR LH	\$	758.70	✓
1	DOOR GUIDE REAR LH	\$	136.40	X
1	DOOR HINGE UPPER REAR LH L70Y	\$	180.70	X
1	DOOR HINGE LOWER REAR LH L70Y	\$	169.90	X
1	DOOR CHECK REAR LH	\$	114.90	X
1	DOOR REGULATOR REAR LH L70Y	\$	657.10	✓
1	DOOR REGULATOR MOTOR REAR LH L70Y	\$	450.60	✓
1	DOOR HANDLE OUTER REAR LH L70Y	\$	42.10	✓

**Trans-cab Auto Services Pte Ltd****AAD2003-047**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5836L**

1 DOOR HANDLE CAP REAR LH L70Y	\$	Sm	57.90	X
1 DOOR HANDLE SEAL REAR LH	\$	Sm	1.60	✓
1 DOOR HANDLE COVER REAR LH	\$	Sm	6.10	X
1 DOOR HANDLE MODULE REAR LH L70Y	\$	Sm	133.40	X
1 DOOR SEAL REAR LH	\$	Sm	119.40	✓
1 DOOR WHEATHERSTRIP REAR LH	\$	Gr	240.50	50% Sm 120.25
1 DOOR GLASS RUNNER SEAL REAR LH	\$	Sm	116.10	X
1 DOOR LOCK REAR LH	\$	Tm	468.20	✓
1 DOOR CATCH REAR LH	\$	✓	131.23	} X
1 DOOR FINISHER REAR LH	\$	Sm	230.30	
1 DOOR MOULDING BLACK REAR LH	\$	Sm	100.50	
1 DOOR FINISHER INNER REAR LH	\$	Sm	183.70	
1 DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	Sm	31.90	
1 DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	Sm	62.80	
1 DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	Sm	13.90	
1 DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	Sm	148.80	
1 DOOR WAIST SEAL INNER REAR LH	\$	Sm	55.80	} X
1 DOOR WAIST SEAL OUTER REAR LH	\$	Sm	169.60	
1 FENDER PANEL REAR LH	\$	By	1,933.20	
1 FENDER PANEL INNER TRIM REAR LH	\$	Sm	671.45	
1 WHEELARCH REAR LH	\$	Sm	181.60	
1 AIR VENT	\$	Sm	59.40	
1 TAILLAMP LH	\$	Sm	401.40	
1 TAILLAMP PANEL LH	\$	✓	401.40	
1 REAR BUMPER	\$	Sm	561.70	} X
1 BUMPER BRACKET SIDE LH REAR	\$	Sm	80.80	
1 BUMPER RETAINER LH RR	\$	Sm	54.20	
1 KNUCKLE ARM REAR LH	\$	Sm	472.10	
1 AXLE SPRING ARM LH	\$	Sm	220.60	
1 LOWER ARM REAR LH	\$	Sm	543.50	
1 ABSORBER REAR	\$	Sm	217.30	
1 KNUCKLE HUB+ BEARING LH/RH	\$	Sm	272.30	

<b>TOTAL</b>	<b>\$</b>	<b>23,139.32</b>
<b>10%</b>	<b>\$</b>	<b>2,313.93</b>
	<b>\$</b>	<b>20,825.39</b>



**Trans-cab Auto Services Pte Ltd**

AAD2003-047

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5836L

**Special Nett**

1 REAR FENDER STICKER "Trans-Cab"	\$	na	100.00	X
1 FRONT DOOR STICKER 'Trans-Cab'	\$	na	80.00	60na
1 FRONT DOOR STICKER 'Classic'	\$	na	80.00	15na
1 REAR DOOR STICKER '6555-3333'	\$	na	100.00	60na
1 LH SIDE RENAULT TYRE 215/60/16	\$	sn	330.00	X
1 LH SIDE RENAULT TYRE RIM	\$	na	380.00	✓
1 REAR WINDSCREEN MOULDING	\$	na	160.00	X
2 WINDSCREEN SEALANT	\$	na	120.00	40na
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	30na
1 DOOR CHECK BOLT	\$	sn	10.20	} X
1 DOOR CHECK NUT	\$	sn	10.20	
1 DOOR GUIDE SCREW	\$	sn	10.85	
1 DOOR HINGE BOLT	\$	sn	12.60	
1 DOOR HINGE NUT	\$	sn	7.20	
1 DOOR MOULDING CLIP	\$	na	5.90	
1 DOOR SEAL CLIP	\$	na	4.90	
1 FENDER INNER TRIM CLIP LH	\$	na	28.00	
1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
1 TAILLAMP CLIP LH	\$	na	5.00	
1SET REAR BUMPER CLIP	\$	na	66.00	
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	
1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	
<b>TOTAL</b>	<b>\$</b>		<b>1,675.85</b>	
<b>TOTAL PARTS</b>	<b>\$</b>		<b>22,501.25</b>	

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 7,500.00 900

To check steering geometry and computer wheel alignment

\$ 220.00 60

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 100

**Trans-cab Auto Services Pte Ltd****AAD2003-047**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5836L**

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	<i>X</i>
To transfer of Front door fittings, attachment and perform water seepage test.	\$	170.00	<i>601</i>
Putty and spray painting of the affected portion.	\$	7,500.00	<i>8801</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00	<i>201</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To rust-proofing of the affected areas.	\$	170.00	<i>901</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	170.00	<i>601</i>
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	<i>1201</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	<i>nn</i> 380.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	<i>nn</i> 170.00	<i>X</i>

To check ABS brake efficiency, final checking and testing. \$ *nn* 380.00 *X*

**TOTAL \$ 18,270.00****Over All Total \$ 40,771.25****LUMP SUM (REPAIR DAY)****25 DAYS***6 days*

LKK Auto Consultants Pte Ltd notify the Repairer of the following:

- To remedy inherent safety defect
- To rectify Corrosion and rust during recovery
- Parts prices are subject to confirmation
- Third party services are not a Licensed Provider
- No illegal practices are allowed
- Environmental protection must be observed and is subject to Environmental Protection Company

Acknowledged by Repairer:  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EGI20003809/KQF3N2  
**Date:** 19/03/2020

### REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:  
**Claimant Vehicle No :** SHC5836L **Insured Vehicle No :** GBE1132X  
Date of Loss: 07/03/2020 Nature of Claim: TP Claim No: CDMCG20000427

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5836L**  
Make & Model: RENAULT LATITUDE, 2.0 D dCi (A) Engine No: M9R8839C002291  
Reg. Date: 11/12/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC280921  
Colour: Metallic White/Red Odometer: 688870 km  
Engine Capacity: 1995 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
Front Left Side: Giti 9 mm Rear Left Side: Giti 7 mm  
Front Right Side: Giti 9 mm Rear Right Side: Giti 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,501.25	7,145.79	15,355.46	68.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,270.00	2,310.00	15,960.00	87.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>40,771.25</b>	<b>9,455.79</b>	<b>31,315.46</b>	<b>76.81</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,550.00</b>		
<b>(S\$)</b>	40,771.25	7,550.00	33,221.25	81.48
<b>+ GST 7.00/7.00% (S\$)</b>	2,853.99	528.50	2,325.49	81.48
<b>Nett Amount (S\$)</b>	<b>43,625.24</b>	<b>8,078.50</b>	<b>35,546.74</b>	<b>81.48</b>

### INSPECTION

Date of Assignment: 10/03/2020  
Date Inspected: 10/03/2020 Inspected At: Trans-Cab Services Pte Ltd (HQ)  
2 Ang Mo Kio Street 63  
Singapore 569111  
Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 19 Mar 2020)
<b>Parts:</b>	143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC5836L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL FRT LH	Bent	2,844.66 FL	*2,844.66 FL
2	1		*DOOR REGULATOR FRT LH	Serviceable	758.10 FL	*- FL
3	1		*DOOR REGULATOR MOTOR FRT LH	Serviceable	501.40 FL	*- FL
4	1		*DOOR REGULATOR GUIDE FRT LH	Serviceable	69.00 FL	*- FL
5	1		*DOOR WEATHERSTRIP FRONT LH	Serviceable	316.00 FL	*- FL
6	1		*DOOR SEAL FRONT LH	Serviceable	69.60 FL	*- FL
7	1		*DOOR SEAL LOWER FRONT LH	Serviceable	93.90 FL	*- FL
8	1		*DOOR GLASS RUNNER SEAL FRONT LH	Serviceable	332.00 FL	*- FL
9	1		*DOOR MOULDING FRONT LH	Serviceable	100.50 FL	*- FL
10	1		*DOOR FINISHER FRONT LH	Serviceable	258.90 FL	*- FL
11	1		*DOOR HANDLE OUTER FRONT LH	Repair	169.50 FL	*- FL
12	1		*DOOR HANDLE CAP FRONT LH	Repair	17.30 FL	*- FL
13	1		*DOOR HANDLE MODULE FRT LH L70Y	Serviceable	133.40 FL	*- FL
14	1		*DOOR LOCK FRT LH	Repair	453.80 FL	*- FL
15	1		*DOOR MIRROR ASSY LH	Serviceable	727.90 FL	*- FL
16	1		*ROCKER PANEL INNER GARNISH LH	Serviceable	466.51 FL	*- FL
17	1		*ROCKER PANEL INNER LH	Repair	1,024.79 FL	*- FL
18	1		*ROCKER PANEL OUTER LH	Repair	1,184.99 FL	*- FL
19	1		*DOOR HARNESS WIRE LH	Serviceable	2,670.00 FL	*- FL
20	1		*DOOR FINISHER CLIP KIT LH	Not Necessary	94.00 FL	*- FL
21	1		*DOOR PANEL REAR LH	Bent	758.70 FL	*758.70 FL
22	1		*DOOR GUIDE REAR LH	Serviceable	136.40 FL	*- FL
23	1		*DOOR HINGE UPPER REAR LH L70Y	Repair	180.70 FL	*- FL
24	1		*DOOR HINGE LOWER REAR LH L70Y	Repair	169.90 FL	*- FL
25	1		*DOOR CHECK REAR LH	Serviceable	114.90 FL	*- FL
26	1		*DOOR REGULATOR REAR LH L70Y	Bent	657.10 FL	*657.10 FL
27	1		*DOOR REGULATOR MOTOR REAR LH L70Y	Jammed	450.60 FL	*450.60 FL
28	1		*DOOR HANDLE OUTER REAR LH L70Y	Cracked	42.10 FL	*42.10 FL
29	1		*DOOR HANDLE CAP REAR LH L70Y	Serviceable	57.90 FL	*- FL
30	1		*DOOR HANDLE SEAL REAR LH	Necessary	1.60 FL	*1.60 FL
31	1		*DOOR HANDLE COVER REAR LH	Serviceable	6.10 FL	*- FL
32	1		*DOOR HANDLE MODULE REAR LH L70Y	Serviceable	133.40 FL	*- FL
33	1		*DOOR SEAL REAR LH	Serviceable	119.40 FL	*- FL
34	1		*DOOR GLASS RUNNER SEAL REAR LH	Serviceable	116.10 FL	*- FL
35	1		*DOOR LOCK REAR LH	Jammed	468.20 FL	*468.20 FL
36	1		*DOOR CATCH REAR LH	Repair	131.23 FL	*- FL
37	1		*DOOR FINISHER REAR LH	Serviceable	230.30 FL	*- FL
38	1		*DOOR MOULDING BLACK REAR LH	Serviceable	100.50 FL	*- FL
39	1		*DOOR FINISHER INNER REAR LH	Serviceable	183.70 FL	*- FL
40	1		*DOOR FINISHER BRACKET INNER REAR LH L70Y	Serviceable	31.90 FL	*- FL
41	1		*DOOR FINISHER BRACKET INNER REAR LH L70Y	Serviceable	62.80 FL	*- FL
42	1		*DOOR FINISHER BRACKET INNER REAR LH L70Y	Serviceable	13.90 FL	*- FL
43	1		*DOOR FINISHER BRACKET INNER REAR LH L70Y	Serviceable	148.80 FL	*- FL
44	1		*DOOR WAIST SEAL INNER REAR LH	Serviceable	55.80 FL	*- FL
45	1		*DOOR WAIST SEAL OUTER REAR LH	Serviceable	169.60 FL	*- FL
46	1		*FENDER PANEL REAR LH	Bent	1,933.20 FL	*1,933.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*FENDER PANEL INNER TRIM REAR ;H	Serviceable	671.45 FL	*- FL
48	1		*WHEELARCH REAR LH	Serviceable	181.60 FL	*- FL
49	1		*AIR VENT	Serviceable	59.40 FL	*- FL
50	1		*TAILLAMP LH	Serviceable	401.40 FL	*- FL
51	1		*TAILLAMP PANEL LH	Repair	401.40 FL	*- FL
52	1		*REAR BUMPER	Serviceable	561.70 FL	*- FL
53	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
54	1		*BUMPER RETAINER LH RR	Serviceable	54.20 FL	*- FL
55	1		*KNUCKLE ARM REAR LH	Serviceable	472.10 FL	*- FL
56	1		*AXLE SPRING ARM LH	Serviceable	220.60 FL	*- FL
57	1		*LOWER ARM REAR LH	Serviceable	543.50 FL	*- FL
58	1		*ABSORBER REAR	Serviceable	217.30 FL	*- FL
59	1		*KNUCKLE HUB + BEARING LH/RH	Serviceable	272.30 FL	*- FL
60	1		*REAR FENDER STICKER TRANS-CAB	Not Necessary	100.00 FS	*- FS
61	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
62	1		*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS
63	1		*REAR DOOR STICKER 6555-3333	Necessary	100.00 FS	*60.00 FS
64	1		*LH SIDE RENAULT TYRE 215/60/16	Serviceable	330.00 FS	*- FS
65	1		*LH SIDE RENAULT TYRE RIM	Dented	380.00 FS	*380.00 FS
66	1		*REAR WINDSCREEN MOULDING	Not Necessary	160.00 FS	*- FS
67	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
68	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	100.00 FS	*30.00 FS
69	1		*DOOR CHECK BOLT	Serviceable	10.20 FS	*- FS
70	1		*DOOR CHECK NUT	Serviceable	10.20 FS	*- FS
71	1		*DOOR GUIDE SCREW	Serviceable	10.85 FS	*- FS
72	1		*DOOR HINGE BOLT	Serviceable	12.60 FS	*- FS
73	1		*DOOR HINGE NUT	Serviceable	7.20 FS	*- FS
74	1		*DOOR MOULDING CLIP	Not Necessary	5.90 FS	*- FS
75	1		*DOOR SEAL CLIP	Not Necessary	4.90 FS	*- FS
76	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
77	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
78	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
79	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*- FS
80	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
81	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
82	1		*DOOR WEATHERSTRIP REAR LH (50%)	Cut	216.45 FS	*120.25 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>24,791.13</b>	<b>7,861.41</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>2,289.88</b>	<b>715.62</b>
<b>Total Parts (\$\$)</b>	<b>22,501.25</b>	<b>7,145.79</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	7,500.00	900.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	100.00
4	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
5	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	880.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	20.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	90.00
10	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
11	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
12	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	120.00
13	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
14	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING	New	380.00	0.00
15	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
16	TO CHECK ABS BRAKE EFFICIENCY,FINAL CHECKING AND TESTING	New	380.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>18,270.00</b>	<b>2,310.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >