

SW WERKZ PTE LTD

BLOCK 25 KAKI BUKIT ROAD 4 #03-65/67/68 SYNERGY @ KB Singapore 417800
HP: 92712214 TEL: (65) 63844844 FAX: (65) 63834944

POH WEI HAN
25 KAKI BUKIT ROAD4
03-65 SYNERGY @KB
Singapore 417800

01st MARCH 2020

TPQBE
Vic

Accident date: 21st FEBRUARY 2020

Estimated repair cost for vehicle no: SKH9110J KIA CERATO FORTE 1.6SX '10

S/n	Qty	Items	U/price	Amount
1	1	Front bonnet <i>Denied.</i>		\$752.00 ✓
2	2	Front bonnet hinges <i>HEM</i>	\$0.00	\$0.00 X
3	1	Front bonnet lock <i>HEM</i>		\$112.00 X
4	1	front grille <i>at</i>		\$207.00 ✓
5	1	front grille emble logo <i>HEM</i>		\$35.00 ✓
6	8	Front grille clips <i>HEM</i>	\$6.50	\$52.00 20
7	2	front support panel <i>HEM</i>	\$495.00	\$990.00 X
8	1	Front headlamp <i>1 cracked.</i>		\$454.80 ✓
9	1	Front headlamp lower bracket <i>HEM</i>		\$38.10 X
10	1	Front bumper <i>Repair</i>		\$575.00 X
11	2	Front Bumper Side Bracket <i>2</i>	\$58.20	\$116.40 X
12	10	Front bumper clips	\$6.50	\$65.00 X
13	2	Front bumper fog lamp <i>HEM</i>	\$165.20	\$330.40 X
14	2	Front bumper fog lamp cover <i>HEM</i>	\$86.20	\$172.40 X
15	1	Front bumper lower grille		\$205.00 X
16	1	Front bumper reinforcement		\$373.00 X
17	1	Front bumper inner sponge		\$125.30 X

Subtotal :- \$4,603.40

Labour charges

To Remove & refix front windscreen

\$120.00 X

Gum

\$50.00 X

Tuff kote

\$120.00 X

To Check Wiring System

\$60.00 30

Panel beating

\$600.00 400

Spray painting

\$600.00 400

Subtotal :- \$1,550.00

Total :- \$6,153.40

total: 2151.92
w/s: 17K

03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: