

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE

速良摩哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6 Blk D 01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒杆噴漆
代理保險：車禍
賠償及買賣汽車

MR HO PHIAK JOO

DATE: 09/03/2020

DOA : 03/03/2020

ESTIMATE REPAIR FOR VEHICLE NO. SMJ 2091 S (MERCEDES C180)

	Description		Nett Price	
1 pc	Rear bootlid logo	Net	\$ 65.00	✓
1 pc	C180 emblem 98.00	Net	\$ 102.00	✓
1 pc	Rear bumper 1790	Net	\$ 2,140.00	✓
2 pcs	Rear bumper side retainer @SS\$75.00	Net	\$ 150.00	X
1 pc	Rear bumper reinforcement 684.00	Net	\$ 820.00	✓
1 pc	Rear bumper lower garnish 70.00	Net	\$ 270.00	✓
1 pc	Bumper chrome centre 292.00	Net	\$ 310.00	✓
4 pcs	Bumper centre reverse sensor @SS\$216.00	Shuck	\$ 864.00	2 pcs
1 pc	Bumper centre sensor seal	Net	\$ 25.00	✓
1 pc	Taillamp	Net	\$ 908.00	X
1 pc	Headlamp (rh)	Welding	\$ 2,980.00	✓
1 pc	Front bumper 1600.00	Net	\$ 1,880.00	✓
1 pc	Radiator grille	Net	\$ 165.00	✓
1 pc	Radiator carrier	Net	\$ 190.00	X
1 pc	Logo	Net	\$ 160.00	✓
1 pc	Logo inner base	Net	\$ 95.00	✓
4 pcs	Radiator centre moulding @SS\$102.00	Net	\$ 408.00	X
1 pc	No. plate garnish 135.00	Net	\$ 160.00	✓
			\$ 11,692.00	
			\$ (1,169.20)	
			\$ 10,522.80	

Less : 10%

Special Nett Items

1 set	No. plate & housing for	Net	\$ 60.00	40
	To remove & fix reverse sensor		\$ 80.00	50
	To spray anti-rust		\$ 100.00	X
	Labour charges for knocking & replacing parts.		\$ 1,300.00	700
	Spraypainting		\$ 1,200.00	900

TOTAL :

\$ 13,262.80

not Allowed
nlu

10/3/20
4/3 #7650

Whepne After rep.
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-8791-02
102
7911-91
9601-91
7681