

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

09 MAR 2020

ESTIMATE

Estimate No. : b1 54715
Date Estimated : 09/03/2020
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Wong Her Shann (Wang HeXian)
1 Jalan Mengkudu
Sembawang Hills Estate
Singapore 577389

- ACCOUNT - 158
Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS566S	WBA2J520407E04071	05/07/2019	M240i COUPE	0

DESCRIPTION

To replace front bumper, air duct, bumper support, bonnet and attachments.

1700 4,250.00

Painting front bumper and bonnet.

2102 2,336.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To supply front emboss number plate. BT

83.00

To carry out body cavity preservation.
(Per panel).

100 118.00

Sundries.

80 ✓ ? 150.00

Xpel film coating for bumper and bonnet.

1,700.00

Total Labour 1: 8,991.00

DESCRIPTION

BONNET / DO ? X NN
FRT BUMPER TOP MOUNT ? X NN
FRT SHOCK ABSORBER (M) ? ✓ BR
FRT BUMPER PANEL PRIMED (M/PDC) / DO
LICENCE PLATE BASE (M) / MT
FRT LH GRILLE (CERUM GREY) / MT
Grille, fron (RM) - MT
AIR DUCT RADIATOR ? ✓ BR
PLAQUE 82MM / MC

QTY	PRIC	VALUE
1	1,178.70	1,178.70
1	380.00	380.00
1	46.95	46.95
1	1,118.50	1,118.50
1	83.50	83.50
1	281.50	281.50
1	281.50	281.50
1	92.95	92.95
1	71.60	71.60

105.35

Total Parts : 3,535.20

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X
E S T I M A T E

Estimate No. : b1 54715
Date Estimated : 09/03/2020
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS566S	WBA2J520407E04071	05/07/2019	M240i COUPE	0

Steer (CLKK) W/L P/L
16/3/20, 11.30am
P/P
By B/L sy
S dys

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	8,991.00
Parts	:	3,535.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	876.83
Grand Total	:	13,403.03

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



To: Inthiran Thurasamy / mobile 81214600 / inthiran.thurasamy@simedarby.com.sg
DR JOANNE / mobile : 8388 1133 / lcjoanne@gmail.com / DR HERSHANN WONG

Date 06 March 2020


BMW M240i - SL5566S - XPEL FRONT REDO JOB QUOTE

We refer to your enquiry & pleased to draft for the job -
DR JOANNE / DR HERSHANN WONG's BMW M240i
DRAFT FOR BMW M240I - XPEL ULTIMATE PLUS PPF JOB



HIGHLIGHT PART TO DO - HOOD \$900.00

...XPEL + Your Car = Protection You Can Trust



BUMPER KIT - \$800.00

TOTAL PRICE FOR JOB ABOVE : \$1,700.00 / before gst
USING XPEL ULTIMATE PLUS PPF

Previously done on - July 2019



XPEL PROTECTION FILM CARE

To keep your film looking great, follow a few simple guidelines:

- Wait 48 Hours after installation to wash your car
- Use only soft cloth or microfiber towels on the film
- Do NOT use abrasive Cleaners on the film
- Do NOT use dyed or colored car wax on the film

For additional care instructions, see www.xpel.com/care
