

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SAMSUNG C & T CORPORATION
 3 CHURCH STREET #11-01 SAMSUNG HUB
 SINGAPORE 049483

Contact : 81265994

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

ESTIMATE

Repair Code : CLM16116
 Date in : 06/03/2020
 Vehicle Num. : SLD1454D
 Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT
 Chassis/Eng# : MR053REH104551086/1ZRY292285

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Repair</i>	1	781.10	+ 781.10
REAR BOOTLID 'ALTIS' EMBLEM	1	54.10	✓ 54.10
REAR BOOTLID 'COROLLA' EMBLEM	1	50.20	✓ 50.20
REAR BOOTLID 'LOGO' EMBLEM	1	58.50	✓ 58.50
REAR BOOTLID MECHANISM LOCK <i>Dye</i>	1	379.20	✓ 379.20
REAR BOOTLID WEATHER STRIP <i>cut</i>	1	271.45	✓ 271.45
REAR BUMPER <i>behind</i>	1	581.90	✓ 581.90
REAR BUMPER REFLECTOR L/R <i>LH cracked</i>	2	141.45	282.90 141.45
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	398.70	✓ 398.70
REAR BUMPER REINFORCEMENT BRACKET L/R <i>LH Bent</i>	2	165.00	330.00 165
REAR BUMPER REVERSE SENSOR COVER L/R <i>new</i>	2	121.10	+ 242.20
REAR BUMPER REVERSE SENSOR L/R <i>Dye</i>	2	189.50	✓ 379.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	65.00	✓ 130.00
REAR END PANEL <i>Dented</i>	1	781.90	✓ 781.90
REAR END PANEL INNER TOP GARNISH <i>behind</i>	1	185.99	✓ 185.99
REAR LH BUMPER END SEAL COVER <i>new</i>	1	231.35	+ 231.35
REAR LH FENDER INNER TRIM <i>new</i>	1	338.00	+ 338.00
REAR LH TAILLAMP <i>cracked</i>	1	391.90	✓ 391.90

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SAMSUNG C & T CORPORATION
 3 CHURCH STREET #11-01 SAMSUNG HUB
 SINGAPORE 049483

Contact : 81265994

ESTIMATE

Repair Code : CLM16116
 Date in : 06/03/2020
 Vehicle Num. : SLD1454D
 Model : TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT
 Chassis/Eng# : MR053REH104551086/1ZRY292285

REAR TAILLAMP LOWER BRACKET L/R	<i>LH included</i>	2	88.70	<i>88.70</i>	177.40
Subtotal before discount					6,045.79
Percentage discount	25%	<i>4057.99</i>			1,511.45
Sub-total 1					4,534.34
REAR BUMPER CLIPS - SET	<i>NA</i>	1	80.00	<i>30</i>	80.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>NA</i>	1	40.00	<i>10</i>	40.00
REAR LH FENDER INNER TRIM CLIPS - SET	<i>NA</i>	1	50.00	<i>+</i>	50.00
REAR LH TAILLAMP CLIPS - SET	<i>NA</i>	1	25.00	<i>✓</i>	25.00
Subtotal before discount					195.00
Percentage discount	0%				0.00
Sub-total 2					195.00
Parts-total					4,729.34

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To transfer rear bootlid mechanism lock outer handle reflector

<i>1590</i>	<i>70</i>	100.00
	<i>60</i>	140.00
	<i>800</i>	1,000.00
	<i>600</i>	1,000.00
	<i>60</i>	120.00
	<i>+</i>	80.00
Labour Total		2,440.00
Parts & Labour Total		7,169.34

total: 4688.49.

H/S: 3.7K.

*Adrian Lij
 10/03/20
 06 Dyn.*