

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 32075

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0251/2020/NS
Date : 9-Mar-20

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Goh Chin Seng Eugene
Address : Blk 153 Bishan St 13
#05-52
Singapore 570153
Telephone : HP +65 96696521
Type of Claim : Own Damage Claims
Policy No. : 1800019376-01
Vehicle No : **SDB 1330 H**
Model Code : Audi A4 Sedan 2.0 TFSI 8W
Model / Year : Mar-18
Engine No : CVK 053242
Chassis No : WAUZZZF43JA094802
Mileage : 49701
Date In : 9-Mar-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Mar-20
Place of Accident : Along PIE Before Exit 18A

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDB 1330 H

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 /	
2	To remove and renew aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00 ?	
3	To dismantle and renew front bumper, rhs front fender, bonnet and rhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 5,250.00 <i>500 x 3.5</i>	1750
4	To respray front bumper, rhs front fender, bonnet and hinges. <i>* 200 add Frd LH dnr - 1</i>	\$ 3,500.00 <i>550 x 4</i>	2400
5	To carry out pre-repair diagnostic check and post-repair diagnostic check.	S/N \$ 384.00	192 /
TOTAL LABOUR CHARGES		: \$ 10,310.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDB 1330 H

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER / DR	\$	2,010.00
2	FRONT BUMPER FIXING PARTS / MC	\$	269.00
3	FRONT BUMPER SECURING STRIP / MC	\$	34.00
4	FRONT BUMPER GRILLE - CENTRE ?	\$	185.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE X	\$	198.00
6	FRONT BUMPER AIR GUIDE - RH ?	\$	59.00
7	RADIATOR GRILLE / DR	\$	1,714.00
8	FRONT BUMPER AIR GUIDE GRILLE - RH X	\$	344.00
9	FRONT BUMPER CARRIER ?	\$	757.00
10	FRONT BUMPER FOAM FILLER PIECE ?	\$	117.00
11	FRONT BUMPER COVER / DR	\$	120.00
12	FRONT BUMPER GUIDE SECTION - RH ?	\$	36.00
13	FRONT BUMPER BRACKET - RH ?	\$	214.00
14	CAUTION SIGN STICKER / MC	NEC \$	13.00
15	AIRCON STICKER / MC	NEC \$	7.00
16	LOCK CARRIER BRACKET ?	\$	129.00
17	FRONT BUMPER SUPPORT - LH / RH ?	2 \$	54.00
18	HORN - RH LOW TONE ?	\$	270.00
19	SPRING SHACKLE - RH ?	\$	27.00
20	FRONT FENDER - RH / DD	\$	722.00
SUB TOTAL SPARE PARTS CHARGES		:	\$ 7,279.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDB 1330 H

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	FRONT FENDER ATTACHMENT PARTS ?	\$	190.00
22	FRONT FENDER CLOSING ELEMENT - RH ?	\$	47.00
23	FRONT FENDER BRACKET - RH ?	\$	33.00
24	DEFORMATION ELEMENT BRACKET - RH ?	\$	46.00
25	FRONT FENDER BRACKET ?	\$	30.00
26	FRONT FENDER BRACE - RH FRONT ?	\$	112.00
27	WHEEL HOUSING LINER - RH X	\$	228.00
28	WHEEL HOUSING LINER ATTACHMENT PARTS X	\$	86.00
29	WHEEL SPOILER X	\$	69.00
30	WHEEL SPOILER TRIM - RH X	\$	34.00
31	STONE CHIP GUARD - RH X	\$	48.00
32	BONNET / 00	\$	2,634.00
33	BONNET ATTACHMENT PARTS / MK	\$	116.00
34	BONNET LID HINGE - LH / RH / BT	2 \$	574.00
35	BONNET IMPACT PROTECTION - CENTRE / MK	\$	26.00
36	BONNET IMPACT PROTECTION - LH / MK	\$	26.00
37	BONNET IMPACT PROTECTION - RH / MK	\$	26.00
38	FENDER LEDGE COVER - RH OUTER ?	\$	29.00
39	FENDER LEDGE COVER - RH FRONT ?	\$	21.00
40	BONNET GAS FILLED STRUT X	2 \$	224.00
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 4,599.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDB 1330 H

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
41	BONNET STRIKER - LH / (RH) / OT	21 \$	94.00
42	BONNET LID LOCK (RH) / OT	21 \$	403.00
43	BONNET BOWDEN CABLE - CENTRE ?	\$	54.00
44	BONNET RELEASE CABLE ?	\$	54.00
45	BONNET RELEASE LEVER ?	\$	13.00
46	BONNET LID LOCK CABLE ?	\$	69.00
47	BONNET SOUND ABSORBER X	\$	323.00
48	LED HEADLIGHT - RH / BR	\$	7,321.00
49	MAIN LIGHT ELECTRONICS POWER MODULE ?	\$	732.00
50	LIGHT CONTROL SYSTEM CONTROL UNIT ?	\$	707.00
51	HEADLIGHT HOSE - RH ?	\$	34.00
52	LIFT CYLINDER - RH ?	\$	198.00
53	HEADLIGHT CORRUGATED PIPE ?	\$	88.00
54	LOCK CARRIER ?	\$	956.00
55	COOLANT REGULATOR SUPPORT ?	2 \$	71.00
56	AIRCON CONDENSER ?	\$	586.00
57	RADIATOR ?	\$	766.00
58	READY MIX COOLANT ?	\$	86.00
59	RADIATOR AIR GUIDE - RH ?	\$	27.00
60	RADIATOR INNER DUCT - RH ?	\$	12.00
SUB TOTAL SPARE PARTS CHARGES		:	\$ 12,594.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Steve CLKK)

Surveyed Date

:

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

10/3/20, 4.00 pm
OD - N/A AL (Rev 1)
Excess - ?
P/P
Ry RL SJ
6 days

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1181

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/00/0251/2020/NS

Date

10-Mar-20

Service Advisor

Clary Tan

Pages

1 of 1

Regn No

SDB 1330 H

Model No

Audi A4 Sedan 2.0 TFSI 8W

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$ 350.00	/

TOTAL

\$ 350.00

Steve
10/3/20

For Premium Automobiles Pte Ltd

Authorised Signature