



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGJ898R

CHINA TAIPING INSURANCE (S) PTE LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 42007
Reg No/Reg Date SGJ898R / 24/04/2017
Date In/Mileage 11/03/2020/ 35435
Chassis No WDC2539462F206638
Engine No 27492030943079
Make/Model MB/MB GLC 250 4MATIC SUV (X253)
Colour/Trim 029 996 Hyacinth Re/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	
WC000668	Credit	04/06/2020/ 19:50	CH	371 / Go Chee Han	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request
M BPNSUN

POLICY NO/ACC DATE : DMPCSN3020901900 // 8-3-2020
DRIVE IN/EXCESS : 9-3-2020 // \$950
DATE IN/DATE SURVEY: 11-3-2020 1300 // Taufikh - LKK
BY/AUTHORIZED ON : 11-3-2020 1731 // Veron Chen - LKK

A BPILAB					1920.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.					
A BPIRES					1800.00
RESPRAY FRONT BUMPER & LH/FRONT FENDER & HOOD					
A BPILAB				0.10	380.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT					
A BPILAB					120.00
TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT					
A BPILAB					540.00
TO INSPECT & CONDUCT WHEEL ALIGNMENT. NETT					
S BPNSUB					60.00
LABOUR TO REMOVE AND INSTALL LPC TYRE FROM RIM, WHEEL BALANCE AND INSTALL NEW VALVE HEAD					
X BPNEXC					-950.00
INSURANCE EXCESS					
X LH/COVER BUMPER & FENDER AREA	1.00	224.96	00.00		224.96
X LEFT FRONT FENDER	1.00	895.61	00.00		895.61
X FRONT BUMPER	1.00	1343.58	00.00		1343.58
X LH/BASIC MOUNTING FOR BUMPER	1.00	69.46	00.00		69.46
X LH/FRONT DISK WHEEL	1.00	779.44	00.00		779.44
X LEFT HEADLAMP UNIT	1.00	3414.32	00.00		3414.32

Confirmed & accepted by

Nett 10,597.37
7% GST on 10597.37 741.82

Authorized signatory and company stamp

Total Payable 11,339.19

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg