

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0253/2020/GW  
**Date** : 10-Mar-20

**Vehicle NOT IN workshop. Please arrange for survey**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr. Goh Miah Wee  
**Address** : 135 Serangoon Ave 3  
#08-09  
Singapore 556114  
**Telephone** : HP +65 88286662  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 1800079209  
**Vehicle No** : **SMA 8682 U**  
**Model Code** : Audi A3 Sedan 1.0 TFSI  
**Model / Year** : Jun-18  
**Engine No** : CHZ 940565  
**Chassis No** : WAUZZZ8V1J1066907  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 05-Mar-20  
**Place of Accident** : HDB Car Park Near BLK 90 HDB Pipit

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SMA 8682 U

S/N	Nature of Jobs	Estimated Charges
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00 500
3	To respray front bumper and lhs front fende and bonnet.	\$ 2,800.00 550
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 4,752.00</b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMA 8682 U

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER / BR	\$ 1,894.00	
2	FRONT BUMPER FIXING PARTS ?	\$ 176.00	
3	FRONT BUMPER GUIDE SECTION-LH / BR	\$ 36.00	
4	FRONT BUMPER GRILLE-CENTER X	\$ 151.00	
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE ?	\$ 505.00	
6	FRONT BUMPER CLOSING ELEMENT-LH ?	\$ 280.00	
7	FRONT BUMPER COVER TRIM-LH ?	\$ 153.00	
8	FRONT BUMPER ADAPTER WHEEL HOUSING LINER-LH / MC	\$ 36.00	
9	RADIATOR GRILLE / BR	\$ 1,338.00	
10	FRONT BUMPER CLOSING ELEMENT ?	\$ 180.00	
11	FRONT AIR GUIDE GRILLE-LH ?	\$ 177.00	
12	FRONT BUMPER REINFORCEMENT BAR X	\$ 691.00	
13	FRONT FOAM FILLIER PIECE X	\$ 178.00	
14	FRONT BUMPER COVER TRIM-LH ?	\$ 115.00	
15	FRONT SIGNAL HORN-LH X	\$ 188.00	
16	LED HEADLIGHT -LH ?	\$ 5,193.00	
17	LED HEADLIGHT LIFT CYLINDER-LH ?	\$ 134.00	
18	HOSE FOR HEADLIGHT WASHER SYSTEM X	\$ 64.00	
19	WASH WATER RESERVOIR X	\$ 190.00	
20	RADIATOR AIR GUIDE -LH ?	\$ 23.00	

### **SUB-TOTAL SPARE PARTS CHARGES**

**: \$ 11,702.00**

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMA 8682 U

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	RADIATOR AIR GUIDE-UPPER CENTER X	\$ 12.00	
22	FRONT WHEEL HOUSING LINER-LH / TN	\$ 159.00	
23	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS / M	\$ 84.00	
24	FRONT CAR PLATE NO. X	S/N \$ 60.00	
25	SUNDRIES 7	\$ 300.00	

**TOTAL SPARE PARTS CHARGES : \$ 12,317.00**

**TOTAL LABOUR CHARGES : \$ 4,752.00**

**GRAND TOTAL : \$ 17,069.00**

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** : Steve (LKK)  
**Surveyed Date** : 10/3/20, 11.15 am  
**Authorised Date** : 00- Not Authorised (Rental)  
**Excess Cost** : Excess - ?  
**Liability** : P/P  
**Remarks** : My Bel my

**Please Note** : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant