

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0253/2020/GW
Date	:	10-Mar-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Goh Miah Wee
Address	:	135 Serangoon Ave 3 #08-09 Singapore 556114
Telephone	:	HP +65 88286662
Type of Claim	:	Own Damage Claims
Policy No.	:	1800079209
Vehicle No	:	SMA 8682 U
Model Code	:	Audi A3 Sedan 1.0 TFSI
Model / Year	:	Jun-18
Engine No	:	CHZ 940565
Chassis No	:	WAUZZZ8V1J1066907
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	05-Mar-20
Place of Accident	:	HDB Car Park Near BLK 90 HDB Pipit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMA 8682 U

S/N Nature of Jobs	Estimated Charges
1 To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 360.00 ✓
2 To dismantle and renew front bumper and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00 500 ✓
3 To respray front bumper and lhs front fende and bonnet.	\$ 2,800.00 550 ✓
4 To carry out diagnostic checks.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES	: \$ 4,752.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 8682 U

Store 16/3/22

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>BR</i>	\$ 1,894.00	1515.20
2	FRONT BUMPER FIXING PARTS ?	\$ 176.00	X NN
3	FRONT BUMPER GUIDE SECTION-LH <i>BR</i>	\$ 36.00	28.64
4	FRONT BUMPER GRILLE-CENTER X	\$ 151.00	X NN
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE ? <i>BR</i>	\$ 505.00	404
6	FRONT BUMPER CLOSING ELEMENT-LH ?	\$ 280.00	X NN
7	FRONT BUMPER COVER TRIM-LH ?	\$ 153.00	X NN
8	FRONT BUMPER ADAPTER WHEEL HOUSING LINER-LH <i>Mc</i>	\$ 36.00	28.16
9	RADIATOR GRILLE <i>BR</i>	\$ 1,338.00	1070.40
10	FRONT BUMPER CLOSING ELEMENT ?	\$ 180.00	X NN
11	FRONT AIR GUIDE GRILLE-LH ?	\$ 177.00	X NN
12	FRONT BUMPER REINFORCEMENT BAR X	\$ 691.00	X NN
13	FRONT FOAM FILLER PIECE X	\$ 178.00	X NN
14	FRONT BUMPER COVER TRIM-LH ?	\$ 115.00	X NN
15	FRONT SIGNAL HORN-LH X	\$ 188.00	X NN
16	LED HEADLIGHT -LH ?	\$ 5,193.00	X NN
17	LED HEADLIGHT LIFT CYLINDER-LH ?	\$ 134.00	X NN
18	HOSE FOR HEADLIGHT WASHER SYSTEM X	\$ 64.00	X NN
19	WASH WATER RESERVOIR X	\$ 190.00	X NN
20	RADIATOR AIR GUIDE -LH ?	\$ 23.00	X NN

SUB-TOTAL SPARE PARTS CHARGES

: \$ 11,702.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 8682 U

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	RADIATOR AIR GUIDE-UPPER CENTER X	\$ 12.00	X NN
22	FRONT WHEEL HOUSING LINER-LH / TN	\$ 159.00	127.20
23	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS / NK	\$ 84.00	X NN
24	FRONT CAR PLATE NO. X	S/N \$ 60.00	40 ✓ NEC
25	SUNDRIES 7	\$ 300.00	8.64 NEC ✓
TOTAL SPARE PARTS CHARGES		: \$ 12,317.00	
TOTAL LABOUR CHARGES		: \$ 4,752.00	
GRAND TOTAL		: \$ 17,069.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183


11/3/2020

Telefax

Name

:

Steve (LKK)

DD- Not Authorised (Revised)

Surveyed Date

:

Excess - ?

Authorised Date

:

Excess Cost

:

P/P

Liability

:

By B/L sy

Remarks

:

4 - 7 days

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant