

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms; China Taiping Insurance (Singapore) Pte Ltd

Date 10/3/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLK5763Z

Chassis No: JM6BN22A8H0138162

MAKE / MODEL : Mazda 3 Sedan 1.5 AT

DATE OF ACCIDENT : 04/03/2020

YOUR INSURED VEHICLE NUMBER : PC3459K

MILEAGE : 170873 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	R/R taillamp <i>RH / CR 4</i>	1PC	\$ 750.00	\$ 750.00
2	Rear bumper LH retainer <i>X SVC</i>	1PC	\$ 76.10	\$ 76.10
3	Rear bumper reinforcement <i>?</i>	1PC	\$ 564.20	\$ 564.20
4	Rear bumper <i>/ RD</i>	1PC	\$ 1,500.00	\$ 1,500.00
5	Rear bumper RH reflector <i>?</i>	1PC	\$ 75.50	\$ 75.50
6	Rear bumper RH tow cover <i>X SVC</i>	1PC	\$ 35.00	\$ 35.00
				\$ 3,000.80
			Less 20%	\$ 600.16
			Total	\$ 2,400.64

LABOUR CHARGES

- 1 To labour charge for removing rear bumper reinforcement, rear bumper out to facilitate repairs and replacement of parts \$ 750.00 *400*

- 2 To respray rear boot and rear bumper \$ 800.00 *400*

LABOUR TOTAL S\$: \$ 1,550.00
TOTAL S\$: \$ 3,950.64
7% GST \$ 484.00
GRAND TOTAL S\$: \$ 6,430.36

Repair day - 3 days

Lump sum

After paint photo

Sun Pm (Lklc)

11/03/2020

TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: