

ASS. REC. BY:

REF: CS/III 20063854 / Uyf3 12

Special Instruction:

Surveyor: MORTALASSIGNMENT (Office)

From (Person):

Gabrie / WLIof IIIDate/Time: 11.3.2020 10.09A.M

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 3577U

Insured:

SHA 2042R

at Workshop n/s

M/S Automobili Hub Enterprise

Tel:

9786 4483

of

1 Kaki Bukit Ave 6 #02-11 Autobay

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 10. Mar. 2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11/3/2020 11.16a.m

Person Contacted:

Mr LimVehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLW 3577U - NA/INC18003347/24 DOA-051005/2020
	SHA 2042R - CC3/E 15005591/EPI352 DOA-30103/2015

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: S2W 357TU
 at Workshop m/s: Autobahn
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: S2W 357TU Yr Regn: 2, 18
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA /
 Make: Toyota prius Alpha Hybrid 1797
 Colour: Cmy A/C: Insured / Std / NI / NA
 Sp Reading: 189367 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 2VW 400027981
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: in order / Jammed / Leaked / Burnt or
 Brake: in order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 89k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 13 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS LTA 51860
 Date: _____ Person Contacted: _____ Vehicle IN / OUT

Tyre Size: F: 205/60R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or FALKEN
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 10/3/20 D.O.I. 11/3/20
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
free of all o/s.
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
7 yrs 11 mths exp 9800 net + 37140

23/3/20 4/5 \$16,000 conf. sent with AH xcopy (Red \$22265-75, 58%)

RECEIVED 24 MAR 2020

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 13
 Resurvey No. of Trip: 4

Date/Time, File Return to?
24/3/20 Typist

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	450
Transportation:	11
Photos	
Others	
TOTAL	461

Report Format :
Lump Sum / I.B.I. (\$ 16000/=)

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 11 March 2020 10:09 AM
To: Cindy Tan; 'sur@lkkauto.com'; 'Admin-D (LKKAuto)'
Cc: Sherini Pillai
Subject: RE: Yref: SHA 2042R Oref: KSG/5119/2020/G/ct
Attachments: client's GIA.PDF

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLW3577U and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

*We started using audatex since 1st dec 2019. Please do adjustments throught Audatex and upload the report onto Merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Cindy Tan [mailto:cindy.tan@kannansg.com.sg]
Sent: Wednesday, 11 March 2020 9:30 am
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: RE: Yref: SHA 2042R Oref: KSG/5119/2020/G/ct

Dear Sirs / Mdm

WITHOUT PREJUDICE

**RE: PROPERTY DAMAGE CLAIM
CLAIMANT : GD CARZ (UEN NO: 53122597J)
ACCIDENT INVOLVING VEHICLE NO. SFX 9683Y, SLW 3577U & SHA 2042R ALONG PIE TOWARDS TUAS AT
KPE EXIT TUNNEL ON 10 MARCH 2020 AT 0950 HRS
PRE-REPAIR INSPECTION NOTICE**

We refer to the above matter and to your email dated 11 March 2020.

We are instructed to propose using LKK Auto Consultants Pte Ltd as the single joint expert as listed in your said email.

Kindly contact Mr Lim at 9786 4483 to arrange for the pre-repair inspection soonest possible.

Regards

Cindy Tan

M/S KANNAN SG
Advocates & solicitors
50 Chin Swee Road
#08-03 Thong Chai Building
Singapore 169874

TEL: (+65) 6429 0253

FAX: (+65) 6223 1660

.....
.....
IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY. THANK YOU.
.....
.....

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]
Sent: Wednesday, 11 March, 2020 9:01 AM
To: Cindy Tan
Subject: RE: Yref: SHA 2042R Oref: KSG/5119/2020/G/ct

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

We started using audatex since 1st dec 2019. Please submit your estimate/quotation throught Audatex so that our surveyors can make the adjustments according.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Cindy Tan [mailto:cindy.tan@kannansg.com.sg]
Sent: Tuesday, 10 March 2020 4:23 pm
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Yref: SHA 2042R Oref: KSG/5119/2020/G/ct

Dear Sirs / Mdm

WITHOUT PREJUDICE

**RE: PROPERTY DAMAGE CLAIM
CLAIMANT : GD CARZ (UEN NO: 53122597J)
ACCIDENT INVOLVING VEHICLE NO. SFX 9683Y, SLW 3577U & SHA 2042R ALONG PIE TOWARDS TUAS AT
KPE EXIT TUNNEL ON 10 MARCH 2020 AT 0950 HRS
PRE-REPAIR INSPECTION NOTICE**

We act for M/s Gd Carz, the owner of motor vehicle No. SLW 3577U, which was involved in the aforesaid accident. A copy of the Singapore Accident Statement filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceeds to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle at our clients' workshop. The details are as follows:-

Place: M/s Automobile Hub Enterprise
1 Kaki Bukit Avenue 6
#02-11 Autobay@Kaki Bukit
Singapore 417883

Contact Person: Mr Lim - 9786 4483

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Kindly revert.

Regards

Cindy Tan

M/S KANNAN SG
Advocates & solicitors
50 Chin Swee Road
#08-03 Thong Chai Building
Singapore 169874

TEL: (+65) 6429 0253

FAX: (+65) 6223 1660

.....
.....
IMPORTANT: THIS E-MAIL IS INTENDED ONLY FOR THE USE OF THE ADDRESSEE AND MAY CONTAIN CONFIDENTIAL INFORMATION AND/OR MAY BE COVERED BY PROFESSIONAL PRIVILEGE. IT MUST NOT BE READ, USED OR DISCLOSED BY ANY PERSON OTHER THAN THE ADDRESSEE(S) NAMED. IF YOU HAVE RECEIVED THIS E-MAIL IN ERROR, PLEASE NOTIFY US IMMEDIATELY BY TELEPHONE (COLLECT INTERNATIONAL CALL IF APPROPRIATE) AT (+65) 6429 0252 OR BY E-MAIL AND DELETE THE E-MAIL IMMEDIATELY. THANK YOU.

.....
.....

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

ANNOUNCING Das WeltAuto
as sgCarMart Premium Dealer 2020

Das WeltAuto.

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

BMW 3 Series 316i Sport.



Fully Done Up Unit, Regularly
Serviced.
Direct Owner StarAd

HIN LUNG AUTO
No Fee Garage **30 years**
of car sale

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

Browse by Category

Sort by Date Posted 20 results/page

6 vehicles

Prius Alpha Hybrid 1.8A S

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Milage	Veh Type	Status
Search Selection	Prius Alpha Hybrid 1.8A S		Any	Any	2018	Any	Any	Any	Available
	Toyota	Prius Alpha Hybrid 1.8A S	<u>\$95,000</u>	\$10,600 /yr	09-Feb-2018	1,797 cc	-	MPV	Available
	Fuel Type: Petrol-Electric Elegant Brown, 7 Seaters MPV, Low Fuel Consumption With Hybrid, Low Maintenance Cost, Very Well Maintained, With Warranty, Easy F... Prime Motor & Leasing Posted: 10-Mar-2020 Tags: 2018 Toyota Prius, Toyota Prius, Toyota, Prius								
	Toyota	Prius Alpha Hybrid 1.8A S	\$92,800	\$9,830 /yr	08-May-2018	1,797 cc	70,000 km	MPV	Available
	Fuel Type: Petrol-Electric Brand New Condition, Low Fuel Consumption, Spacious Interior, 7 Seats MPV, Warranty With 3 Free Servicing, Loan 95% In House Loan... Posted: 09-Mar-2020 Tags: 2018 Toyota Prius, Toyota Prius, Toyota, Prius								
	Toyota	Prius Alpha Hybrid 1.8A S	\$94,800	\$10,580 /yr	07-Feb-2018	1,797 cc	37,000 km	MPV	Available
	Fuel Type: Petrol-Electric Elegant Brown, 7 Seaters MPV, Low Fuel Consumption With Hybrid, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexib... Posted: 07-Mar-2020 Tags: 2018 Toyota Prius, Toyota Prius, Toyota, Prius								
	Toyota	Prius Alpha Hybrid 1.8A S	\$102,500	\$10,510 /yr	22-Oct-2018	1,797 cc	-	MPV	Available
	Fuel Type: Petrol-Electric Elegant White, 7 Seater MPV, Low Fuel Consumption, With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy... Prime Motor & Leasing Posted: 29-Feb-2020 Tags: 2018 Toyota Prius, Toyota Prius, Toyota, Prius								
	Amazing Glaze AG5 Pte Ltd - Paint Protection Certified by both Boeing and Airbus Industries, Amazing Glaze provides durable automotive paint protection system. More info about this shop								
	Toyota	Prius Alpha Hybrid 1.8A S	\$98,000	\$10,400 /yr	29-Jun-2018	1,797 cc	30,322 km	MPV	Available
	Fuel Type: Petrol-Electric 1 OWNER ONLY Fantastic Condition, Best Fuel Efficiency 7 Seaters MPV, 100% In-house Loan Packages Available, High Trade-In. Whats... Posted: 05-Feb-2020 Tags: 2018 Toyota Prius, Toyota Prius, Toyota, Prius								
	Toyota	Prius Alpha Hybrid 1.8A S	\$99,800	\$10,620 /yr	29-Jun-2018	1,797 cc	59,288 km	MPV	Available
	Fuel Type: Petrol-Electric 100% Loan Available. 1 Owner. Original Condition. Elegant Silver On Black Interior. Please Call For Viewing/Test Drive Now.								

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	597J
Vehicle Details	
Vehicle No.:	SLW3577U
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Mar 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS ALPHA HYBRID 1.8S CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	2ZR0A79316
Chassis No.:	ZVW400027981
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$28,143.00
Original Registration Date:	08 Feb 2018
First Registration Date:	08 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$21,401.00 <i>107.00</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Feb 2028
PARF Rebate Amount:	\$16,050.00
Intended COE Rebate Details	
COE Expiry Date:	07 Feb 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,289.00
COE Rebate Amount:	\$35,810.00
Total Rebate Amount:	\$51,860.00

The information contained herein is correct as at 11 Mar 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/03/2020 15:53
Date Of Accident	10/03/2020 09:50
Exact Location Of Accident	PIE TOWARDS TUAS AT KPE EXIT TUNNEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW3577U
Insured/Policyholder	
Name Of Registered Owner	GD CARZ
Co Reg No	5XXXX597J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81888453
Alternative Phone No	OFFICE-81888453

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRER USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5111925837
Cover Note Number	

Driver

Name of Driver	ISMAIL BIN OMAR
NRIC No	SXXXX604B
Date Of Birth	24/04/1972
Occupation	OUTDOOR
Date Of Driving Pass	13/09/2000
Driving Experience	19 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81888453
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	APT BLK 412 BEDOK NORTH AVE 2 #03-122
Postcode	460412
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA2042R
Vehicle Make/Model/Colour	BLUE
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SFX9683Y
Vehicle Make/Model/Colour	TOYOTA CAMRY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	ISMAIL BIN OMAR
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLW3577U
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	APT BLK 412 BEDOK NORTH AVE 2 #03-122
Postcode	460412

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

E. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 

Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRC/IN No.:

Repair Estimate

27	Rear door checker o/s	NA	1	\$ 109.00	\$ 109.00	X
28	Rear door window channel o/s	11	1	\$ 85.00	\$ 85.00	X
29	Tailgate	1450-10 Body	1	\$ 2,154.00	\$ 2,154.00	X
30	Tailgate spoiler	11	1	\$ 415.00	\$ 415.00	X
31	Tailgate spoiler brake lamp	11	1	\$ 334.00	\$ 334.00	X
32	Tailgate outer garnish	Sub/cne	1	\$ 485.00	\$ 485.00	X
33	Tailgate "TOYOTA" logo	67-10	1	\$ 92.00	\$ 92.00	X
34	Tailgate "PRIUS" emblem	72-6-10	1	\$ 77.00	\$ 77.00	X
35	Tailgate "HYBRID" emblem	NA	1	\$ 59.00	\$ 59.00	X
36	Tailgate buzzer	NA	1	\$ 369.00	\$ 369.00	X
37	Tailgate inner handle	NA	1	\$ 136.00	\$ 136.00	X
38	Tailgate inner lock	M/Jm	1	\$ 485.00	\$ 485.00	X
39	Tailgate lock sensor	show	1	\$ 334.00	\$ 334.00	X
40	Tailgate striker	11	1	\$ 95.00	\$ 95.00	X
41	Tailgate trimboard	581-9-10	1	\$ 945.00	\$ 945.00	X
42	Tailgate weatherstrip	7w1	1	\$ 218.00	\$ 218.00	X
43	Tailgate hinge	11	2	\$ 176.00	\$ 352.00	X
44	Tailgate windscreen moulding	166-10	1	\$ 194.00	\$ 194.00	X
45	Taillamp	561-10x2=112270	2	\$ 989.00	\$ 1,978.00	X
46	Rear bumper	665-10	1	\$ 1,296.00	\$ 1,296.00	X
47	Rear bumper retainer	NA	2	\$ 74.00	\$ 148.00	X
48	Rear fender side air vent o/s	Bin	1	\$ 126.00	\$ 126.00	X
49	Rear wheel house panel o/s	Body	1	\$ 845.00	\$ 845.00	X
50	Rear bumper top bracket	NS	4	\$ 78.00	\$ 312.00	X
51	Rear bumper side reflector	99-10	2	\$ 196.00	\$ 392.00	X
52	Rear bumper lower cowl	NS	1	\$ 498.00	\$ 498.00	X
53	End panel outer	678-10	1	\$ 785.00	\$ 785.00	X
54	End panel inner	455-10	1	\$ 696.00	\$ 696.00	X
55	End panel top garnish	371-10	1	\$ 389.00	\$ 389.00	X
56	Rear fender inner trim o/s	11	1	\$ 663.00	\$ 663.00	X
57	Rear fender glass moulding o/s	NA	1	\$ 76.00	\$ 76.00	X
58	Rear fender o/s	1125-10	1	\$ 1,265.00	\$ 1,265.00	X
59	Rear fender cowling	182-25	2	\$ 219.00	\$ 438.00	X
60	Spare tyre compartment middle board	NA	1	\$ 348.00	\$ 348.00	X
61	Spare tyre compartment side board	11	2	\$ 196.00	\$ 392.00	X
62	Tailgate wiper motor	11	1	\$ 364.00	\$ 364.00	X
63	Tailgate wiper arm	11	1	\$ 82.00	\$ 82.00	X
64	Rear floor panel tool tray	6PC	1	\$ 775.00	\$ 775.00	X
65	Rear bumper impact absorber	NS	1	\$ 127.00	\$ 127.00	X
66	Tools holder sponge	NS	1	\$ 197.00	\$ 197.00	X

Repair Estimate

67	Spare tyre panel	3-tyre/sec	1	\$ 1,194.00	\$ 1,194.00	
68	Exhaust assy	223.10 Two/Sec	1	\$ 878.00	\$ 878.00	
69	Exhaust assy mounting	set	2	\$ 55.00	\$ 110.00	
70	Exhaust heat shield	set	1	\$ 186.00	\$ 186.00	
71	Rear axle	17	1	\$ 3,345.00	\$ 3,345.00	X
72	Rear shock absorber	17	2	\$ 477.00	\$ 954.00	X
73	Rear shock absorber top mount	17	2	\$ 86.00	\$ 172.00	X
Subtotal					\$ 39,473.00	
List discount					25.00%	
Total					\$ 29,604.75	19070.00 252 1432.53

Special nett items						
No.	Parts description		QTY	UNIT PRICE	AMOUNT	
1	Bonnet insulator clips	17	8	\$ 5.50	\$ 44.00	X
2	Bonnet weatherstrip	17	1	\$ 48.00	\$ 48.00	X
3	Rear door inner trim clips o/s	17	8	\$ 5.50	\$ 44.00	X
4	Rear wheel house panel sealant o/s	set	1	\$ 100.00	\$ 100.00	50
5	Front bumper clips	set	10	\$ 5.50	\$ 55.00	50
6	Front support panel top garnish clips	17	6	\$ 5.50	\$ 33.00	X
7	Engine under cowling clips	17	6	\$ 5.50	\$ 33.00	X
8	Front licence plate & frame	set	1	\$ 55.00	\$ 55.00	40
9	Radiator coolant	17	1	\$ 60.00	\$ 60.00	X
10	Rear bumper cowling clips	17	8	\$ 5.50	\$ 44.00	X
11	Rear fender glass sealant o/s	set	1	\$ 100.00	\$ 100.00	40
12	Rear licence plate & frame	set	1	\$ 55.00	\$ 55.00	40
13	Tailgate outer garnish clips	17	4	\$ 8.50	\$ 34.00	X
14	Tailgate trimboard clips	set	10	\$ 8.50	\$ 85.00	50
15	Tailgate windscreen sealant	set	1	\$ 80.00	\$ 80.00	40
16	Rear bumper clips	set	12	\$ 8.50	\$ 102.00	50
17	End panel sealant	set	1	\$ 100.00	\$ 100.00	50
18	Rear fender inner trim clips	17	20	\$ 8.50	\$ 170.00	X
19	Spare tyre panel 185/65 r	set	1	\$ 100.00	\$ 100.00	✓
20	Rear fender cowling clips	17	16	\$ 8.50	\$ 136.00	X
21	End panel top garnish clips	17	6	\$ 5.50	\$ 33.00	X
22	Sundries	17	1	\$ 50.00	\$ 50.00	X
Total					\$ 1,561.00	

1set Rear bumper reverse sensor
 1set Rear reverse camera
 Battery Rear

200 should - S.N
 350 should - S.N
 200 do - S.N

Repair Estimate

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew front accident damaged portions. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00
2	To disconnect front wire harness of electrical components to facilitate repairs, reconnect and check functions including focusing headlamps.	0.25	\$ 50.00
3	To remove and refit radiator to facilitate repair. To perform pressure test and check cooling system functionality.	1	\$ 200.00
4	Supply spray paint material and necessary items to respray front bumper, bonnet, support panel, o/s front fender and other affected area / panel.	5	\$ 1,000.00
5	To dismantle / renew rear accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	8	\$ 1,600.00
6	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
7	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	1	\$ 200.00
8	To remove and refit, straighten and re-adjust exhaust pipe and replace exhaust silencer.	0.75	\$ 150.00
9	To remove and refit interior upholstery to facilitate repair work.	0.75	\$ 150.00
10	To remove and refit o/s rear fender glass to facilitate the repair.	0.75	\$ 150.00
11	To align rear chassis frame and to conduct chassis alignment on Car-O-Liner.	1.5	\$ 300.00
12	Supply spray paint material and necessary items to respray rear bumper, o/s rear fender, tailgate, end panel and other affected area / panel.	8	\$ 1,600.00
13	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00
14	To remove and refit rear undercarriage for replacement of parts.	1	\$ 200.00
15	To conduct computerized wheel alignment.	0.5	\$ 100.00
16	To rust proof all affected portions after repair.	1	\$ 200.00
Total labour			\$ 7,100.00

400
15
X
600
✓
15
60
60
100
80
X
1300
120
X
X
100

Estimate Grand Total \$ 38,265.75

39015.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-1430253
S. N. 1260.00
L-4400.00

200/253
202

16010-02

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III20003854/UYF3N2
Date: 30/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No:
Claimant Vehicle No : SLW3577U **Insured Vehicle No :** SHA2042R
 Date of Loss: 10/03/2020 Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW3577U** Engine No: 22R0A79316
 Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Chassis No: ZVW400027981
 Reg. Date: 08/02/2018 (Man. Year: 2017) Odometer: 189367 km
 Colour: Grey
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,915.75	15,562.54	16,353.21	51.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,100.00	4,450.00	2,650.00	37.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,015.75	20,012.54	19,003.21	48.71
Approved Total (Overridden) (S\$)		16,000.00		
Nett Amount (S\$)	39,015.75	16,000.00	23,015.75	58.99

INSPECTION

Date of Assignment: 11/03/2020
 Date Inspected: 11/03/2020 Inspected At: Automobile Hub Enterprise
 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @
 KAKI BUKIT
 Singapore 417883
 Estimated Period of Repair: 13.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Mar 2020)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLW3577U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,068.00 FL	*- FL
2	1		*BONNET LOCK	Not Necessary	187.00 FL	*- FL
3	2		*BONNET HINGE	Not Necessary	286.00 FL	*- FL
4	1		*BONNET BOTTOM LOCK ASSY	Not Necessary	68.00 FL	*- FL
5	1		*BONNET LOCK SENSOR	Not Necessary	169.00 FL	*- FL
6	1		*FRONT BUMPER	Dented/Deformed	1,389.00 FL	*665.10 FL
7	1		*FRONT BUMPER TOP PANEL	Repair	637.00 FL	*- FL
8	1		*FRONT BUMPER SIDE RETAINER	O/s Bent	156.00 FL	*78.00 FL
9	1		*HEADLAMP ASSY O/S	Holder Cracked	2,936.00 FL	*1,855.10 FL
10	1		*HEADLAMP LOWER BRACKET O/S	Not Necessary	105.00 FL	*- FL
11	1		*HEADLAMP SUPPORT PANEL O/S	Repair	457.00 FL	*- FL
12	1		*HEADLAMP TOP BRACKET O/S	Not Necessary	267.00 FL	*- FL
13	1		*FRONT BUMPER GRILLE	Torn	678.00 FL	*481.50 FL
14	1		*FRONT BUMPER GRILLE TOYOTA EMBLEM	Scratched	117.00 FL	*117.00 FL
15	1		*FRONT BUMPER LOWER GRILLE	Torn	295.00 FL	*295.00 FL
16	1		*FOG LAMP O/S	Cracked	469.00 FL	*469.00 FL
17	1		*FRONT BUMPER TOWING CAP	Deformed	73.00 FL	*73.00 FL
18	1		*FRONT BUMPER SIDE LAMP O/S	Cracked	397.00 FL	*397.00 FL
19	1		*FRONT BUMPER SIDE LAMP GARNISH O/S	Scratched	145.00 FL	*145.00 FL
20	1		*FRONT BUMPER SPONGE	Torn	187.00 FL	*187.00 FL
21	1		*FRONT BUMPER REINFORCEMENT BRACKET O/S	Bent	557.00 FL	*350.00 FL
22	1		*FRONT SUPPORT PANEL	Repair	675.00 FL	*- FL
23	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	289.00 FL	*- FL
24	1		*REAR DOOR O/S	Repair	1,443.00 FL	*- FL
25	1		*REAR DOOR HINGE O/S	Not Necessary	122.00 FL	*- FL
26	1		*REAR DOOR LOCK O/S	Not Necessary	332.00 FL	*- FL
27	1		*REAR DOOR CHECKER O/S	Not Necessary	109.00 FL	*- FL
28	1		*REAR DOOR WINDOW CHANNEL O/S	Not Necessary	85.00 FL	*- FL
29	1		*TAILGATE	Badly Dented	2,154.00 FL	*1,450.10 FL
30	1		*TAILGATE SPOILER	Not Necessary	415.00 FL	*- FL
31	1		*TAILGATE SPOILER BRAKE LAMP	Not Necessary	334.00 FL	*- FL
32	1		*TAILGATE OUTER GARNISH	Bent/Cracked	485.00 FL	*485.00 FL
33	1		*TAILGATE TOYOTA LOGO	Necessary	92.00 FL	*67.10 FL
34	1		*TAILGATE PRIUS EMBLEM	Necessary	77.00 FL	*72.60 FL
35	1		*TAILGATE HYBRID EMBLEM	Necessary	59.00 FL	*59.00 FL
36	1		*TAILGATE BUZZER	Not fitted	369.00 FL	*- FL
37	1		*TAILGATE INNER HANDLE	Deformed	136.00 FL	*136.00 FL
38	1		*TAILGATE INNER LOCK	Dented/Jammed	485.00 FL	*485.00 FL
39	1		*TAILGATE LOCK SENSOR	Shorted	334.00 FL	*334.00 FL
40	1		*TAILGATE STRIKER	Not Necessary	95.00 FL	*- FL
41	1		*TAILGATE TRIMBOARD	Distorted	945.00 FL	*581.90 FL
42	1		*TAILGATE WEATHERSTRIP	Twisted	218.00 FL	*218.00 FL
43	2		*TAILGATE HINGE	Not Necessary	352.00 FL	*- FL
44	1		*TAILGATE WINDSCREEN MOULDING	Necessary	194.00 FL	*166.10 FL
45	2		*TAILLAMP	Cracked	1,978.00 FL	*1,122.20 FL
46	1		*REAR BUMPER	Distorted	1,296.00 FL	*665.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	2		*REAR BUMPER RETAINER	Bent	148.00 FL	*148.00 FL
48	1		*REAR FENDER SIDE AIR VENT O/S	Torn	126.00 FL	*126.00 FL
49	1		*REAR WHEEL HOUSE PANEL O/S	Badly Dented	845.00 FL	*845.00 FL
50	4		*REAR BUMPER TOP BRACKET	No such part	312.00 FL	*- FL
51	1		*REAR BUMPER SIDE REFLECTOR	O/s Cracked	392.00 FL	*99.50 FL
52	1		*REAR BUMPER LOWER COWLING	No such part	498.00 FL	*- FL
53	1		*END PANEL OUTER	Badly Dented	785.00 FL	*678.10 FL
54	1		*END PANEL INNER	Badly Dented	696.00 FL	*455.10 FL
55	1		*END PANEL TOP GARNISH	Distorted	389.00 FL	*371.10 FL
56	1		*REAR FENDER INNER TRIM O/S	Distorted	663.00 FL	*663.00 FL
57	1		*REAR FENDER GLASS MOULDING O/S	Necessary	76.00 FL	*76.00 FL
58	1		*REAR FENDER O/S	Badly Dented/Buckled	1,265.00 FL	*1,125.10 FL
59	1		*REAR FENDER COWLING	O/s Torn	438.00 FL	*182.25 FL
60	1		*SPARE TYRE COMPARTMENT MIDDLE BOARD	Cracked	348.00 FL	*348.00 FL
61	2		*SPARE TYRE COMPARTMENT SIDE BOARD	Not Necessary	392.00 FL	*- FL
62	1		*TAILGATE WIPER MOTOR	Not Necessary	364.00 FL	*- FL
63	1		*TAILGATE WIPER ARM	Not Necessary	82.00 FL	*- FL
64	1		*REAR FLOOR PANEL TOOL TRAY	Distorted	775.00 FL	*685.00 FL
65	1		*REAR BUMPER IMPACT ABSORBER	No such part	127.00 FL	*- FL
66	1		*TOOLS HOLDER SPONGE	No such part	197.00 FL	*- FL
67	1		*SPARE TYRE PANEL	Badly Dented/Buckled	1,194.00 FL	*1,194.00 FL
68	1		*EXHAUST ASSY	Twisted/Bent	878.00 FL	*823.10 FL
69	2		*EXHAUST ASSY MOUNTING	Necessary	110.00 FL	*110.00 FL
70	1		*EXHAUST HEAT SHIELD	Bent	186.00 FL	*186.00 FL
71	1		*REAR AXLE	Not Necessary	3,345.00 FL	*- FL
72	2		*REAR SHOCK ABSORBER	Not Necessary	954.00 FL	*- FL
73	2		*REAR SHOCK ABSORBER TOP MOUNT	Not Necessary	172.00 FL	*- FL
74	8		*BONNET INSULATOR CLIPS	Not Necessary	44.00 FS	*- FS
75	1		*BONNET WEATHERSTRIP	Not Necessary	48.00 FS	*- FS
76	8		*REAR DOOR INNER TRIM CLIPS O/S	Not Necessary	44.00 FS	*- FS
77	1		*REAR WHEEL HOUSE PANEL SEALANT O/S	Necessary	100.00 FS	*50.00 FS
78	1		*SET FRONT BUMPER CLIPS	Necessary	55.00 FS	*50.00 FS
79	6		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	33.00 FS	*- FS
80	6		*ENGINE UNDER COWLING CLIPS	Not Necessary	33.00 FS	*- FS
81	1		*FRONT LICENCE PLATE & FRAME	Bent	55.00 FS	*40.00 FS
82	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*- FS
83	8		*REAR BUMPER COWLING CLIPS	Not Necessary	44.00 FS	*- FS
84	1		*REAR FENDER GLASS SEALANT O/S	Necessary	100.00 FS	*40.00 FS
85	1		*REAR LICENCE PLATE & FRAME	Bent	55.00 FS	*40.00 FS
86	4		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	34.00 FS	*- FS
87	1		*SET TAILGATE TRIMBOARD CLIPS	Necessary	85.00 FS	*50.00 FS
88	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
89	1		*SET REAR BUMPER CLIPS	Necessary	102.00 FS	*50.00 FS
90	1		*END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS
91	20		*REAR FENDER INNER TRIM CLIPS	Not Necessary	170.00 FS	*- FS
92	1		*SET SPARE TYRE PANEL INSULATOR	Necessary	100.00 FS	*100.00 FS
93	16		*REAR FENDER COWLING CLIPS	Not Necessary	136.00 FS	*- FS
94	6		*END PANEL TOP GARNISH CLIPS	Not Necessary	33.00 FS	*- FS
95	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
96	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
97	1		*SET REAR REVERSE CAMERA	Shorted	350.00 FS	*350.00 FS
98	1		*BATTERY REAR	Dented	200.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	41,784.00	20,330.05
- List Item Discount on L Items 25.00/25.00% (\$\$)	9,868.25	4,767.51
Total Parts (\$\$)	31,915.75	15,562.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW FRONT ACCIDENT DAMAGED PORTIONS.TO PANEL BEAT,RESHAPE,STRAIGHTE,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,000.00	400.00
2	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING FOCUSING HEADLAMPS	New	50.00	15.00
3	TO REMOVE AND REFIT RADIATOR TO FACILITATE REPAIR.TO PERFORM PRESSURE TEST AND CHECK COOLING SYSTEM FUNCTIONALITY	New	200.00	0.00
4	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY FRONT BUMPER,BONNET,SUPPORT PANEL,O/S FRONT FENDER AND OTHER AFFECTED AREA/PANEL	New	1,000.00	600.00
5	TO DISMANTLE/RENEW REAR ACCIDENT DAMAGED PORTION.TO PANEL BEAT,RESHAPE,STRAIGHTE,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,600.00	1,600.00
6	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS	New	50.00	15.00
7	TO REMOVE,REFIT TAILGATE COMPONENTS TO REPLACE TAILGATE,CHECK AND RE-ADJUST CLOSE GAP,ALIGNMENT AND WATER SEEPAGE	New	200.00	60.00
8	TO REMOVE AND REFIT,STRAIGHTEN AND RE-ADJUST EXHAUSTPIPE AND REPLACE EXHAUST SILENCER	New	150.00	60.00
9	TO REMOVE AND REFIT INTERIOR UPHOLSTERY TO FACILITATE REPAIR WORK	New	150.00	100.00
10	TO REMOVE AND REFIT O/S REAR FENDER GLASS TO FACILITATE THE REPAIR	New	150.00	80.00
11	TO ALIGN REAR CHASSIS FRAME AND TO CONDUCT CHASSIS ALIGNMENT ON CAR-O-LINER	New	300.00	0.00
12	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY REAR BUMPER,O/S REAR FENDER,TAILGATE,END PANEL AND OTHER AFFECTED AREA/PANEL	New	1,600.00	1,300.00
13	TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR WORK	New	150.00	120.00
14	TO REMOVE AND REFIT REAR UNDERCARRIAGE FOR REPLACEMENT OF PARTS	New	200.00	0.00
15	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	100.00	0.00
16	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	200.00	100.00
Gross Labour Cost (S\$)			7,100.00	4,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >