

Code	Description	Part Number	Part Source	Price SGD
3571	L/R LAMP PANEL	63720SNBE00ZZ	Original	bt ✓ 65.00
4971	L/C-PILLAR TRIM	84180SNAA11ZA	Original	180.00
4985	END PANEL TRIM	84640SNAA01ZA	Original	30.00
1003	REAR BOOT LOCK	COVER	Original	10.00
1004	REAR BOOT 1.6 IVTEC	LOGO	Original	15.00
1006	L/R FENDER INNER	SHIELD	Original	50.00
1007	REAR FENDER AIR VENT	LH	OEM	de ✓ 30.00

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Savings	0.00
Subtotal	2,518.00
Fixed Sundry Parts Price	100.00
Total	2,618.00

Extras

Code	Description	Price SGD
1000	TO RESET & DIAGNOSE FAULT CODE	150.00*
1001	REAR WINDSCREEN SEALANT	40.00*
1002	TO DO WHEEL ALIGNMENT	80.00*
1005	CHECK WIRING .	30.00*
1009	RR BUMPER SENSOR RETAINER (4PCS)	nec ✓ 100.00*
1010	RR BUMPER SENSOR ECU	dis ✓ 240.00*
Total Extras		640.00