

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9785T**AAD2003-052**

Not Authorised
1/Qty @ 5250/-

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

10 MAR 2020

Third Party Insurer :

Date of Registration:

SHD 9785T

VF1ABL15AUC277263

RENAULT

LATITUDE

8.3.2020

CHINA TAIPING

14/4/2014

PART		LIST	
1	DOOR PANEL FRT RH	\$	<i>As</i> 2,844.66 ✓
1	DOOR HINGE UPPER RH	\$	<i>n</i> 261.28 X
1	DOOR HINGE LOWER RH	\$	<i>n</i> 300.55 X
1	DOOR CHECK FRT RH	\$	<i>sn</i> 194.77 X
1	DOOR REGULATOR FRT RH	\$	<i>By</i> 758.10 ✓
1	DOOR REGULATOR MOTOR FRT RH	\$	<i>sn</i> 796.46 ✓
1	DOOR REGULATOR GUIDE FRT RH	\$	<i>sn</i> 120.97
1	DOOR WHEATHESTRIIP FRONT RH	\$	<i>sn</i> 410.27
1	DOOR SEAL FRONT RH	\$	<i>sn</i> 72.82
1	DOOR SEAL LOWER FRONT RH	\$	<i>sn</i> 93.90
1	DOOR SEAL FRT RH	\$	<i>sn</i> 63.10
1	DOOR MOULDING BLACK FRONT RH	\$	<i>sn</i> 176.82
1	DOOR FINISHER FRONT RH	\$	<i>sn</i> 515.06
1	DOOR FINISHER CLIP KIT FRT RH	\$	<i>na</i> 94.00
1	DOOR GLASS RUNNER SEAL FRONT RH	\$	<i>sn</i> 626.36
1	DOOR HANDLE OUTER FRONT RH	\$	<i>n</i> 477.76
1	DOOR HANDLE CAP FRONT RH	\$	<i>sn</i> 35.52
1	DOOR HANDLE SEAL FRT RH	\$	<i>sn</i> 7.89
1	DOOR HANDLE COVER FRT RH	\$	<i>sn</i> 13.22
1	DOOR HANDLE MODULE FRT RH L70Y	\$	<i>sn</i> 133.60
1	DOOR LOCK FRT RH	\$	<i>n</i> 908.75
1	DOOR CATCH FRT RH	\$	<i>n</i> 131.23
1	DOOR FINISHER INNER FRT RH	\$	<i>sn</i> 323.44
1	DOOR FINISHER INNER BRACKET FRT RH	\$	<i>sn</i> 46.97
1	DOOR WAIST SEAL OUTER FRT RH	\$	<i>sn</i> 291.27
1	DOOR WAIST SEAL INNER FRT RH	\$	<i>sn</i> 122.15
1	DOOR MIRROR ASSY RH	\$	<i>sn</i> 1,483.40
1	DOOR HARNESS WIRE RH	\$	<i>sn</i> 2,670.00
1	ROCKER PANEL INNER GARNISH RH	\$	<i>sn</i> 466.51
1	ROCKER PANEL INNER RH	\$	<i>n</i> 1,024.79
1	ROCKER PANEL OUTER RH	\$	<i>n</i> 1,184.99

X

Trans-cab Auto Services Pte Ltd

AAD2003-052

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9785T

- 1 ROCKER PANEL CENTER RH
- 1 FENDER PANEL FRT RH
- 1 WHEELARCH FRT RH
- 1 FENDER BRACKET LOWER RH
- 1 FENDER INSULATOR RH
- 1 BUMPER COVER FRT
- 1 BUMPER RETAINER FRT RH
- 1 DOOR PANEL REAR RH
- 1 DOOR GUIDE REAR RH
- 1 DOOR HINGE UPPER REAR RH L70Y
- 1 DOOR HINGE LOWER REAR RH L70Y
- 1 DOOR CHECK REAR RH

\$	Bj	990.25	✓
\$	N	437.10	}
\$	Sn	191.40	
\$	Sn	11.80	
\$	Sn	65.50	
\$	N	747.20	
\$	Sn	101.40	
\$	N	758.70	
\$	Sn	136.40	
\$	N	241.60	
\$	N	169.90	
\$	Sn	114.90	X

TOTAL	\$	20,616.75
10%	\$	2,061.68
	\$	18,555.08

Special Nett

- 1 FRONT DOOR STICKER 'Trans-Cab'
- 1 FRONT DOOR STICKER 'Classic'
- 1 REAR DOOR STICKER '6555-3333'
- 1 RH SIDE RENAULT TYRE 215/60/16
- 1 RH SIDE RENAULT TYRE RIM
- 1 RH SIDE RENAULT TYRE RIM COVER
- 1 WHEELARCH CLIP FRT RH
- 1 DOOR CHECK BOLT
- 1 DOOR CHECK NUT
- 1 DOOR GUIDE SCREW
- 1 DOOR HINGE BOLT
- 1 DOOR HINGE NUT
- 1 DOOR MOULDING CLIP
- 1 DOOR SEAL CLIP
- 1 BUMPER BRACKET CLIP FRT RH
- 1 BUMPER CLIP FRT

\$	Nu	80.00	605N
\$	Nu	80.00	155N
\$	Nu	100.00	605N
\$	Nu	300.00	}
\$	Nu	380.00	
\$	Nu	60.00	
\$	Nu	30.50	
\$	Sn	10.20	
\$	Sn	10.20	
\$	Sn	10.85	
\$	Sn	12.60	
\$	Sn	7.20	
\$	Nu	5.90	
\$	Nu	7.30	}
\$	Nu	12.00	
\$	Nu	66.00	

TOTAL	\$	1,172.75
--------------	----	-----------------

TOTAL PARTS	\$	19,727.83
--------------------	----	------------------

LABOUR

To transfer of tire, rim and on wheel balancing.

\$	Nu	170.00	X
----	----	--------	---

Trans-cab Auto Services Pte Ltd

AAD2003-052

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9785T

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	7,500.00	6001
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
To transfer of Front door fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of front fender fittings, attachment and perform water seepage test.	\$	4 170.00	X
Putty and spray painting of the affected portion.	\$	7,500.00	801
To Check Electrical Lighting Concerned.	\$	170.00	201
To rust-proofing of the affected areas.	\$	170.00	301
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	4 170.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	4 170.00	X
TOTAL	\$	17,170.00	
Over All Total	\$	36,897.83	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LUMP SUM (REPAIR DAY)~~25 DAYS~~

5 days