

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5774B**AAD2003-048***Not Withheld**Resurvey B4 point*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

10 MAR 2020

Third Party Insurer :

Date of Registration:

SHD 5774B

JTDKB3FU103074864

TOYOTA

PRIUS

6.3.2020

AIG

1/11/2018

PART		LIST	
1	REAR BUMPER	\$	<i>Per / Per</i> 442.60 ✓
1	REAR BUMPER RE-INFORCEMENT	\$	<i>SVC</i> 332.70 ✗
1	REAR BUMPER TOWING COVER	\$	<i>S</i> 15.40 ✗
1	GUARD, REAR BUMPER, CENTER	\$	<i>Per / Per</i> 576.30 ✓
1	REAR BUMPER SIDE RETAINER LH	\$	<i>S</i> 116.50
1	REAR BUMPER SIDE RETAINER RH	\$	<i>S</i> 117.70
1	REAR TAILGATE	\$	<i>N</i> 1,147.80
1	REAR TAILGATE OUTER GARNISH	\$	<i>N</i> 925.60
1	REAR TAILGATE WEATHERSTRIP	\$	<i>S</i> 372.30
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>N</i> 650.30
1	TAILLAMP LOWER RH	\$	<i>S</i> 502.00
1	TAILLAMP UPPER RH	\$	<i>S</i> 451.80
1	REAR BUMPER SIDE RH	\$	<i>S</i> 123.70
1	REAR BUMPER SIDE LH	\$	<i>S</i> 123.70
1	TAILLAMP LOWER LH	\$	<i>S</i> 502.00
1	TAILLAMP UPPER LH	\$	<i>S</i> 443.30
1	COVER, REAR COMBINATION LAMP, LH	\$	<i>S</i> 64.50
1	COVER, REAR COMBINATION LAMP, RH	\$	<i>S</i> 64.50
1	COVER, DECK TRIM, REAR	\$	<i>S</i> 126.70
1	COVER, FLOOR UNDER, NO 1	\$	<i>S</i> 175.10
1	COVER, FLOOR UNDER, NO 2	\$	<i>S</i> 241.90
1	COVER, REAR FLOOR	\$	<i>S</i> 229.90
1	SEAL, REAR BUMPER SIDE, LH	\$	<i>S</i> 88.50

TOTAL	\$	7,834.80
25%	\$	1,958.70
	\$	5,876.10

Special Nett

Trans-cab Auto Services Pte Ltd**AAD2003-048**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5774B

1SET	PARKING AID	\$	<i>Sn</i>	700.00	X
1SET	REAR BUMPER CLIP	\$	<i>na</i>	66.00	✓
1	REAR TAILGATE TOYOTA LOGO	\$	<i>na</i>	47.00	✓
1	REAR TAILGATE WORDING 'PRIUS'	\$	<i>na</i>	52.90	✓
1	REAR TAILGATE WORDING 'HYBRID'	\$	<i>na</i>	53.50	✓
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>na</i>	80.00	30 <i>na</i>
1	REAR TAILGATE STICKER '6555-3333'	\$	<i>na</i>	80.00	30 <i>na</i>
1	REAR BUMPER PROTECTOR	\$	<i>na</i>	100.00	30 <i>na</i>
1	REAR WHEEL RIM	\$	<i>Sn</i>	1,879.40	X
1	REAR TYRE 195/65/15	\$	<i>Sn</i>	350.00	X
1	REAR WHEEL RIM COVER	\$	<i>Sn</i>	211.50	X
1	REAR RH BUMPER RETAINER CLIP	\$	<i>na</i>	35.00	X
1	REAR LH BUMPER RETAINER CLIP	\$	<i>na</i>	35.00	X
TOTAL		\$		3,690.30	

TOTAL PARTS	\$	9,566.40
--------------------	-----------	-----------------

LABOUR

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>na</i>	170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>na</i>	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i>	170.00	X
Putty And Spray Painting Of The Affected Portion.	\$		6,000.00	4401
To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i>	380.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i>	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	501

Trans-cab Auto Services Pte Ltd**AAD2003-048**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5774B

To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>100</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>2000</i>
TOTAL	\$	14,170.00	
Over All Total	\$	23,736.40	

(PART-BY-PART) Repair Days**20 Days***2 1/2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: