

辉 陽 汽 車 有 限 公 司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

07/03/2020

Owner: DENG JIA

ESTIMATE TO REPAIR HONDA FIT - SMJ8363T

1pc	rear tailgate	814.20
1pc	rear tailgate outer garnish	
1pc	rear tailgate "H" logo	
2pcs	rear tailgate side reflector @\$289.30	
1pc	rear tailgate windscreen glass moulding	
1pc	rear tailgate inner lock	180
1pc	rear tailgate inner rubber	92.30
1pc	rear tailgate inner garnish	
1pc	rear tailgate inner handle	
2pcs	rear tailgate absorber @\$159.50	
2pcs	rear taillamp @\$357.40	C305
1pc	rear taillamp LH panel	
2pcs	rear taillamp lower bracket @\$75.50	
1pc	rear bumper	575
2pcs	rear bumper side retainer @\$39.10	
1pc	rear bumper LH side garnish	
1pc	rear bumper centre garnish	
1pc	rear end panel	391.80
1pc	rear end panel inner garnish	168
1pc	rear end panel sensor	
1pc	rear end panel buzzer	105
1pc	rear float panel	
1pc	rear float panel cardboard	
1pc	rear float panel sponge	
1pc	rear LH fender	930
1pc	rear LH fender inner trim	
1pc	front bonnet	682.50
2pcs	front bonnet hinge @\$85.50	
1pc	front bonnet LH inner rubber	
1pc	front bonnet inner lock	126.80
2pcs	front headlamp @\$895.00	810
2pcs	front headlamp bracket @\$38.20	
1pc	front centre grille	
1pc	front centre grille lower chrome	
1pc	front centre grille top chrome	

balance c/f



Not Authorized	
11 days	10,800
Repair After Paint	
16 days	
BS	958.50 ✓
PS	258.55 X
GR	27.10 A
MS	578.60 X
MS	191.50 ✓
MS	258.50 ✓
MS	135.20 ✓
MS	112.70 X
MS	85.20 X
MS	319.00 A
MS	714.80 ✓
MS	185.30 ✓
MS	151.00 ✓
MS	896.50 ✓
MS	78.20 ✓
MS	125.50 ✓
MS	189.50 ✓
MS	589.00 ✓
MS	255.20 ✓
MS	191.50 ✓
MS	125.50 ✓
MS	649.50 X
MS	198.10 X
MS	285.50 ✓
MS	985.25 ✓
MS	385.20 ✓
MS	958.50 ✓
MS	171.00 ✓
MS	85.20 ✓
MS	385.25 ✓
MS	1,790.00 ✓
MS	76.40 X
MS	382.90 ✓
MS	224.10 X
MS	245.60 X

\$ 13,249.35

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

07/03/2020

Owner: DENG JIA

ESTIMATE TO REPAIR HONDA FIT - SMJ8363T

	balance b/f		\$ 13,249.35
1pc	front centre grille "H" logo	Mr	\$ 35.50 ✓
1pc	front centre grille inner bracket	\$	28.50 X
1pc	front centre grille top garnish	\$	30.90 X
1pc	front bumper 580.30	Bill cm	\$ 694.70 ✓
2pcs	front bumper side retainer @\$25.50	WLS D-1	\$ 51.00 ✓
1pc	front bumper LH side cover	Red	\$ 380.20 ✓
1pc	front bumper LH side top garnish	Dr	\$ 158.50 ✓
1pc	front bumper lower grille	Sn	\$ 198.20 X
10pcs	front bumper clip @\$5.00	Mr	\$ 50.00 ✓
1pc	front bumper reinforcement	Br	\$ 285.50 ✓
2pcs	front bumper reinforcement side rubber @\$37.50	Sn	\$ 75.00 X
1pc	front support panel 486.90	Br	\$ 680.25 ✓
1pc	front air-con condensor	Sn	\$ 750.50 X
1pc	front radiator	Sn	\$ 950.00 X
1pc	front radiator cowling	Sn	\$ 250.50 X
2pcs	front fender @\$685.00 C480.30	Br	\$ 1,370.00 ✓
1pc	front LH fender inner shield	Sn	\$ 280.50 X
10pcs	front LH fender inner shield clip \$5.00	Mr	\$ 50.00 X
			\$ 19,569.10
	less 20%		\$ 3,913.82
			\$ 15,655.28
1set	rear parking sensor	Mr s.nett	\$ 280.00 2000
	remove & refit rear windscreen glass		\$ 120.00 ✓
	remove & refit rear LH fender glass		\$ 120.00 601
	wiring		\$ 250.00 401
	tuffkote		\$ 250.00 1801
	spray painting		\$ 2,600.00 2000
	labour charges		\$ 2,400.00 2000
	Total		\$ 21,675.28

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

