



方 商 昭 噴 漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

NATALIA LI MAN-CHING
20 LINCOLN ROAD
#24-02
SINGAPORE 308353

*Not Authorized
11/12/07
Paying After Repair
4 days*

Dear sir

Estimate cost of repair to vehicle no. SCH 6988H

To supply

1. Rear bumper	<i>nd/cnt</i>	1,228.00	✓
2. Rear bumper moulding centre	<i>nd</i>	158.00	—
3. Rear bumper moulding side x2	<i>nd</i>	116.00	—
4. Rear fender right	<i>nd</i>	2,301.00	X
5. Rear fender inner garish	<i>nd</i>	182.00	X
6. Rear fender protector	<i>nd/cnt</i>	118.00	✓
7. Rear fender protector chrome	<i>nd</i>	111.00	✓
8. Wheel rim sport	<i>nd</i>	950.00	✓
9. Rear wheel tyre	<i>nd</i>	350.00	X
10. Knuckle arm		690.00	?
11. Bearing		354.00	?
12. Upper arm	<i>108</i>	560.00	X
13. Drive shaft	<i>nd</i>	1,230.00	X
14. Rear shock absorber	<i>nd</i>	650.00	X
15. Stay bar link	<i>nd</i>	340.00	X
Labour charges			
Panel beating		1,200.00	<i>5002</i>
Spray painting		1,000.00	<i>5501</i>
Under carriages n wheel alignment		650.00	?
Total			

Your faithfully

Albert
ALBERT POON

12/188

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: