

Steve (LKK) *not RA* 10/3/20, 3.00pm  
 5 days, P/P, R/B, Bel RJ

**Main Office:**  
 Mova Building  
 No. 22, Jalan Kilang,  
 Singapore 159419  
 Tel: (65) 6476 3333  
 Fax: (65) 6271 5891  
 www.mova.com.sg

**Workshop Dept:**  
 Block 1008,  
 Bukit Merah Lane 3,  
 #01-04/06/08/94  
 Singapore 159722

Tel: (65) 6272 3892  
 Fax: (65) 6270 8314

Co. Reg. 198904033G  
 GST Reg. M2-0088864-2

# Estimate

09/03/2020

**MS FIRST CAPITAL INSURANCE LIMITED**  
 36 Robinson Road  
 #16-01 City House  
 Singapore 068877.

Page # :- 1  
 Veh # :- SMK873K  
 Veh Model :- PEUGEOT 3008 TURBO 1.6  
 Estimate# :- CK420495  
 Claim # :-  
 ACC. Date :- 07/03/20  
 Terms :- C.O.D Days  
 Remarks :-

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
<b>LIST ITEMS :</b>				
1.	TAILLAMP ASSY RH / <i>CMT</i>	1 PC	400.00	400.00
2.	TAILLAMP LOWER BRACKET RH / <i>CRW</i>	1 PC	140.00	140.00
3.	REAR BUMPER GARNISH - CENTER / <i>BR</i>	1 PC	520.00	520.00
4.	REAR BUMPER GARNISH - RH / <i>CR4</i>	1 PC	480.00	480.00
5.	REAR BUMPER / <i>BR</i>	1 PC	980.00	980.00
6.	REAR BUMPER REFLECTOR RH / <i>BR</i>	1 PC	120.00	120.00
7.	REAR BUMPER SPONGE	1 PC	200.00	200.00
8.	REAR BUMPER REINFORCEMENT	1 PC	450.00	450.00
9.	REAR BUMPER BRACKET RH ( <i>Robin</i> ) / <i>MT</i>	1 PC	145.00	145.00
10.	REAR BUMPER RETAINER RH / <i>BR</i>	1 PC	140.00	140.00
11.	REAR BUMPER CLIPS / <i>MC</i>	10 PCS	8.00	80.00
12.	REAR FENDER COWLING RH / <i>TN</i>	1 PC	160.00	160.00
13.	REAR END PANEL X / <i>R</i>	1 PC	950.00	950.00
14.	REAR END PANEL TOP COVER X	1 PC	380.00	380.00
15.	REAR FENDER INNER TRIM RH - CHECK X	1 PC		
16.	TAILGATE (REPAIR) X / <i>R</i>	1 PC		
17.	TAILGATE LOGO / <i>MC</i>	1 PC	120.00	120.00
18.	TAILGATE EMBLEM - PEUGEOT / <i>MC</i>	1 PC	115.00	115.00
19.	TAILGATE EMBLEM - 3008 / <i>MC</i>	1 PC	100.00	100.00
	LIST TOTAL S\$			5,480.00
	20% DISCOUNT S\$			-1,096.00
				4,384.00
<b>SPECIAL NET ITEMS :</b>				
1.	REVERSE SENSOR / <i>BR</i>	1 SET	200.00	200.00
	SPECIAL NET TOTAL S\$			200.00
<b>LABOUR :</b>				
	TO CUT/WELD REAR END PANEL. KNOCK AND STRAIGHTEN REAR FENDER RH, SPARE WHEEL PANEL. REMOVE AND REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION		<i>600</i>	900.00
	SPRAY PAINT REAR FENDER LH, REAR END PANEL, REAR BUMPER, REAR BUMPER GARNISH, TAILGATE		<i>600</i>	700.00
	REMOVE & REFIT LUGGAGE COMPARTMENT INNER TRIM, GARNISH, COVERING		<i>50</i>	60.00
	REMOVE & REINSTALL REVERSE SENSOR AND CHECK FUNCTION		<i>30</i>	50.00
	LABOUR TOTAL S\$			1,710.00

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel : (65) 6476 3333  
Fax : (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722

Tel : (65) 6272 3892  
Fax : (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

# Estimate

09/03/2020

**MS FIRST CAPITAL INSURANCE LIMITED**  
36 Robinson Road  
#16-01 City House  
Singapore 068877.

Page # :- 1 137786  
Veh # :- SMK873K  
Veh Model :- PEUGEOT 3008 TURBO 1.6  
Estimate# :- CK420495  
Claim # :-  
ACC. Date :- 07/03/20  
Terms :- C.O.D Days  
Remarks :-

Attention :- XA026

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E



NON-TAX AMOUNT S	
AMOUNT S\$	6,294.00
GST @ 7 %	440.58
<b>AMOUNT DUE S\$</b>	<b>6,734.58</b>

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: