

FORM 10

ASS. REC. BY:

REF: CS/11420003886/Usd3⁰²

Special Instruction:

Sineyer: Marcus
Menthen

ASSIGNMENT (Office)

From (Person): Mr Yinnul

of A14

Date/Time: 11/03/2020 @ 8.59am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKC 8285X

Insured:

SFL 9473A

at Workshop m/s

BL Automobile

Tel:

of

25 kaki Bukit Road 4 # 03-21 Synergy

Policy No:

Claim No:

322444721SG003

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 07/03/2020

CA / REV / REP. / REV 24 HRS ^{1up}

H.O.D. Endorsement:

Date/Time: 11:44am @ 11/3/2020

Person Contacted:

Lee mei

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate ✓

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKCP28X

Yr Regn:

10/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Honda civic

C.C

1595

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

143359

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMF D 462095200934

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FA Ken

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

7/3/20

D.O.I.

11/3/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

see 21-10-2024 L7A 14095
* lawyer case

Lawyer

13/3/20 4/5 1800 confirmed with kemei

(£ 5,961.72 Red - 69%)

RECEIVED 16 MAR 2020

Date/Time, File Pass to?

☐

: Preli. Report

1)

16/03/20

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) S + RS, Si

) Photos

) Others

)

TOTAL

250

11

261

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

ASSIGNMENT

Supervisor:

MARCUS

DOI:

Date / Time:

11/3/2020

Registered in Merimen:

11/3/2020

Pre-assign / CCU / FTE



Insured Vehicle No. : SPL 9473A

Claim No. : _____

Name of Insured : _____

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II : S\$ _____ D.O.A : 7/3/2020

Place of Accident : _____

Is driver the owner? (YES / NO) Nature of Accident : _____

If NO, Driver Name / Age : _____

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : _____ (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SKC8285X

INSRS:
WSP: BL Automobile
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time

SKC8285X : X ; SPL9473A : X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

PRELIMINARY ADVICE Date/Time:

Sent By:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$ (days) Reduction: %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

Email ☐ Call ☐

Final Liability: % (Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost: S\$

Loss of Rental (LOR): S\$ (days)

Loss of Use (LOU): S\$ (\$ x days)

Loss of Income (LOI): S\$ (\$ x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search S\$

Medical: S\$

Disbursement: S\$ (e.g. Tow/ Independent)

Legal Cost S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total: S\$ Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: S\$

Name 1:


Payee 2: (Strike if N.A.) S\$

Name 2:

Payee 3: (Strike if N.A.) S\$

Nat id 3:

3136/166
PRE-REPAIR INSPECTION REQUEST – SKC8285X vs SFL9473A (OI) on D.O.A.: 07/03/2020

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Lim, Kok-Chong, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Subramaniam, Divyashni, Teo, Ericweihong
Sent: 3/11/2020 8:59:21 AM
Attachments:  BL_SKC8285X DOA07032020 NOA&GIA.pdf

Hi,

Please refer to the enclosed request from **B L Automobile Service**.

Claim no : 3122444721SG003
Case Owner : Bennie Tan Wei Zhong

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Marcua Chua** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 8001206556 | Ext: 1002208
Yinrul.Hor@aig.com | www.aig.sg

11:44am @ 11/3/2020
✓ IM
S: Marcus
P: Lee Mei

From: amylia.blgarage@gmail.com <amylia.blgarage@gmail.com>
Sent: Tuesday, March 10, 2020 11:49 AM
To: Hor, Yinrul <Yinrul.Hor@aig.com>
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFL9473A AND SKC8285X ON 07/03/2020

Dear Sirs,

We agree to accept your list of surveyors and has chosen:

LKK Auto Consultants – Marcus Chua

to carry out the PRI as SJE whereby the cost of survey will be bear by you.

Please send them the assignment. We await for their arrangement to survey the car.

From: Hor, Yinrul
Sent: Tue, 10 Mar 2020 01:27:10 +0000
To: Amylia Wong
Cc: Lim, Kok-Chong, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Subramaniam, Divyashni, Teo, Ericweihong
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SFL9473A AND SKC8285X ON 07/03/2020

Without Prejudice

Your Reference : SKC8285X

Our Reference : SFL9473A

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)

AIG

FNOL Adjuster I

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 8001206556 | Ext: 1002208

Yinnul.Hor@aig.com | www.aig.sg

From: Amylia Wong [mailto:amyliablgarage@gmail.com]

Sent: Monday, March 09, 2020 3:19 PM

To: AIG SGP, Claims-Survey

Subject: [EXTERNAL] Notification of Accident Involving SKC8285X & SFL9473A

This message is from an external sender; be cautious with links and attachments.

Our Ref: SKC8285X

Notification of Accident Involving SKC8285X & SFL9473A At Junction Of Serangoon North Ave 5 & Yio Chu Kang Road on 07.03.2020

Please arrange for pre-repair inspection.

Kindly let us have your list of **Ten** surveyors for our consideration.

Please acknowledge upon receipt of the Notification of Accident during office hours
(Mon - Fri, 9:00am - 6:00pm)

Thanks & Best Regards,

Lee Mei

B L Automobile Service

25 Kaki Bukit Road 4

#03-24 Synergy@KB

Singapore 417800

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Management Unit with 5 Years Warranty and Servicing!



Agent Unit, with Low Mileage.
Special Interest Rate 1.99%
Last 2 Units!
StarAd

• Free VICOM evaluation

• Free grooming and 8 months maintenance




• In-house workshop ensures quality service

• Member of SVTA and hire purchase association

• 100% deposit refund for unapproved loan



YONG LEE SENG MOTOR PTE LTD

Browse by Category		Back (1 2) Next		Sort by Date Posted		20 results/page	
32 vehicles		CIVIC 1.6		Advanced Search		Submit	
Search Selection		civic 1.6	Any	Any	> 10 year(s) old	Any	Any
	Honda Civic 1.6A VTI (New 5-yr COE)		\$33,800	\$6,760 /yr	10-Mar-2010	1,595 cc	102,000 km
	\$0 Downpayment Available! Low Monthly Installment At Only \$819! Car In Very Good Condition, Cheapest In The Market, Lowest Depre...		Posted: 10-Mar-2020 Tags: 2010 Honda Civic, Honda Civic, Honda, Civic				
	Honda Civic 1.6M VTI (COE till 09/2021)		\$11,800	\$7,580 /yr	16-Nov-2006	1,595 cc	148,193 km
	New Arrival! Cheapest In Town! 2 Owners Only! Rare Silver Civic 1.6 Manual VTI For Sale! Ideal For Short Term Usage! Very Low Mileag...		Posted: 10-Mar-2020 Tags: 2006 Honda Civic, Honda Civic, Honda, Civic				
	Honda Civic 1.6A VTI (COE till 06/2022)		\$17,800	\$7,840 /yr	19-Jun-2007	1,595 cc	-
	Smooth Engine, Easy To Maintain Unit, Immaculate Condition, Depreciation Is Even Cheaper, Do Not Miss, Bank And In House Loan Avail...		Motor Universe Credit Pte Ltd				
	Honda Civic 1.6A VTI (COE till 11/2022)		\$19,800	\$7,410 /yr	12-Nov-2007	1,595 cc	-
	Is your COE expiring? Let us help you renew it!		Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.				
	Honda Civic 1.6A VTI (COE till 11/2024)		\$33,800	\$7,200 /yr	19-Nov-2009	1,595 cc	106,808 km
	Low Mileage, Brand New Leather And Roof Lining, New Paintwork, No Repairs Needed, Car In Superb Condition, Full Loan And Bank Loa...		SmartCars Boutique Pte Ltd				
	Honda Civic 1.6A VTI (New 5-yr COE)		\$35,300	\$7,060 /yr	06-Mar-2010	1,595 cc	96,800 km
	2nd Owner Only Mileage Done 98,600km Only. 10 Years \$52,800 Selling Price, Full Loan Can Try.		Posted: 09-Mar-2020 Tags: 2010 Honda Civic, Honda Civic, Honda, Civic				
	GET YOUR COE RENEWAL LOAN						
	Compare						

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 180E

Vehicle Details

Vehicle No.: SKC8285X

Vehicle to be Exported: No

Intended Deregistration Date: 11 Mar 2020

Vehicle Make: HONDA

Vehicle Model: CIVIC 1.6L 5AT

Primary Colour: Grey

Manufacturing Year: 2008

Engine No.: R16A14003504

Chassis No.: JHMFD46209S200934

Maximum Power Output: 92.0 kW (123 bhp)

Open Market Value: \$23,665.00

Original Registration Date: 22 Oct 2009

First Registration Date: 22 Oct 2009

Transfer Count: 5

Actual ARF Paid: \$23,637.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 21 Oct 2024

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$15,287.00

COE Rebate Amount: \$14,095.00

Total Rebate Amount: \$14,095.00**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Mar 2020

BL AUTOMOBILE SERVICE

25 KAKI BUKIT ROAD 4 #03-24 SYNERGY @KB SINGAPORE 417800

TEL: 9240 6288

FAX: 6702 3577

Email: amylia.blgarage@gmail.com

THIRD PARTY CLAIM ESTIMATION

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#08-16 Singapore 079120

Vehicle Number : SKC8285X
Make / Model : Honda Civic
Chassis Number : JHMFD46209S200934
Accident Date : 07/03/2020
Reference : SKC8285X

Not Authorized
2/11/20
11/3/20
2/s \$1800
Take ph. After repair
4 days

8/1/20096608

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	Boot lid 12 X	\$ 752.40 X
1	Boot lid top lock 11 X	\$ 112.50 X
1	Boot lid weatherstrip 11 X	\$ 112.00 X
1	Boot lid logo 11	\$ 35.10
1	Boot lid emblem 'CIVIC' 11	\$ 45.00
2	Boot lid reflector @ \$215.00 11 X	\$ 430.00 X
1	Rear bumper 10/12 638	\$ 722.00
2	Rear bumper side retainer @ \$28.40 11 X	\$ 56.80 X
1	Rear tail lamp LH 11	\$ 285.00
1	Rear tail lamp lower bracket LH 11 X	\$ 20.60 X
1	Rear tail lamp panel LH 11 X	\$ 63.80 X
1	Rear end panel 11 X	\$ 485.70 X
1	Rear end panel top garnish 11 X	\$ 88.00 X
1	Rear spare tyre panel 11 X	\$ 812.00 X
		\$ 4,020.90
	Less 20%	\$ (804.18)
	Subtotal	\$ 3,216.72
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
10	Rear bumper clip @ \$5.00 11 40	\$ 50.00
2	Rear tail lamp clip @ \$5.00 11 X	\$ 10.00
1	Rear end panel insulation 11 X	\$ 90.00
1 set	Rear reverse sensor 11 200	\$ 280.00
1	Rear end panel top garnish clips (set) 11 X	\$ 15.00
	Subtotal	\$ 445.00
	Balance C/F	\$ 3,661.72

LABOUR AND MISCELLANEOUS CHARGES

	Balance B/F	\$ 3,661.72
1.	To remove and transfer of bootlid component.	\$ 14X 60.00
2.	To remove, refit, replaced damaged lamps and check up electrical wiring.	\$ 20 80.00
3.	To remove and refit rear bumper sensor.	\$ 50 60.00
4.	To apply undercoating on affected area.	\$ 17X 100.00
5.	To remove and refit undercarriage.	\$ 17X 300.00
6.	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident.	\$ 450 700.00
7.	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident	\$ 700 800.00
	Subtotal	\$ 2,100.00
	Grand total	\$ 5,761.72

LUK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To inspect/damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No direct payment to client is allowed
- Supplementary item(s) must be reviewed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P. 1003-10
202

P- 802-48

S.N- 240.00

L- 1220.00

2262-48

202

1809.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20003886/USD3N2
Date: 19/03/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700080206
Claimant Vehicle No :	SKC8285X	Insured Vehicle No :	SFL9473A
Date of Loss:	07/03/2020	Nature of Claim:	TP
		Claim No:	3122444721SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC8285X	Engine No:	R16A14003504
Make & Model:	HONDA CIVIC, 1.6 L (A)	Chassis No:	JHMF46209S200934
Reg. Date:	22/10/2009 (Man. Year: 2008)	Odometer:	143359 km
Colour:	White		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,661.72	1,042.48	2,619.24	71.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,220.00	880.00	41.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,761.72	2,262.48	3,499.24	60.73
Approved Total (Overridden) (S\$)		1,800.00		
Nett Amount (S\$)	5,761.72	1,800.00	3,961.72	68.76

INSPECTION

Date of Assignment:	11/03/2020	BI Automobile Service (HQ)
Date Inspected:	11/03/2020	Inspected At: 25 Kaki Bukit Road 4 Synergy @ KB. #03-24
Estimated Period of Repair:	4.0 days	Singapore 417800

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	752.40 FL	*- FL
2	1		*BOOT LID TOP LOCK	Not Necessary	112.50 FL	*- FL
3	1		*BOOT LID WEATHERSTRIP	Not Necessary	112.00 FL	*- FL
4	1		*BOOT LID LOGO	Necessary	35.10 FL	*35.10 FL
5	1		*BOOT LID EMBLEM CIVIC	Necessary	45.00 FL	*45.00 FL
6	2		*BOOT LID REFLECTOR	Not Necessary	430.00 FL	*- FL
7	1		*REAR BUMPER	Dented/Deformed	722.00 FL	*638.00 FL
8	2		*REAR BUMPER SIDE RETAINER	Not Necessary	56.80 FL	*- FL
9	1		*REAR TAIL LAMP LH	Cracked	285.00 FL	*285.00 FL
10	1		*REAR TAIL LAMP LOWER BRACKET LH	Not Necessary	20.60 FL	*- FL
11	1		*REAR TAIL LAMP PANEL LH	Not Necessary	63.80 FL	*- FL
12	1		*REAR END PANEL	Repair	485.70 FL	*- FL
13	1		*REAR END PANEL TOP GARNISH	Not Necessary	88.00 FL	*- FL
14	1		*REAR SPARE TYRE PANEL	Repair	812.00 FL	*- FL
15	10		*REAR BUMPER CLIP	Necessary	50.00 FS	*40.00 FS
16	2		*REAR TAIL LAMP CLIP	Not Necessary	10.00 FS	*- FS
17	1		*REAR END PANEL INSULATION	Not Necessary	90.00 FS	*- FS
18	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
19	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	15.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,465.90	1,243.10
- List Item Discount on L Items 20.00/20.00% (\$)	804.18	200.62
Total Parts (\$)	3,661.72	1,042.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER OF BOOTLID COMPONENT	New	60.00	0.00
2	TO REMOVE,REFIT,REPLACED DAMAGED LAMPS AND CHECK UP ELECTRICAL WIRING	New	80.00	20.00
3	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	60.00	50.00
4	TO APPLY UNDERCOATING ON AFFECTED AREA	New	100.00	0.00
5	TO REMOVE AND REFIT UNDERCARRIAGE	New	300.00	0.00
6	TO PROVIDE LABOUR CHARGES,WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS,REPAIR INCLUDING CUT AND WELD;RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	700.00	450.00
7	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS,REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT	New	800.00	700.00
Gross Labour Cost (\$\$)			2,100.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >